

Figure - 开发 Dev #110746

开发 Dev # 110122 (New): 【MK】管理总票
开发 Dev # 110126 (New): 【MK】【AF】管理总票
【MK】【FW】【QuickSettings】【TC-RID: 1201-0201903】
2022-07-25 20:07 - CD FW-程天颖

Status:	New	Start date:	2022-07-25
Priority:	Normal	Due date:	
Assignee:	CD FW-鲁凯峰	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_20221030		
Description			
■ 需求列表: "WiFi 蓝牙 截屏 护眼模式 屏幕录制 深色模式 亮度调节 音量调节 播放器 游戏模式 平行视界 电源选项 编辑入口" ■ 提出URL：必填 ■ 自测case：必填 ■ 注意点：需要测试注意的前提条件			
Related issues:			
Related to Figure - 需求 Requirement # 111008: 【Locked需求】La...		分析&分解中 In 2022-08-03	2022-08-22
Related to Figure - 需求 Requirement # 111084: 【需求变更】-手势交互需...		完成 Closed 2022-08-05	2022-08-22

History

- #1 - 2022-08-04 19:47 - CD FW-王伟
- Subject changed from 【MK】【019】【QuickSettings】【TC-RID: 0301-0201803】 to 【MK】【019】【QuickSettings】【TC-RID: 1201-0201803】
- #2 - 2022-08-05 11:13 - CD FW-王伟
- Assignee set to FW&MW2组_DLTS 刘显鹤
- #3 - 2022-08-05 16:03 - FW&MW2组_DLTS 刘显鹤
- 目前确认，消息中心和控制中心合到一起显示，不再区分状态栏左侧下滑和右侧下滑；
- #4 - 2022-09-08 08:34 - CD FW-王伟
- Subject changed from 【MK】【019】【QuickSettings】【TC-RID: 1201-0201803】 to 【MK】【FW】【QuickSettings】【TC-RID: 1201-0201803】
- #5 - 2022-09-08 08:37 - CD FW-王伟
- Assignee changed from FW&MW2组_DLTS 刘显鹤 to CD FW-鲁凯峰

- #6 - 2022-09-22 20:07 - CD FW-王伟
- Subject changed from 【MK】 【FW】 【QuickSettings】 【TC-RID: 1201-0201803】 to 【MK】 【FW】 【QuickSettings】 【TC-RID: 1201-0201903】
- #7 - 2022-09-26 20:07 - CD FW-王伟
- Target version set to VX1_MCE_FSE_V2.0_20220930
- #8 - 2022-10-10 20:16 - CD FW-王伟
- Target version changed from VX1_MCE_FSE_V2.0_20220930 to VX1_MCE_FSE_V3.0_20221030

UE功能已经完成，待UI适配。

#9 - 2022-12-05 19:21 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
167496	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
CommitMessage		AF:QuickSettings: Don't allow left and right swiping of the media player	

#10 - 2022-12-06 18:29 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
167733	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com
AF:QuickSettings: update qs scroll viewTC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: Ia0a89af015cb71f79988ad3c7193f2fb45079a92			

#11 - 2022-12-08 10:03 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
167497	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:QuickSettings: Update edit mode UITC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: I5de92a2fdb7b0e14a1c3bb882e4101fc54cef66f			

#12 - 2022-12-14 17:32 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
170245	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com
AF:QuickSettings: update qs animatorTC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: Ifd3b5f33e1a1d3e489d99989af5f7455a6dcfd31			

#13 - 2022-12-16 09:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
170546	general/platform/frameworks/native	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:QuickSettings: update screen record uiTC-RID: 1201-0201905IssueID: TS-R-DF-110746Change-Id: Idf9cd22ee6c841be1240970d86ba1f3a0e24fb1f			

#14 - 2022-12-16 09:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
170543	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:QuickSettings: update screen record uiTC-RID: 1201-0201905IssueID: TS-R-DF-110746Change-Id: Iefdb50562bac901115d5bef76af885505a64c748			

#15 - 2022-12-16 17:01 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
170701	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Toast: update toast uiTC-RID: 1201-0207401IssueID: TS-R-DF-110746Change-Id: I02e6c476a469e88589e2bf7957295e93bb138f9c			

#16 - 2022-12-22 20:24 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143167	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangwei0629@thundersoft.com
FW:QuickSettings: Change the quicksettings listChange the quicksettings listTC-RID: 1201-0201803IssueID: TS-R-DF-110746Change-Id: I4efbf36b98e50db7905a324a32914283f7ef9599			

#17 - 2022-12-22 20:24 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143366	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com

AF:QuickSettings:Add screensaver and screen-off entryAdd screen saver and screen-off function buttons in the footerview of QSTC-RID: 1201-0201803IssueID: TS-R-DF-110746Change-Id: Ib06234af1813a23a29d55aab794bd3183a9e1d03

#18 - 2022-12-22 20:40 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154110	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com
AF:QuickSettings: update qs ui layoutre-layout qs panel to implement ui requirementTC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: I7157c23b2ae6fd5b066a8886652768ab7e7b8c1d			

#19 - 2022-12-22 20:42 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155223	general/platform/vendor/thundercom m/overlay	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com
AF:QuickSettings: disable doze servicedisable doze service to show ambient clockTC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: I428dfe41a9544368eddd1d58fd9db07579180ab7			

#20 - 2022-12-22 20:44 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155887	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com
AF:QuickSettings: fix qs animator issue1. disable qs scroll2. disable date view when scroll3. don't close notification panel when middle clickTC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: I020e0c2881b00eac2cd881eb279157f47f7c1de3			

#21 - 2022-12-22 20:53 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
163334	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com

#22 - 2022-12-22 20:54 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
164360	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com
AF:QuickSettings: update brightenss and volume viewTC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: Idc09c6eb195bd66eeb324a664aada681ac746fe4			

#23 - 2022-12-22 20:54 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
164721	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com
AF:QuickSettings: update header viewTC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: l2c1ce1a8c2c8aa0102ce9b5ee8523d5be466a10c			

#24 - 2023-02-24 19:48 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
184200	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings: update qs ui layoutTC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: l94be6e526589f532b372be2592d3ea0e62effeb3			

#25 - 2023-03-09 19:39 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
186437	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings: Update the time display of the status bar and control centerTC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: l340f652300401b550ab5a45e40af8ae0373454a4			

#26 - 2023-03-21 20:10 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
188817	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12	caoqg0702@thundersoft.com

		-dev	
AF:QuickSettings: change UI for VC1TC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: l75dcf15ec9ffbedf6c428d22ded086304092e6e6			

#27 - 2023-05-10 19:19 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
199162	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:QuickSettings: Disable screenshot soundTC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: l370cdc8cbb2a0fdefd1ce3a931dfaa07d6a3aada			

#28 - 2023-06-02 19:24 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
203987	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	hong.wang_a@thundersoft.com
AF:Toast: update toast uiTC-RID: 1201-0207401IssueID: TS-R-DF-110746Change-Id: Id4c71e94d0a2fcda1a12ccf9da7a10bc4068c97f			

#29 - 2023-06-19 19:12 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208312	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:QuickSettings: delete ScreenRecordTile.TC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: l1afe0b8000ffbdba603e373d44f4978c4297e01a3			

#30 - 2023-06-20 19:49 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208709	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	lei.zheng@thundersoft.com
FW:SystemUI: Hide the wifi status bar iconTC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: l5ed691bc8ee17ce254853a761908e2368b7e2cc2			

#31 - 2023-06-20 22:11 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
208862	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:QuickSettings: delete ScreenRecordTile.TC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: I1afe0b8000ffbd603e373d44f4978c4297e01a3(cherry picked from commit 75afbda9e6224cca4aea256bf9e2370af841b3e7)			

#32 - 2023-06-25 10:32 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209414	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangxl0510@thundersoft.com
AF:SystemUI: Hide the ethernet status bar iconTC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: I7b2ef4c78506f838ffea2767332289d6b95a0cae			

#33 - 2023-06-25 21:32 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209206	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
FW:SystemUI: Hide the wifi status bar iconTC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: I5ed691bc8ee17ce254853a761908e2368b7e2cc2(cherry picked from commit 064fbf08ca2dbe687d4a1478f98ebfa99614c12e)			

#34 - 2023-06-25 21:47 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209681	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:SystemUI: Hide the ethernet status bar iconTC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: I7b2ef4c78506f838ffea2767332289d6b95a0cae(cherry picked from commit 75e142112a3c6ba141ce991a06bef1e552bd8890)			

#35 - 2023-06-26 16:06 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209737	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com

AF:Toast:small window toast carshTC-RID: 1201-0207401IssueID: TS-R-DF-110746Change-Id: I7abd0bc61d55dd9894e56a4391c9ac8feffd9e53

#36 - 2023-06-26 20:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209946	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Toast:small window toast carshTC-RID: 1201-0207401IssueID: TS-R-DF-110746Change-Id: I7abd0bc61d55dd9894e56a4391c9ac8feffd9e53(cherry picked from commit 99d64e988c39e73962db23336e8cd24de0e0eeb9)			

#37 - 2023-07-18 19:54 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
215797	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	hong.wang_a@thundersoft.com
AF:SystemUI:Quick settings will flash white when entering the settingsremove animationTC-RID: 1201-0201903IssueID: TS-R-DF-110746,IOVDEV-37638Change-Id: I069a11dc82add640a17a5b64ca210c6f9c0a3f02			

#38 - 2023-07-19 14:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216019	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:QuickSettings: Fix volume control problem.TC-RID: 1201-0201903IssueID: TS-R-DF-110746, IOVDEV-36913Change-Id: Ie888ec8aa37df68fe3d21105fedd692a596efe06			

#39 - 2023-07-19 23:54 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216244	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com

AF: SystemUI: Quick settings will flash white when entering the settings remove animation TC-RID: 1201-0201903 IssueID: TS-R-DF-110746, IOVDEV-37638 Change-Id: I069a11dc82add640a17a5b64ca210c6f9c0a3f02 (cherry picked from commit bdd681d6dd7f1ee69974fabd543ec67570f383a0)

#40 - 2023-07-20 23:27 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216506	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF: QuickSettings: Fix volume control problem. TC-RID: 1201-0201903 IssueID: TS-R-DF-110746, IOVDEV-36913 Change-Id: Ie88ec8aa37df68fe3d21105fedd692a596efe06 (cherry picked from commit 17d38fd6adf0497cb7803d31c72bea7c5d617901)			

#41 - 2023-07-25 18:16 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
217407	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com
AF: QuickSettings: update qs animator TC-RID: 1201-0201903 IssueID: TS-R-DF-110746, IOVDEV-35790 Change-Id: Ibccb1473d3ecd89f6718b57361bca75508070a8e			

#42 - 2023-07-25 19:49 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
217538	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF: SystemUI: Add log when volume dialog show and dismiss TC-RID: 1201-0201901 IssueID: TS-R-DF-110746, IOVDEV-37154 Change-Id: Idddd8c2ad15bd9f75b1ffaf769775a11d3eaff1e			

#43 - 2023-07-26 15:22 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
217658	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF: QuickSettings: Forbid edge show in music controller panel. TC-RID: 1201-0201903 IssueID: TS-R-DF-110746, IOVDEV-38029 Change-Id: Ic66593d81a2a6e55282ef17afd2ff129d0b206f4			

#44 - 2023-07-27 23:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218215	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:QuickSettings: update qs animatorTC-RID: 1201-0201903IssueID: TS-R-DF-110746, IOVDEV-35790Change-Id: lbccb1473d3ecd89f6718b57361bca75508070a8e(cherry picked from commit c176b0e48e02716e6a7ac5109adc5d23a70e4ee3)			

#45 - 2023-07-27 23:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218216	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:SystemUI: Add log when volume dialog show and dismissTC-RID: 1201-0201901IssueID: TS-R-DF-110746, IOVDEV-37154Change-Id: ldddb8c2ad15bd9f75b1ffaf769775a11d3eaff1e(cherry picked from commit f60ebdedc9d73e818cca47aa528f3a42b86436f1)			

#46 - 2023-07-27 23:44 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218220	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:QuickSettings: Forbid edge show in music controller panel.TC-RID: 1201-0201903IssueID: TS-R-DF-110746, IOVDEV-38029Change-Id: lc66593d81a2a6e55282ef17afd2ff129d0b206f4(cherry picked from commit 81675ee298e5917cb3bd64dd8360b023904f5d80)			

#47 - 2023-07-28 10:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218350	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:SystemUI:Quick settings will flash white when logclick tilefixed animationTC-RID: 1201-0201903IssueID: TS-R-DF-110746,IOVDEV-36401Change-Id: lea76f6039cbbc1cdad375134c82c2fc5c3b5b7dea			

#48 - 2023-07-31 18:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218604	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:QuickSettings: Fix music controller panel twinkle proble.TC-RID: 1201-0201903IssueID: TS-R-DF-110746, IOVDEV-38450Change-Id: I96ce05323baf062f9aa1731f9316043385dea464			

#49 - 2023-08-01 22:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
219401	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:SystemUI:Quick settings will flash white when logclick tilefixed animationTC-RID: 1201-0201903IssueID: TS-R-DF-110746,IOVDEV-36401Change-Id: lea76f6039cbc1cdad375134c82c2fc5c3b5b7dea(cherry picked from commit a48aad5ac56d478d805f961f0152ea3203508250)			

#50 - 2023-08-01 22:23 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
219407	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:QuickSettings: Fix music controller panel twinkle proble.TC-RID: 1201-0201903IssueID: TS-R-DF-110746, IOVDEV-38450Change-Id: I96ce05323baf062f9aa1731f9316043385dea464(cherry picked from commit aadb1f0e4e71d94c5bb785529c493b1c399f4860)			

#51 - 2023-08-02 15:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
217904	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:StatusBar:Add log when clock color changeTC-RID: 1201-0201901IssueID: TS-R-DF-110746, IOVDEV-36443Change-Id: Ia555889759eef3ffe0e30591033ff4ba51c031cb			

#52 - 2023-08-03 16:55 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader

219346	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:QuickSettings: Fix bluetooth tile background problem.TC-RID: 1201-0201903IssueID: TS-R-DF-110746, IOVDEV-38681Change-Id: If712bd95a201b2f54e09e5d45ad763c06243c0aa			

#53 - 2023-08-04 10:13 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
300133	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:StatusBar:Add log when clock color changeTC-RID: 1201-0201901IssueID: TS-R-DF-110746, IOVDEV-36443Change-Id: Ia555889759eef3ffe0e30591033ff4ba51c031cb(cherry picked from commit 6ce39655d49576c615f6db478256e7379b4a4eff)			

#54 - 2023-08-09 13:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
301543	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:QuickSettings: Fix volume controller problem from mute.TC-RID: 1201-0201903IssueID: TS-R-DF-110746, IOVISSUE-14344Change-Id: Ibc95d403c2cc186cefcfd96fab06502f81d5734e			

#55 - 2023-08-09 17:01 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
301628	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:SystemUI: Add log when volume dialog show and dismiss.TC-RID: 1201-0201901IssueID: TS-R-DF-110746, IOVDEV-37154Change-Id: I2745705e956c6134adc595f251b543ffc6258e97			

#56 - 2023-08-10 18:53 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302262	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com

AF:SystemUI:Volume dialog don't dismiss when runing monekeyTC-RID: 1201-0201901IssueID: TS-R-DF-110746, IOVDEV-37154Change-Id: I148aadd58c067dbae0f7ec2232cf9886172627d7

#57 - 2023-08-10 20:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302374	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:QuickSettings: Fix bluetooth tile background problem.TC-RID: 1201-0201903IssueID: TS-R-DF-110746, IOVDEV-38681Change-Id: If712bd95a201b2f54e09e5d45ad763c06243c0aa(cherry picked from commit a4fddec51c91c0e959dc3179c36061a79b457825)			

#58 - 2023-08-10 20:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302427	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:QuickSettings: Fix volume controller problem from mute.TC-RID: 1201-0201903IssueID: TS-R-DF-110746, IOVISSUE-14344Change-Id: Ibc95d403c2cc186cefcfd96fab06502f81d5734e(cherry picked from commit a89303e9aa0bfc381481dd6c780dc5f98a14e7a9)			

#59 - 2023-08-10 20:53 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302430	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:SystemUI: Add log when volume dialog show and dismiss.TC-RID: 1201-0201901IssueID: TS-R-DF-110746, IOVDEV-37154Change-Id: I2745705e956c6134adc595f251b543ffc6258e97(cherry picked from commit d167aaee53ed8da7e1c25de2f6b7997aafefee58)			

#60 - 2023-08-14 18:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302925	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:SystemUI:Volume dialog don't dismiss when runing monekeyTC-RID: 1201-0201901IssueID: TS-R-DF-110746, IOVDEV-37154Change-Id:			

#61 - 2023-08-25 14:18 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
306027	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:StatusBar: Add log when clock changeTC-RID: 1201-0201901IssueID: TS-R-DF-110746, IOVDEV-37255Change-Id: I2d4d76857409ffe29383f1c19ef3a843856f9805			

#62 - 2023-08-29 19:12 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
307176	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:StatusBar: Add log when clock changeTC-RID: 1201-0201901IssueID: TS-R-DF-110746, IOVDEV-37255Change-Id: I2d4d76857409ffe29383f1c19ef3a843856f9805(cherry picked from commit f49120f80a7c4b9c86bd07bd8ffbd68205e41140)			

#63 - 2023-09-12 19:48 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
312195	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings: Do not respond to clicks on the blank area in the notification center and control center.TC-RID: 1201-0201903IssueID: TS-R-BUG-110746Change-Id: I43fddba51a9bb73ad19a2af2a8546e6bc3007e6b			

#64 - 2023-09-18 19:39 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
313580	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings: Adapt the new UI for the VC1 model.TC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: Ie4baa02ce7f73285bd6b735562cc14ace36ad0cb			

#65 - 2023-09-19 14:25 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
313736	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings: Adapt the new UI for the VC1 model.TC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: Id1482d72c3046efafc7bb044d0ae54acd3d7d980			

#66 - 2023-09-20 10:32 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
314322	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:Toast: VC1 new toast UI.TC-RID: 1201-0207401IssueID: TS-R-DF-110746Change-Id: I523226e49007c22e4fcd0de4b399290316333f66			

#67 - 2023-09-20 20:01 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
314631	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:QuickSettings: Adapt the new UI for the VC1 model.TC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: Ie4baa02ce7f73285bd6b735562cc14ace36ad0cb(cherry picked from commit 237a8be2ca6d472811d8621767fd9058045e94d6)			

#68 - 2023-09-20 20:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
314632	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:QuickSettings: Adapt the new UI for the VC1 model.TC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: Id1482d72c3046efafc7bb044d0ae54acd3d7d980(cherry picked from commit c08746699399cde7692283cb8fc553a9fefe2f83)			

#69 - 2023-09-20 20:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
314636	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

AF:Toast: VC1 new toast UI.TC-RID: 1201-0207401IssueID: TS-R-DF-110746Change-Id: I523226e49007c22e4fcd0de4b399290316333f66(cherry picked from commit 2e56bd0c24d68111e470d51e2974fa754c8eb7e6)

#70 - 2023-09-25 14:16 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
315703	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:Toast: VC1 new toast UI additional.TC-RID: 1201-0207401IssueID: TS-R-DF-110746Change-Id: Icab8a4d34cc722c25fd7fab06f8d4a60cd4f3a99			

#71 - 2023-09-26 17:25 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
316214	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:SystemUI: add debug log for volume desyncadd debug log for volume desyncTC-RID: 1201-0201903IssueID: TS-R-DF-110746 , IOVDEV-43064Change-Id: Icc79124da2e4fce68dc2e5ac720bcaafc3346991			

#72 - 2023-09-26 17:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
316028	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wujun.wang@thundersoft.com
AF:QuickSettings: add screen clean tileAdd screen clean mode.1.add tile in qs.2.disable and intercept gesture.3.keep screen on.TC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: I04d47c59a060490d62aadeb4910d4366f12bf8d6			

#73 - 2023-09-26 17:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
316027	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wujun.wang@thundersoft.com

AF:QuickSettings: add screen clean tileAdd logic to intercept gesture forscreen clean.TC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: I85341215e6f7d7eb5ae1583f7cb4612bc1ef66b8

#74 - 2023-10-07 16:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317242	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:QuickSettings: Do not respond to clicks on the blank area in the notification center and control center.TC-RID: 1201-0201903IssueID: TS-R-BUG-110746Change-Id: I43fddba51a9bb73ad19a2af2a8546e6bc3007e6b(cherry picked from commit 6659c9a3ef6b0123d8639962f8d81af36611d9e9)			

#75 - 2023-10-07 17:05 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317338	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Toast: VC1 new toast UI additional.TC-RID: 1201-0207401IssueID: TS-R-DF-110746Change-Id: Icab8a4d34cc722c25fd7fab06f8d4a60cd4f3a99(cherry picked from commit 463d45f3af726d1340664a96b96b0b94bfd7bfe0)			

#76 - 2023-10-07 17:08 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317310	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:QuickSettings: Components in editing state use the default background.TC-RID: 1201-0201903IssueID: TS-R-DF-110746, IOVDEV-45321Change-Id: I254a577a247d119ba1a3a713b84ba8f9ab80aafc			

#77 - 2023-10-07 17:10 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317345	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com

AF:SystemUI: add debug log for volume desyncadd debug log for volume desyncTC-RID: 1201-0201903IssueID: TS-R-DF-110746 , IOVDEV-43064Change-Id: lcc79124da2e4fce68dc2e5ac720bcaafc3346991(cherry picked from commit 17a7c3bcfbc05f185262e24b18f42d8885b72329)

#78 - 2023-10-07 19:18 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317379	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings: Change the settings icon for the settings center buttonTC-RID: 1201-0201903IssueID: TS-R-DF-110746, IOVDEV-44712Change-Id: I11cd0c9fdd9df2b9cfaeef54b0f6877d27fefe02			

#79 - 2023-10-08 00:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317353	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:QuickSettings: add screen clean tileAdd logic to intercept gesture forscreen clean.TC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: I85341215e6f7d7eb5ae1583f7cb4612bc1ef66b8(cherry picked from commit 1a74e53f9d813c11ba4ca4bdccbc01480706d301)			

#80 - 2023-10-08 00:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317354	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:QuickSettings: add screen clean tileAdd screen clean mode.1.add tile in qs.2.disable and intercept gesture.3.keep screen on.TC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: I04d47c59a060490d62aadeb4910d4366f12bf8d6(cherry picked from commit 010c6ff924f577a815a4745a33dede313c4d3848)			

#81 - 2023-10-08 13:56 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317477	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12	caoqg0702@thundersoft.com

		-dev	
AF:QuickSettings: Modify error interception handling in the clean mode.TC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: I894ede2997f260a5d49238d27533340dc4be9003			

#82 - 2023-10-12 20:00 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
319039	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings: Adapt the new UI for the MCE model.TC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: Ie469a9452925e33b368f42f5960015004ac366c6			

#83 - 2023-10-12 22:11 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
318984	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:QuickSettings: Components in editing state use the default background.TC-RID: 1201-0201903IssueID: TS-R-DF-110746, IOVDEV-45321Change-Id: I254a577a247d119ba1a3a713b84ba8f9ab80aafc(cherry picked from commit ecc31b5843a662ea92810a1d547284b425ac8214)			

#84 - 2023-10-12 22:12 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
319107	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:QuickSettings: Change the settings icon for the settings center buttonTC-RID: 1201-0201903IssueID: TS-R-DF-110746, IOVDEV-44712Change-Id: I11cd0c9fdd9df2b9cfaeef54b0f6877d27fef02(cherry picked from commit b537b992ec4c0fa027ef5406de46b203d051e09e)			

#85 - 2023-10-12 22:17 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
319113	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

AF:QuickSettings: Modify error interception handling in the clean mode.TC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: l894ede2997f260a5d49238d27533340dc4be9003(cherry picked from commit e49bc36e5d77d1f93785510925b1b0ba6f4eda32)

#86 - 2023-10-19 16:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
320819	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:Toast: MCE new toast UI.TC-RID: 1201-0207401IssueID: TS-R-DF-110746Change-Id: lec0d232f42d4333ac2e1fe5d57a67a09a4d752e2			

#87 - 2023-10-23 17:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
321902	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings: Adjust the wording for screen-off.TC-RID: 1201-0201903IssueID: TS-R-DF-110746, IOVDEV-40211Change-Id: le4e6a8c448a0a11ede586bc8f65668af3898363f			

#88 - 2023-10-27 01:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323291	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:QuickSettings: Adapt the new UI for the MCE model.TC-RID: 1201-0201903IssueID: TS-R-DF-110746Change-Id: le469a9452925e33b368f42f5960015004ac366c6(cherry picked from commit 7e970499a875296018fe862c4120637c67f25aef)			

#89 - 2023-10-27 01:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323311	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Toast: MCE new toast UI.TC-RID: 1201-0207401IssueID: TS-R-DF-110746Change-Id: lec0d232f42d4333ac2e1fe5d57a67a09a4d752e2(cherry picked from commit c89a5f839a5ba0f9854862a9058b23446333e4dd)			

#90 - 2023-10-27 02:09 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323326	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:QuickSettings: Adjust the wording for screen-off.TC-RID: 1201-0201903IssueID: TS-R-DF-110746, IOVDEV-40211Change-Id: Ie4e6a8c448a0a11ede586bc8f65668af3898363f(cherry picked from commit 79a6549f09e5ebcd66dc2010fe6f1d4ff896a3bd)			

#91 - 2023-12-13 18:12 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
335912	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:Screenshot: Fix touch outside invalid problem after screenshot twice in a row.TC-RID: 1201-0206601IssueID: TS-R-DF-110746, VXMCE-1070Change-Id: Iba74f990eb6efcbd7f1e1df4ac761467200e6d36			

#92 - 2023-12-15 14:23 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
336606	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Screenshot: Fix touch outside invalid problem after screenshot twice in a row.TC-RID: 1201-0206601IssueID: TS-R-DF-110746, VXMCE-1070Change-Id: Iba74f990eb6efcbd7f1e1df4ac761467200e6d36(cherry picked from commit ceac11d9ce8232b252266074583382f7c374d11b)			