

Status:	New	Start date:	2022-08-02
Priority:	Normal	Due date:	
Assignee:	CD SYSTEM-赵正军	% Done:	0%
Category:	SYSTEM	Estimated time:	0.00 hour
Target version:	VC1_FSE_B sample_20221015		
Description			
包含以下任务： 1. prop：系统的属性 2. features：包含的Feature 3. apps/services：包含的应用			

History

- #1 - 2022-08-02 17:35 - CD TPM-申艳艳
- Description updated
- #2 - 2022-09-09 09:55 - CD SYSTEM-赵正军
- Hi,all
- 目前底层kernel已裁剪pcie2/camera/coresight驱动以及对应dts
<https://dev.thundercomm.com/gerrit/c/147840>
<https://dev.thundercomm.com/gerrit/c/147832>
<https://dev.thundercomm.com/gerrit/c/147833>
<https://dev.thundercomm.com/gerrit/c/147839>
<https://dev.thundercomm.com/gerrit/c/147836>
- Thanks!
- #3 - 2022-09-21 11:24 - CD SYSTEM-胡兵
- Assignee changed from CD TPM- 申艳艳 to CD SYSTEM- 赵正军
- 裁剪list参考<https://thundersoft.feishu.cn/sheets/shtcnuGJY7YfHuUjQA7wDzrpFmg?sheet=0oDxjG&view=>
- 目前app&feature AF已裁剪完毕，kernel裁剪待入库。
- 总的裁剪提交参考http://10.4.12.209:8989/RIDGerritsList?FEATURE_ID=0205101&MODEL_NAME=Figure
- 下一步计划：继续裁剪hal相关进程
- #4 - 2022-09-26 15:10 - CD SYSTEM-胡兵
- Target version set to 619

V2.0 裁剪入库app/feature/kernel部分。

#5 - 2022-09-26 15:53 - 物联网项目组-RD3_CDTs 周飞
- Target version changed from 619 to VC1_FSE_B sample_20221015

#6 - 2022-12-22 20:39 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152942	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	zhaozj0108@thundersoft.com
SYSTEM: disabled qvrservice/sxrservice in *.rc1. modify qvrd_vndr.rc and sxrd.rcTC-RID: 1200-0800201IssueID: TS-R-BUG-110965Change-Id: I196938aeb769e7f3042e2bcae1d108a830595044			