

Figure - 开发 Dev #110968

开发 Dev # 110122 (New): 【MK】管理总票
开发 Dev # 110956 (完成 Closed): 【MK】【MM】管理总票
【MK】【001】【MM】【TC-RID: 0301-0900116】副屏音频焦点控制
2022-08-02 20:51 - CD MM陈海波

Status:	完成 Closed	Start date:	2022-08-02
Priority:	Normal	Due date:	2022-08-12
Assignee:	CD MM陈海波	% Done:	0%
Category:	AUDIO-FW	Estimated time:	0.00 hour
Target version:			

Description

此票主要调研与开发音频焦点控制，主要有两点：

1. 副屏使用多媒体，Mic类App时，需要向主屏申请焦点（未接耳机的情况）。
2. 副屏接蓝牙耳机时，不需要向主屏申请焦掉，副屏内部自己管理焦掉。

相关资料:

<https://thundersoft.feishu.cn/file/boxcnbHPsc3OLRynTArN8HfkPqh>

<https://thundersoft.feishu.cn/file/boxcnUVI5DpEIMmZxj811kLIzie>

[https://thundersoft.feishu.cn/file/boxcnezMYT6pCerMrlYR9d2URve\(Audio-FW\)](https://thundersoft.feishu.cn/file/boxcnezMYT6pCerMrlYR9d2URve(Audio-FW))

feature list:

<https://thundersoft.feishu.cn/sheets/shtcnqaFykINSnMcKWLuICl3xnc?sheet=wlkPyp>

History

#1 - 2022-08-02 20:52 - CD MM陈海波

- Parent task changed from #110122 to #110956

#2 - 2022-08-23 17:37 - CD MM陈海波

<https://share.thundersoft.com/redmine/issues/111382> 从QA中得知：

副屏没有mic设备
决定谁播放，中控做决定

#3 - 2022-09-29 09:58 - CD MM陈海波

通过讨论得知:
副屏只考虑申请音频焦点的应用.
目前不对不申请音频焦点的应用做处理.

谢谢!

#4 - 2022-12-22 20:24 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
143276	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com

MM:Audio: Implementing audio focus negotiation with IDCMMImplementing the audio focus negotiation with IDCMT.C-RID: 0301-0900116IssueID:
TS-R-DF-110968Change-Id: I39bab0b853ac28e24fcb16598c112df57220ffb3

#5 - 2022-12-22 20:46 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
158073	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM:Audio: implementing about VoiceCall for audiofocusimplementing about VoiceCall for audiofocusTC-RID: 0301-0900116IssueID: TS-R-DF-110968Change-Id: Ib329a525fed44c5f855a299011dbb0d114b9edb9			

#6 - 2023-02-16 14:42 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
178093	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangjz1204@thundersoft.com
MM: Audio: open audio focus feature1. Enable FSE audio focus controlTC-RID: 0301-0900116IssueID: TS-R-DF-110968Change-Id: I8489dc1a78f1ddb1810cb5f54e8fd2213e87432			

#7 - 2023-02-16 14:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
181645	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangxl0510@thundersoft.com
AF: Bootanimation: Change boot animationSince we enable the IDCMT audio control, If there is no IDCMT,we can't play audio then it will stay at bootanimation and can'tenter home screen.Delete audio data of bootanimation.mp4 to make sure devicecan enter home screen.TC-RID: 1201-0200101IssueID: TS-R-DF-110968Change-Id: I329990c52998c2d41fe952da189f407d8d9babe0			

#8 - 2023-05-31 09:51 - CD MM唐驭俊

- Status changed from New to 完成 Closed

开发完成

close

#9 - 2023-06-15 16:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
206739	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: Fix Abandon focus time too longFix Abandon focus time too longFix the focus release issue of WeChat video callTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-33883Change-Id: I4fb64dcb88b725fc6952976db9f252b51f75f3eb			

#10 - 2023-06-18 22:05 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
207830	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM: Audio: Fix Abandon focus time too longFix Abandon focus time too longFix the focus release issue of WeChat video callTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-33883Change-Id: I4fb64dcb88b725fc6952976db9f252b51f75f3eb(cherry picked from commit c878043239fcd794383ee5ec32c0340fc24e4e12)			

#11 - 2023-06-25 13:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208973	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: Fix WeCom Notification of VOIPFix WeCom Notification of VOIPTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-35413Change-Id: I81f3258257c36146581204f040fca778063ea0cd			

#12 - 2023-06-25 14:04 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209523	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

MM: Audio: Fix WeCom Notification of VOIPFix WeCom Notification of VOIPTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-35413Change-Id: I81f3258257c36146581204f040fca778063ea0cd(cherry picked from commit 3e054ffba12b7833d01d697ea30080a7afa44ad0)

#13 - 2023-07-10 10:34 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212115	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: Fix focus recovery at the end of a callFix focus recovery at the end of a callTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-36025Change-Id: If44fc6f362c17f785f63587c868b63f2d70b575c			

#14 - 2023-07-10 11:34 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213450	general/platform/system/sepolicy	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: Revert MM: Audio: offload disable changeRevert MM: Audio: offload disable changeTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-36968Change-Id: Ie0e04ef914c2c4777c462509793e00d110beb124			

#15 - 2023-07-10 11:34 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213420	general/device/qcom/qssi	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: Revert MM: Audio: offload disableRevert MM: Audio: offload disableTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-36968Change-Id: I8fc76f33e6de848ce0a31bcc6f468ea533e48a07			

#16 - 2023-07-10 11:34 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213454	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com

MM: Audio: Revert MM: Audio: offload disable changeRevert MM: Audio: offload disable changeTC-RID: 0301-0900116IssueID:
TS-R-DF-110968,IOVDEV-36968Change-Id: I8fc76f33e6de848ce0a31bcc6f468ea533e48a07

#17 - 2023-07-12 15:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
213989	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
MM: Audio: Fix focus recovery at the end of a callFix focus recovery at the end of a callTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-36025Change-Id: If44fc6f362c17f785f63587c868b63f2d70b575c(cherry picked from commit e212e2c03098cb7686d5e8ff6248bfeb5425c9db)			

#18 - 2023-07-18 19:55 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
215808	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tangyj0127@thundersoft.com
MM: Audio: lossfocus_in_call status changelossfocus_in_call status changeTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-36672Change-Id: Id29806e78510c532499f19cec862dbbf9475a249			

#19 - 2023-07-19 16:38 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216058	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tangyj0127@thundersoft.com
MM: Audio: Fix Wechat setmode errorFix Wechat setmode errorTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-36017Change-Id: I94e228c1eb6b1c3df5bd7e9c27df87a062efa0f2			

#20 - 2023-07-19 19:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
215949	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangyj0127@thundersoft.com

MM: Audio: disable voip_rxdisable voip_rxTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-36968Change-Id: If5432b64233e4ae19344328ac957aff02006c1f9

#21 - 2023-07-19 23:55 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216245	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM: Audio: lossfocus_in_call status changelossfocus_in_call status changeTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-36672Change-Id: Id29806e78510c532499f19cec862dbbf9475a249(cherry picked from commit a1f7e8e016e72cbef5a1a2b6b9cd28705a5065ae)			

#22 - 2023-07-20 00:06 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216247	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
MM: Audio: disable voip_rxdisable voip_rxTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-36968Change-Id: If5432b64233e4ae19344328ac957aff02006c1f9(cherry picked from commit 03e7e7242fd87af8f1cbc81deeb6574b7f684062)			

#23 - 2023-07-20 23:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216508	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM: Audio: Fix Wechat setmode errorFix Wechat setmode errorTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-36017Change-Id: I94e228c1eb6b1c3df5bd7e9c27df87a062efa0f2(cherry picked from commit ca849c7cf61192ca2c9bed95763f1b3cdebfd612)			

#24 - 2023-07-24 10:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216721	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com

MM: Audio: Fix requestaudiofocus type errorFix requestaudiofocus type error when BT is disconnectedTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-38135Change-Id: I4e91f5f595adb6621f79c11edc0ca9f4e063e781

#25 - 2023-07-25 15:18 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216736	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: Change TIME_OUT_MS to 1000Change TIME_OUT_MS to 1000TC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-35917Change-Id: I5ef3e2e608cea89de05b23a5cff41c624b3c69bc			

#26 - 2023-07-26 10:11 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
214589	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: Fix issue of get focus when switching devices in callFix issue of get focus when switching devices in callTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-38504Change-Id: I3c387ae8ed5bc3bb8711cab7aa9a900abba84418			

#27 - 2023-07-27 11:04 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
217994	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: Fix sync volume when Bluetooth connectingFix sync volume when Bluetooth connectingTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-38449Change-Id: Ie6ed3259fa8596d547802255642e813603ad29b2			

#28 - 2023-07-27 14:00 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218053	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com

MM: Audio: Revert MM: Audio: Fix issue of get focus when switching devices in callRevert MM: Audio: Fix issue of get focus when switching devices in callTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-38504Change-Id: I4756acbd7567fd014066282ed22567c00aab071e

#29 - 2023-07-27 15:25 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218085	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: Fix WeCom Switching DevicesFix WeCom Switching DevicesTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-38504Change-Id: Idb1cde23f32b9c349611ef668dea0bfe0aca8909			

#30 - 2023-07-27 20:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218217	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM: Audio: Fix issue of get focus when switching devices in callFix issue of get focus when switching devices in callTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-38504Change-Id: I3c387ae8ed5bc3bb8711cab7aa9a900abba84418(cherry picked from commit af249167b0f9230cd45fc89a04dc123c11249634)			

#31 - 2023-07-27 20:03 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218218	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM: Audio: Revert MM: Audio: Fix issue of get focus when switching devices in callRevert MM: Audio: Fix issue of get focus when switching devices in callTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-38504Change-Id: I4756acbd7567fd014066282ed22567c00aab071e(cherry picked from commit bfba139af179c07d0ef9753f12d2959343f85ab2)			

#32 - 2023-07-27 23:41 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218209	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

MM: Audio: Change TIME_OUT_MS to 1000Change TIME_OUT_MS to 1000TC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-35917Change-Id: I5ef3e2e608cea89de05b23a5cff41c624b3c69bc(cherry picked from commit 33c0d54260404d31c6c9015b7ddef80b73d530bf)

#33 - 2023-07-27 23:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218243	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
MM: Audio: Fix sync volume when Bluetooth connectingFix sync volume when Bluetooth connectingTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-38449Change-Id: Ie6ed3259fa8596d547802255642e813603ad29b2(cherry picked from commit 9e90c7b09eefbeb968edee367ee2fb0291c49e99)			

#34 - 2023-07-27 23:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218247	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
MM: Audio: Fix WeCom Switching DevicesFix WeCom Switching DevicesTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-38504Change-Id: Idb1cde23f32b9c349611ef668dea0bfe0aca8909(cherry picked from commit 8bcfebb80656d3d414a28eb25e069457e32fc86d)			

#35 - 2023-07-27 23:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218305	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
MM: Audio: Fix requestaudiofocus type errorFix requestaudiofocus type error when BT is disconnectedTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-38135Change-Id: I4e91f5f595adb6621f79c11edc0ca9f4e063e781(cherry picked from commit 25d7b652f3cce18ab595442558a1d3d9cdaef6c)			

#36 - 2023-08-04 15:26 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
300313	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: Fix ANR when adjust volumeFix ANR when adjust volumeTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-33961Change-Id: lccbdce9900b0bbb3dc9064751c65a7f9e105ed99			

#37 - 2023-08-10 20:48 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302380	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM: Audio: Fix ANR when adjust volumeFix ANR when adjust volumeTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-33961Change-Id: lccbdce9900b0bbb3dc9064751c65a7f9e105ed99(cherry picked from commit 147c4d9f88c020189259f3b4241f9ac0f6a3d795)			

#38 - 2023-08-11 10:12 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
302332	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: Fix info is Fix info is TC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-14581Change-Id: l6bda06b2593390e4e8c6edba507e1d77f908dd7f			

#39 - 2023-08-14 18:56 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
303207	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM: Audio: Fix info is Fix info is TC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-14581Change-Id: l6bda06b2593390e4e8c6edba507e1d77f908dd7f(cherry picked from commit a1409f08343f02b8d2c33a427e318f5c747b3fae)			

#40 - 2023-08-21 16:14 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
304781	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangyj0127@thundersoft.com
MM: Audio: Audio HAL Write Data LogAudio HAL Write Data LogTC-RID: 0301-0900116IssueID: TS-R-DF-110968,FIR-268Change-Id: I6d514086ece45833b8a2a7eba866f617fcca4d2f			

#41 - 2023-08-22 18:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
305340	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
MM: Audio: Audio HAL Write Data LogAudio HAL Write Data LogTC-RID: 0301-0900116IssueID: TS-R-DF-110968,FIR-268Change-Id: I6d514086ece45833b8a2a7eba866f617fcca4d2f(cherry picked from commit 7d0449fcfbcc5399e15301497fa36a32a6c364a3)			

#42 - 2023-08-30 17:44 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
307451	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: Modifying the volume wait time to 80msModifying the volume wait time to 80msTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-40451Change-Id: I64a978271d76a681921663eecbeef1ff41d251fc			

#43 - 2023-08-31 23:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
308778	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM: Audio: Modifying the volume wait time to 80msModifying the volume wait time to 80msTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-40451Change-Id: I64a978271d76a681921663eecbeef1ff41d251fc(cherry picked from commit 130e30200a1d6a1d8fc32ca0cb19832fefb8ff3f)			

#44 - 2023-09-25 17:34 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
315784	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: Fix long monitor contention in getDevicesForStreamIntFix long monitor contention in getDevicesForStreamIntTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-41895Change-Id: Ic911a5b75c31b66ea5dd4fe2340b7bae6c1bfb67			

#45 - 2023-10-07 17:06 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317340	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM: Audio: Fix long monitor contention in getDevicesForStreamIntFix long monitor contention in getDevicesForStreamIntTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-41895Change-Id: Ic911a5b75c31b66ea5dd4fe2340b7bae6c1bfb67(cherry picked from commit 3007a46062ad819618aa01cee7db392ebbf880af)			

#46 - 2023-10-18 18:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
320515	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangyj0127@thundersoft.com
MM: Audio: Fix music sound suddenly becomes louder when making a WeChat callFix music sound suddenly becomes louder when making a WeChat callTC-RID: 0301-0900116IssueID: TS-R-DF-110968,PVC1-4104Change-Id: Idcee7c6fba22a88b66816316fc78faa41e59eecd			

#47 - 2023-10-27 02:25 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323346	general/platform/hardware/qcom/audio	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
MM: Audio: Fix music sound suddenly becomes louder when making a WeChat callFix music sound suddenly becomes louder when making a WeChat callTC-RID: 0301-0900116IssueID: TS-R-DF-110968,PVC1-4104Change-Id: Idcee7c6fba22a88b66816316fc78faa41e59eecd(cherry picked from commit			

#48 - 2023-11-08 14:12 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
326509	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: Fix AiQiYi Focus Problems When Screen OffFix AiQiYi Focus Problems When Screen OffTC-RID: 0301-0900116IssueID: TS-R-DF-110968,QMV-163Change-Id: I8fa9a00ff0a8e25418163004dc7c6bc26c416492			

#49 - 2023-11-09 19:54 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
326977	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: Focus handling when Bluetooth is disconnectedFocus handling when Bluetooth is disconnectedTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-38091Change-Id: I0b4f74c8a9882da0b831e1780d993b474afc4e79			

#50 - 2023-11-14 11:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
327875	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM: Audio: Focus handling when Bluetooth is disconnectedFocus handling when Bluetooth is disconnectedTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-38091Change-Id: I0b4f74c8a9882da0b831e1780d993b474afc4e79(cherry picked from commit 9cfc0bd4677cf9597d03547b39b5719c9c2bb72b)			

#51 - 2023-11-20 13:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
329053	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

MM: Audio: Fix AiQiYi Focus Problems When Screen OffFix AiQiYi Focus Problems When Screen OffTC-RID: 0301-0900116IssueID:
TS-R-DF-110968,QMV-163Change-Id: I8fa9a00ff0a8e25418163004dc7c6bc26c416492(cherry picked from commit 83abe53f98305867af93703766ffe60a5e7305c3)

#52 - 2023-11-29 10:29 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
331492	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangyj0127@thundersoft.com
MM: Audio: voice calling mute mediavoice calling mute mediaTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-49150Change-Id: I6912551875db245d872b8f81f73bfe25a1a9ea15			

#53 - 2023-12-11 13:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
334886	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
MM: Audio: voice calling mute mediavoice calling mute mediaTC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-49150Change-Id: I6912551875db245d872b8f81f73bfe25a1a9ea15(cherry picked from commit 022b8f26298bd6112bbdae4ab4af0794bfeb2838)			

#54 - 2023-12-12 09:31 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
335258	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
Revert MM: Audio: voice calling mute mediaThis reverts commit cebf2db58a28f7259963d3ff347675f3d6c2f926.Reason for revert: <revert for tts>TC-RID: 0301-0900116IssueID: TS-R-DF-110968,IOVDEV-49150Change-Id: I86ae0a65cee5484a7f2b388bbb407959f2ffe4ae			