

Figure - 开发 Dev #111031

开发 Dev # 110122 (New): 【MK】管理总票
开发 Dev # 110125 (New): 【MK】【BSP】管理总票
开发 Dev # 110638 (解决 Resolved): 【MK】【008】【BOOT】主任务
【MK】【023】【BUT】【TC-RID: 1200-0102304】添加Android新产品
2022-08-04 16:09 - CD TPM-申艳艳

Status:	完成 Closed	Start date:	2022-08-04
Priority:	Normal	Due date:	2022-10-27
Assignee:	CD BSP-唐金泽	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V1.0_update_20220925		
Description			
请填写信息： ■ 需求列表： https://thundersoft.feishu.cn/sheets/shtcnqaFykINsnMcKWLuICl3xnc L69 添加Android新产品 ■ 提出URL：必填 ■ 自测case：必填 ■ 注意点：需要测试注意的前提条件			

History

- #1 - 2022-08-04 16:10 - CD TPM-申艳艳
- Subject changed from 【MK】【23】【BUT】【TC-RID: 0300-0102304】添加Android新产品 to 【MK】【023】【BUT】【TC-RID: 0300-0102304】添加Android新产品
- #2 - 2022-08-04 21:37 - CD TPM-申艳艳
- Subject changed from 【MK】【023】【BUT】【TC-RID: 0300-0102304】添加Android新产品 to 【MK】【023】【BUT】【TC-RID: 1200-0102304】添加Android新产品
- #3 - 2022-09-06 12:07 - CD BSP-唐金泽
- File 20220906-120711.jpg added
- Status changed from New to 进行中 In Progress
- Assignee changed from CD BSP- 丁武伟 to CD BSP-唐金泽
- 已按照客户最新提供的版本号格式修改了build号
- #4 - 2022-09-13 23:56 - CD BSP-唐金泽

等待PM同步客户需求，后续版本号，是由哪些接口读出：
Ethernet；
CAN；
上层显示；
上层接口；

产品型号从哪里读取；
- #5 - 2022-10-27 21:01 - CD BSP-唐金泽

- Due date set to 2022-10-27
- % Done changed from 0 to 90
- Parent task changed from #110125 to #110638

#6 - 2022-11-01 15:48 - CD BSP-唐金泽

- Status changed from 进行中 In Progress to 解决 Resolved
- Target version set to VX1_MCE_FSE_V1.0_update_20220925
- % Done changed from 90 to 100

#7 - 2022-11-09 11:41 - CD BSP-唐金泽

与浩云沟通确认：
只有在博世fota的时候，会读取版本号
我们正常显示就好
这个我们和他们确定了

#8 - 2022-11-09 11:44 - CD BSP-唐金泽

- Status changed from 解决 Resolved to 完成 Closed

#9 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
140949	general/vendor/thundercomm/products/figure	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:BUT: figure product bring upadd figure productTC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: I18859d0ad8d26fca5da62a31b32385a485a4aebc			

#10 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
141005	general/vendor/thundercomm/products/common	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:BUT: figure product bring upadd product commonTC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: I8d0d3310dda3833381d726f329b00e78e45556b4			

#11 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
141015	general/platform/vendor/qcom-opensource/core-utils	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com

BSP:BUT: figure product bring upadd support for new product in build.shTC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: Ieb5bea2829c9631bd15ba1be2bbeb4cb3e9c5478

#12 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141023	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:BUT: figure product bring up1. enable sanitizer2. clang supportTC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: Id594063cbbac2976b06049a818be476b1bc6057a			

#13 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141026	general/common	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:BUT: figure product bring upuse figure builds insteadTC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: Iba69c3fa2b15930125dc903a8f1c9c76019d0eef			

#14 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141071	general/vendor/thundercomm/products/sepolicy_vndr	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:BUT: Add target SELinux customizationAdd target SELinux customizationTC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: I38587f6cb78b26cb3283223cfee597039902c32d			

#15 - 2022-12-22 20:21 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141072	general/vendor/thundercomm/products/sepolicy	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com

BSP:BUT: Add sepolicy configurationAdd TC sepolicy directoryTC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id:
I22702f7225305bc17eb14d211c5609e8e29ade62(cherry picked from commit 9f41f7e66f94899b106687901023e1f337e82629)

#16 - 2022-12-22 20:22 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141189	general/platform/vendor/qcom-opensource/core-utils	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	dingww0707@thundersoft.com
BSP:BUT: figure product bring upadd support for new product in build.shTC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: Ia27eca67c6737ee8d234613a82dcad488040f44a			

#17 - 2022-12-22 20:22 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141192	general/turbox/tools/build_script/platform	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:BUT: figure product bring upupdate fastboot,meta,hlos for figureTC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: Ia7c6cd5c7fd432aa4610063d7be99fb9e82f5534			

#18 - 2022-12-22 20:22 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
141194	general/turbox/tools/build_script/device	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:BUT: figure product bring upadd figure fastboot flash supportTC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: I9087c3f3e2f1d9b9a54272b33414be297ecf4121			

#19 - 2022-12-22 20:23 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
142332	general/platform/build	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shenyy1110@thundersoft.com

BSP:BUT: qssi build prop custAdd suport for qssi build prop custTC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: Ib177bd10a2b9252de4b079723c9d467bd4af8e5c

#20 - 2022-12-22 20:23 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
142380	general/platform/build	Pre_figure_turbox-c2130c-la1.1-vendor-dev	shenyy1110@thundersoft.com
BSP:BUT: target build prop custAdd suport for target build prop custTC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: I21d008182b725fad8726be195ff62149e714cd77			

#21 - 2022-12-22 20:23 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
142820	general/platform/build	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shenyy1110@thundersoft.com
BSP:BUT: qssi build prop custAdd TARGET_BUILD_VARIANT for privatechange to TC_BUILD_NUMBERTC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: lee2ca6990cf2a1e4b69699e646a1dbdc878a3ff0			

#22 - 2022-12-22 20:23 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
142826	general/platform/build	Pre_figure_turbox-c2130c-la1.1-vendor-dev	shenyy1110@thundersoft.com
BSP:BUT: target build prop custAdd TARGET_BUILD_VARIANT for privatechange to TC_BUILD_NUMBERTC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: le194d427bff177b0b235c5900761cedf73dafc17			

#23 - 2022-12-22 20:24 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
142927	general/turbox/tools/build_script/device	Pre_figure_turbox-c2130c-la1.1-vendor-dev	shenyy1110@thundersoft.com

#24 - 2022-12-22 20:24 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
142933	general/turbox/tools/build_script/platf orm	Pre_figure_turbox-c2130c-la1.1-vendo r-dev	shenyy1110@thundersoft.com
BSP:BUT: target build prop custModify Build nameTC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: l2e764c4d17622e70e96c11649b62c7030916297a			

#25 - 2022-12-22 20:25 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143533	general/turbox/tools/build_script/platf orm	Pre_figure_turbox-c2130c-la1.1-vendo r-dev	shenyy1110@thundersoft.com
BSP:BUT: target build prop custModify release Build zip nameTC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: l8383d289f073c324a4ee837c4ce2333462ab5c1e			

#26 - 2022-12-22 20:25 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
143546	general/turbox/tools/build_script/devi ce	Pre_figure_turbox-c2130c-la1.1-vendo r-dev	wangwei0629@thundersoft.com
BSP:BUT: target build prop custModify release Build zip nameTC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: lf4deabc1886f6f917fa407508263350c4c071338			

#27 - 2022-12-22 20:29 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
147062	general/platform/build	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_evt1	tangjz1204@thundersoft.com
BSP:BUT: qssi build prop custAdd suport for qssi build prop custeg. 01.00.000x.X101TC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id:			

#28 - 2022-12-22 20:29 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
147063	general/platform/build	Pre_figure_turbox-c2130c-la1.1-vendor-release_evt1	tangjz1204@thundersoft.com
BSP:BUT: target build prop custAdd suport for target build prop custeg. 01.00.000x.X101TC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: Ic05379f67cb779c5bb792536b3005751f4d9ffab			

#29 - 2022-12-22 20:29 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
147080	general/platform/build	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiaodong.li@thundersoft.com
BSP:BUT: target build prop custAdd suport for target build prop custeg. 01.00.000x.X101TC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: Ic05379f67cb779c5bb792536b3005751f4d9ffab			

#30 - 2022-12-22 20:29 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
147084	general/platform/build	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xiaodong.li@thundersoft.com
BSP:BUT: qssi build prop custAdd suport for qssi build prop custeg. 01.00.000x.X101TC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: Ib9eb67c253f3710710eb507f7c0927c38a815aef			

#31 - 2022-12-22 20:29 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
147165	general/platform/build	Pre_figure_turbox-c2130c-la1.1-vendor-release_evt1	tangjz1204@thundersoft.com

BSP:BUT: target build prop cust(fix)Add suport for target build prop custeg. 01.00.000x.X101TC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: Idc2e0d5ca456a2a3c92b9417cadcf56dacd7141

#32 - 2022-12-22 20:29 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
147166	general/platform/build	Pre_figure_turbox-c2130c-la1.1-qssi12-release_evt1	tangjz1204@thundersoft.com
BSP:BUT: qssi build prop cust(fix)Add suport for qssi build prop custeg. 01.00.000x.X101TC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: I0aa74783e70df5b00620e7b28869e6a999d06b1d			

#33 - 2022-12-22 20:29 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
147261	general/platform/build	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiaodong.li@thundersoft.com
BSP:BUT: target build prop cust(fix)Add suport for target build prop custeg. 01.00.000x.X101TC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: Idc2e0d5ca456a2a3c92b9417cadcf56dacd7141			

#34 - 2022-12-22 20:29 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
147263	general/platform/build	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xiaodong.li@thundersoft.com
BSP:BUT: qssi build prop cust(fix)Add suport for qssi build prop custeg. 01.00.000x.X101TC-RID: 1200-0102304IssueID: TC-R-DF-111031Change-Id: I0aa74783e70df5b00620e7b28869e6a999d06b1d			

#35 - 2022-12-22 20:37 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152061	general/turbox/tools/build_script/platform	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dulei0503@thundersoft.com

BSP:BUT: Modify images package nameModify DB and Release Build zip nameOld: FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221023.alpha.zipNew:
FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.20.X101.zipTC-RID: 1201-0102304IssueID: TS-R-DF-111031Change-Id:
If13401914f5501b4434d87e8ae2b44fe3553633b

Files			
20220906-120711.jpg	151 KB	2022-09-06	CD BSP-唐金泽