

Status:	New	Start date:	2022-10-28
Priority:	Urgent	Due date:	2023-04-04
Assignee:	CD Test赵飞	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:			
Description			
1、9.30交付：基本功能可用、满足PRD中关于UE的功能定制，A类严重问题解决完毕。			
2、优化完成：基本功能正常、UI/UE基本实现完毕，AB类问题处理完毕。			
3、交付：功能、性能等满足PRD			
Subtasks:			
Bug # 113287: 【AF】【EVT2】【通知中心】查看同一应用的多条通知时，屏幕卡死，无法上下滑动	CLOSED		
Bug # 113292: 【AF】【EVT】【通知中心】用一个测试APP向设备发送少量通知，通知数量显示有误	CLOSED		
Bug # 113293: 【AF】【EVT】【通知中心】同一应用的多条通知，首次进入通知中心时可以点击应用通知标题收起展开...	CLOSED		
Bug # 113294: 【AF】【EVT】【通知中心】重复进入通知中心下方的“历史记录”，会造成settings崩溃	CLOSED		
Bug # 113937: 【AF】【EVT】【通知中心】在后台有设置进程时，点击通知中心下方的“前往通知设置”，点击页面左...	CLOSED		
Bug # 114655: 【AF】【EVT】【通知中心】向左滑动系统消息，等待设备进入屏保，唤醒设备后，通知中心中消息主体...	CLOSED		
Bug # 115050: AF】【EVT】【通知中心】刷机后，首次打开通知中心时，没有通知删除按钮	CLOSED		
Bug # 115072: 【AF】【EVT2】【通知中心&控制中心】把系统字体调至最大后，通知中心和控制中心中的部分文言显示不全	CLOSED		
Bug # 115202: 【AF】【EVT2】【通知中心】进入控制中心编辑页面，点击完成，通知中心的“前往通知设置”按钮单独出现	CLOSED		
Bug # 115700: 【AF】【EVT】【通知中心】点击文字-隐藏通知，会直接跳转到设置页面	CLOSED		
Bug # 115933: 【AF】【EVT】【通知中心】重复左划通知中心的消息，消息主体旁边的设置按钮会消失不见	CLOSED		
Bug # 116306: 【AF】【EVT】【通知中心】当前运行的游戏弹出隐藏通知，打开控制中心关闭游戏模式，通知中心隐藏...	CLOSED		
Bug # 116386: 【AF】【EVT】【通知中心】时钟应用-定时器通知和秒表的暂停通知，部分文言显示不清楚	CLOSED		
Bug # 116460: 【AF】【EVT2】【通知中心】打开任意应用后，点击通知中心下的“前往通知设置”，会先显示应用再...	CLOSED		
Bug # 116725: 【IOISSUE-4644】【AF】【VX1】【EVT2】【通知中心】打开任意应用后，点击通知...	CLOSED		
Bug # 116752: 【AF】【EVT】【通知中心】点击一个应用的隐藏通知，页面跳转时，右上角状态栏短暂闪过所有有隐藏...	CLOSED		
Bug # 117048: 【AF】【EVT3】【通知中心】喜马拉雅车机版退出后台运行，在通知栏仍显示“正在后台收听”	CLOSED		
Bug # 117074: 【AF】【EVT3】【通知中心】通知中心的消息左滑出现删除键，随后按着消息向右滑动手不松并向左滑...	CLOSED		
Bug # 117629: 【AF】【EVT】【通知中心】微信的来电通知中，具体内容看不清楚	CLOSED		
Bug # 117789: 【AF】【EVT3】【通知中心】通知中心无消息时，点击任意空白处进入设置-通知	CLOSED		
Bug # 118987: 【AF】【EVT3】【通知中心】熄屏后点亮设备，随后下划打开通知中心，通知中心背景透明	CLOSED		

History

#1 - 2022-12-05 20:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
167705	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
CommitMessage	AF:Notification: Add transparency effect when swiping left notification		

#2 - 2022-12-07 21:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
168228	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com

AF:Notification: Adjust the background of heads up notificationsAdjust the background of heads up notificationsTC-RID: 1201-0201902IssueID:
TS-R-DF-111051Change-Id: I798c02d7116541331d8e4ad7a898e07038c40762

#3 - 2022-12-22 20:27 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
145643	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	lukf0916@thundersoft.com
AF: Notification: QuickSettings and NotificationStackScroller positionQuickSettings and NotificationStackScroller position.TC-RID: 0301-0201802IssueID: TS-R-DF-111051Change-Id: Id76d2e61f7d8f3ced7e41605e8a4efdbfa34ca8e			

#4 - 2022-12-22 20:28 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
146837	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	lukf0916@thundersoft.com
AF:QuickSettings: re-layout media host1.show a empty media host view by default2.only show 3 buttons when actions button > 33.only show one player when player > 1TC-RID: 1201-0201803IssueID: TS-R-DF-111051Change-Id: Id39f74c1f46c7d57fa11a3ca88e9e00f05909834			

#5 - 2022-12-22 20:30 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
147662	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	lukf0916@thundersoft.com
AF:QuickSettings: add volumeui to qsadd volumeui below to brightnessTC-RID: 1201-0201803IssueID: TS-R-DF-111051Change-Id: I93f541288e8067fe1a7e30c2710a847c51be3ffd			

#6 - 2022-12-22 20:31 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
148362	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	lukf0916@thundersoft.com

AF:QuickSettings: add auto brightness to qs1. add auto brightness2. disable auto brightness btn when start from settings3. don't show mirror when change brightnessTC-RID: 1201-0201803IssueID: TS-R-DF-111051Change-Id: If34afc66b60eb9e23288aa957de5de2f6bd869f7

#7 - 2022-12-22 20:32 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
148476	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com

AF:QuickSettings: re-layout qs panel1. disable power on/off btn in qs footer2. change edit btn from qs footer to qs status bar3. close qspanel when press back key4. change qsTile background corners radius5. change qs volume icon degreesTC-RID: 1201-0201803IssueID: TS-R-DF-111051Change-Id: l8ef6f6a4e2e157f8aac0047e770f3fe5aea017ed

#8 - 2022-12-22 20:33 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
149852	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com

AF:QuickSettings: re-layout qs customizer1. disable qs status bar icon2. change radius for notification scrim,media host,qs brightness,qs volume3. add menu done for qs customizer4. change qs customizer to full screen5. support time am/pmTC-RID: 1201-0201803IssueID: TS-R-DF-111051Change-Id: l134db26d7067b2d18833c364c46141eddcbb3286

#9 - 2022-12-22 20:33 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
149904	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com

AF:QuickSettings: add GameMode Tileadd empty game mode tileTC-RID: 1201-0201803IssueID: TS-R-DF-111051Change-Id: Ice2e4b9766814ff627732d03dcba078ecf9baa30

#10 - 2022-12-22 20:34 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150082	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification:Modify Notification UE1.Add notification display list config2.Notifications are displayed according to configuration categories (whether to hide them or not)3.Hide the default collapse and expand actions of notifications4.Partial notification UITC-RID: 1201-0201802IssueID: TS-R-DF-111051Change-Id: I80cbea1419fab06e0fdf4a151169746b060e5503			

#11 - 2022-12-22 20:36 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
151162	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification:Modify Notification UEApplications that are not in the notification display list cannot have their notification settings adjustedso the relevant items are grayed outTC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id: I3c1d82158cecf9554330d9e14fb9e6d23b166957			

#12 - 2022-12-22 20:36 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
151192	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification:Modify Notification UE1.Add the function of displaying menu with left swipe of notification2.Items in the notification menu are dynamically displayed according to the characteristics of the notificationTC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id: If9f3313b4de158fa9cbf3422b52249d90ff4405b			

#13 - 2022-12-22 20:36 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader

151242	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Whitelist configuration location changePlace notification whitelist in android package for multiple app accessTC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id: lcd2a3d994679546d721046917b82f74f8c879bc5			

#14 - 2022-12-22 20:36 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
151314	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification:Modify Notification UEDisable notification long press operationTC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id: Id8e340e903b108a469c987403f7ee01c4161ff95			

#15 - 2022-12-22 20:37 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152204	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification:Modify Notification UE1.Add the Go to Notification Settings item2.Add notification center header view3.Change the display and action of the clear functionTC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id: Ic9f3275c536280db2e14a29fd0f07154af865e4b			

#16 - 2022-12-22 20:40 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
153446	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Modify Notification UE1.Show hidden notification bar when only hidden type notifications are available2.When only hidden notifications are available, "no notifications" should not be displayed3.When there is no notification at all, the notification header should not be displayed3.Delete notification shelfTC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id: l196410bf662b0e29bc7acd14493681b920292939			

#17 - 2022-12-22 20:43 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155511	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification:the base version of Notification UIthe base version of Notification UITC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id: I7181be8eb7dd57519c4d0136e59091925a5dc115			

#18 - 2022-12-22 20:44 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155929	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Whitelist configuration changeWhitelist configuration changeTC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id: I5449336732be67e835150e87773ab26445a4dc48			

#19 - 2022-12-22 20:44 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
156105	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Improved display of notification menu1.Make the notification menu show up gradually by modifying the transparency2.Make the notification menu invisible when it is obscuredTC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id: I0cee881d0ee68c8ea2863bdc65ce908873536df6			

#20 - 2022-12-22 20:44 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
156242	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Improved display of notification menuImprove the problem that the notification menu is sometimes obscured when the notification is swiped leftTC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id: Ie10f6259600328d30666e0c08149c5c4cc8f5604			

Gerrit Merge Information :

ID	Project	Branch	Uploader
165091	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification:the base version of Notification UIthe base version of Notification UI1.notification header2.notification3.notification expand button4.notification group5.notification slient header6.notification footer7.notification menuTC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id: I27eeec61422207def614bdb402a25d1f6ee3d400			

Gerrit Merge Information :

ID	Project	Branch	Uploader
188277	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: UI change for VC1TC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id: Id08ef8105027d1fb7b3af94bff526a7c3f297e9f			

Gerrit Merge Information :

ID	Project	Branch	Uploader
313282	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Adapt the new UI for the VC1 model.TC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id: I251728e0ab7297206b48987014e308d8b4db0dc9			

Gerrit Merge Information :

ID	Project	Branch	Uploader
314535	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Adapt the new UI for the VC1 model.TC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id:			

#25 - 2023-09-20 20:01 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
314630	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Notification: Adapt the new UI for the VC1 model.TC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id: I251728e0ab7297206b48987014e308d8b4db0dc9(cherry picked from commit ebb5bbeb9c36d444ff309b12c1fd11ebab8bc72f)			

#26 - 2023-09-20 20:09 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
314638	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Notification: Adapt the new UI for the VC1 model.TC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id: I8729e749adf4c71586c1cc361b5491f43b121227(cherry picked from commit 51d745907ec55993fcf043059e1240daeca3dd0b)			

#27 - 2023-10-07 19:18 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317377	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Change the icon for the settings in the notification menu.TC-RID: 1201-0201902IssueID: TS-R-DF-111051, IOVDEV-44755Change-Id: Ie8129307ff5aa76053dfd59ffbabcb4b1f1228916			

#28 - 2023-10-12 15:13 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
318779	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Adapt the new UI for the MCE model.TC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id: Ifc535b932205caae8d03315966a83ac7b15a1388			

Gerrit Merge Information :

ID	Project	Branch	Uploader
319108	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Notification: Change the icon for the settings in the notification menu.TC-RID: 1201-0201902IssueID: TS-R-DF-111051, IOVDEV-44755Change-Id: Ie8129307ff5aa76053dfd59ffbab4b1f1228916(cherry picked from commit 2d54ecf546de06c755d584598e6bda86adccc51a)			

Gerrit Merge Information :

ID	Project	Branch	Uploader
323287	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:Notification: Adapt the new UI for the MCE model.TC-RID: 1201-0201902IssueID: TS-R-DF-111051Change-Id: Ifc535b932205caae8d03315966a83ac7b15a1388(cherry picked from commit 80ae8f82ccb16adaf0f3591d4b76a5e417204e1b)			