

Figure - 开发 Dev #111225

开发 Dev # 110122 (New): 【MK】管理总票
开发 Dev # 111116 (New): 【MK】【LC】管理总票
【MK】【002】【Wi-Fi】【TC-RID: 1201-0400228】wifi连接测试
2022-08-11 20:31 - CD LC-徐玺栋

Status:	New	Start date:	2023-01-16
Priority:	Normal	Due date:	2023-02-03
Assignee:	CD LC-徐玺栋	% Done:	60%
Category:	LC	Estimated time:	0.00 hour
Target version:			

Description

请填写信息：

■需求列表:

<https://thundersoft.feishu.cn/sheets/shtcnqaFykINSnMcKWLuICl3xnc>

■提出URL：必填

■自测case：必填

■注意点：需要测试注意的前提条件

Subtasks:

开发 Dev # 115373: MK】【002】【Wi-Fi】【TC-RID: 1201-0400228】添加WIFI模块...

解决 Resolved

History

#1 - 2022-12-22 20:27 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
145629	general/platform/external/wpa_supplicant_8	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tuyu0702@thundersoft.com
LC:WIFI:Disalbe EAP_PROXY1.Solve the problem that WiFi turn off slowly.2.Disalbe EAP_PROXY because there is no Mobile, and no need foreap proxy.TC-RID: 1201-0400228IssueID: TS-R-DF-111225Change-Id: I3309e5219a68c2be2114631d3702b829133650a5			