

Figure - Bug #111437

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 110875 (New): BSP-BVT测试-TP

【BSP】【EVT】【TP】【必现】上滑/下滑手势无效

2022-08-24 20:33 - SZTS_TEST 邹涛

Status:	CLOSED	Start date:	2022-08-24
Priority:	High	Due date:	
Assignee:	CDTS_TEST 王成	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:	依赖客户及其供应商问题List	Found Version:	0.0.0.20220824_alpha_private_userdebug
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Critical	Fixed Version:	
Reproducibility:	Frequently	Root cause:	
Test Type:	Bring Up Test		
Description			
前置条件：			
1、 DUT各模块功能正常且处于开机状态			
2、 DUT已经外接屏幕			
操作步骤：			
1、 顶部下滑查看页面显示			
2、 底部向上滑动查看页面显示			
预期结果：			
1、 手势生效，打开通知中心			
2、 手势生效，返回launcher首页			
实际结果：			
1、 手势不生效，只有滑动轨迹反馈			
2、 手势不生效，只有滑动轨迹反馈			

History

#1 - 2022-08-30 15:20 - SZ BSP-徐季源
- Assignee changed from SZ BSP- 徐季源 to CD BSP- 唐金泽

#2 - 2022-08-31 16:28 - CD BSP-唐金泽
- File 20220831-working on other project.jpeg added
- File 20220831-issue on Figure.jpeg added
- Status changed from New to ASSIGNED
- Assignee changed from CD BSP- 唐金泽 to CD BSP- 余霄

现分析是因为抬手后报点手势有回勾，导致抬手有问题。
TP的固件问题，需要由厂家分析，出现该状况原因
后续由余霄跟进。！

#3 - 2022-09-08 23:04 - CD BSP-唐金泽
- Category set to BSP

#4 - 2022-09-21 12:01 - CD BSP-余霄

VC1屏幕touch能正常操作，确认为VX1屏幕固件问题。

#5 - 2022-09-27 11:14 - 物联网项目组-RD3_CDTS 周飞

- Target version set to 依赖客户及其供应商问题List

#6 - 2022-10-14 11:03 - CD BSP-余霄

- Status changed from ASSIGNED to RESOLVED

- Assignee changed from CD BSP-余霄 to CDTS_TEST 王成

优化后驱动处断点问题后 其他均与820a差别不大

请使用10-14 DB进行验证

#7 - 2022-10-18 14:04 - CDTS_TEST 王成

- Status changed from RESOLVED to VERIFIED

目前优化后的版本，除了低概率的触控断点，TP已和客户提供的样机差距不大，

#8 - 2022-10-18 14:04 - CDTS_TEST 王成

- Status changed from VERIFIED to CLOSED

Files			
logcat22222.txt	6.08 MB	2022-08-24	SZTS_TEST 邹涛
20220831-working on other project.jpeg	2.15 MB	2022-08-31	CD BSP-唐金泽
20220831-issue on Figure.jpeg	630 KB	2022-08-31	CD BSP-唐金泽