

Figure - Bug #111524

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 110880 (New): BSP-BVT测试-launcher

【AF】【EVT】【launcher】【偶现一次】launcher页面dock栏消失

2022-08-29 20:43 - SZTS_TEST 邹涛

Status:	CLOSED	Start date:	2022-08-29
Priority:	High	Due date:	
Assignee:	SZTS_TEST 邹涛	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V1.0_update_20220925	Found Version:	0.0.0.20220826_alpha_private_userdebug
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	
Severity:	Critical	Fixed Version:	2022-09-05
Reproducibility:	Rarely	Root cause:	在setInsets()方法中设置hotseat的高度
Test Type:	Bring Up Test		
Description			
前置条件			
1、 DUT各模块功能正常且处于开机状态			
操作步骤：			
1、 正常使用TP过程中，查看屏幕显示			
实际结果：			
1、 launcher页面dock消失			
预期结果：			
1、 launcher页面dock正常显示，不会消失			

History

#1 - 2022-08-31 16:15 - CD APP-王营
- Assignee changed from CD APP-王营 to CD- App-李朝鹏

#2 - 2022-09-02 16:47 - CD- App-李朝鹏
- Status changed from New to ASSIGNED
- % Done changed from 0 to 70

#3 - 2022-09-02 17:00 - CD- App-李朝鹏

- Current conclusion
- 已修改，等待测试进行验证
- My analysis
- 1.在setInsets方法中设置了hotseat的高度为零，这方法会在launcher运行中被多次调用，导致hotseat再次被设为零。
- 2.现从setInsets方法中移出对hotseat高度的设置。
- 3.直接在hotseat的布局文件中设置hotseat的高度。
- Next action / ■ Submit URL
- 1.等待测试验证。
- 2.进行launcher进行各种操作，观察hotseat是否消失。

#4 - 2022-09-06 16:18 - CD- App-李朝鹏

- Status changed from ASSIGNED to RESOLVED
- Target version set to 594
- % Done changed from 70 to 100
- Resolution changed from -- to FIXED
- Fixed Version set to 2022-09-05
- Root cause set to 在setInsets()方法中设置hotseat的高度

■ Current conclusion

测试同事已验证，未出现hotseat消失情况

■ My analysis

- 1.在Hotseat类的setInsets()方法中设置了hotseat的高度为零，在launcher上的所有组件都加载完成后，将hotseat的高度设置为4个图标的高度，setInsets()这个方法会在操作launcher的过程中被多次调用，导致hotseat再次被设为零，进而看不到hotseat。
- 2.现从setInsets方法中移出对hotseat高度的设置。
- 3.直接在hotseat的布局文件中设置hotseat的高度。
- 4.进而不存在hotseat的高度被再次设为0的情况。

■ Next action / ■ Submit URL

- 1.等待测试验证。
- 2.进行launcher进行各种操作，观察hotseat是否消失。

#5 - 2022-09-06 16:19 - CD- App-李朝鹏

- Assignee changed from CD- App-李朝鹏 to SZTS_TEST 邹涛

■ Current conclusion

测试同事已验证，未出现hotseat消失情况

■ My analysis

- 1.在Hotseat类的setInsets()方法中设置了hotseat的高度为零，在launcher上的所有组件都加载完成后，将hotseat的高度设置为4个图标的高度，setInsets()这个方法会在操作launcher的过程中被多次调用，导致hotseat再次被设为零，进而看不到hotseat。
- 2.现从setInsets方法中移出对hotseat高度的设置。
- 3.直接在hotseat的布局文件中设置hotseat的高度。
- 4.进而不存在hotseat的高度被再次设为0的情况。

■ Next action / ■ Submit URL

- 1.等待测试验证。
- 2.进行launcher进行各种操作，观察hotseat是否消失。

#6 - 2022-09-14 11:52 - CD TPM-申艳艳

- Category set to CD-APP

#7 - 2022-09-14 17:05 - SZTS_TEST 邹涛

release分支0907号版本验证问题已修复

#8 - 2022-09-14 17:09 - SZTS_TEST 邹涛

- Status changed from RESOLVED to VERIFIED

#9 - 2022-09-14 17:09 - SZTS_TEST 邹涛

- Status changed from VERIFIED to CLOSED

#10 - 2022-09-16 09:39 - CD SWPM-杨宏伟

- Target version changed from 594 to VX1_MCE_FSE_V1.0_update_20220925

#11 - 2023-04-06 18:33 - CD BSP-杜磊

- Subject changed from 【BSP】 【EVT】 【launcher】 【偶现一次】launcher页面dock栏消失 to 【AF】 【EVT】 【launcher】 【偶现一次】launcher页面dock栏消失

Files

logcat.txt	4.53 MB	2022-08-29	SZTS_TEST 邹涛
------------	---------	------------	--------------