

Figure - Bug #111740

【Figure】【EVT】【电气性能】E20 反馈：下降1V以下时间大于20ms，试验后，重新上电，运行操作指令，功能正常

2022-09-05 15:58 - 项目二组\_SD3 曾小文

Status:	CLOSED	Start date:	2022-09-05
Priority:	High	Due date:	2022-09-26
Assignee:	SZ HW Test-曾小文	% Done:	0%
Category:	EE	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	2022.08.25
Resolution:	--	Degrated:	--
Severity:	Major	Verified Version:	
Reproducibility:	Every time	Fixed Version:	
Test Type:	Release Test	Root cause:	
Description			

History

- #1 - 2022-09-14 11:31 - CD TPM-申艳艳
- Category set to EE
- #2 - 2022-09-23 16:51 - IOT-SP-TEST 刘颖
- Due date set to 2022-09-26
- Assignee changed from SZ-硬件二组\_SD3 王苗 to SZ HW Test-曾小文

今天金辉自测已通过，需要测试同学安排复测；

- #3 - 2022-10-09 17:35 - SZ HW Test-曾小文
- Status changed from New to RESOLVED

复测PASS

- #4 - 2022-10-09 17:36 - SZ HW Test-曾小文
- Status changed from RESOLVED to VERIFIED

复测PASS

- #5 - 2022-10-09 17:36 - SZ HW Test-曾小文
- Status changed from VERIFIED to CLOSED