

Figure - 开发 Dev #111811

开发 Dev # 110122 (New): 【MK】管理总票
开发 Dev # 110126 (New): 【MK】【AF】管理总票
【MK】【APP】【LeBoCastApp】【TC-RID: 1201-0300501】
2022-09-08 08:24 - CD FW-王伟

Status:	完成 Closed	Start date:	2022-09-08
Priority:	Normal	Due date:	2022-09-16
Assignee:	CD FW王武军	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:			
Description			
■ 需求列表: 集成乐播投屏的SDK，实现相关投屏功能，PRD： https://thundersoft.feishu.cn/docx/doxcniTUEPldhB9hq1trqSQOnEg ■ 提出URL：必填 ■ 自测case：必填 ■ 注意点：需要测试注意的前提条件			

History

- #1 - 2022-09-08 08:28 - CD FW-王伟
- Subject changed from 【MK】【LeBoCastApp】【TC-RID: 1201-0300701】 to 【MK】【APP】【LeBoCastApp】【TC-RID: 1201-0300701】
- #2 - 2022-11-14 11:36 - CD FW-王伟
- Assignee changed from CD AF-陈羽杰 to CD FW王武军
- #3 - 2022-11-14 11:37 - CD FW-王伟
- 乐播的开发，还没有完成，待UE确定好之后，需要对照着再次检查开发
- #4 - 2022-11-14 11:37 - CD FW-王伟
- Status changed from New to 进行中 In Progress
- % Done changed from 0 to 50
- #5 - 2022-12-22 18:14 - CD FW-王伟
- Subject changed from 【MK】【APP】【LeBoCastApp】【TC-RID: 1201-0300701】 to 【MK】【APP】【LeBoCastApp】【TC-RID: 1201-0300501】
- #6 - 2022-12-22 20:48 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
159763	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:LeboCast: LeboCast Base Code1.LeboCast Base CodeTC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: Ic2b4f02a40d170c6ea72cf9739a5a8eb682714fc			

#7 - 2022-12-22 20:49 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
159764	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:LeboCast: add selinux permissionTC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: Ia579e18ee1189e15f23d326451671fa6678df023			

#8 - 2022-12-22 20:50 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
160666	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:LeboCast: Default dynamic permission for mediaTC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: Ia91688feb7674fb4b167c0a0b0c8a43cf4aec2c4			

#9 - 2022-12-23 13:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
171842	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:LeboCast: UI changeTC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I3bb9aad982183cc7b5d637a34bb168a9c8e196e			

#10 - 2023-01-18 11:06 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
177334	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:LeboCast:Change connect stringTC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I26ab1637361a4c101c78ba63cfce5b793ff19d28			

#11 - 2023-02-02 09:51 - CD FW王武军

- Status changed from 进行中 In Progress to 完成 Closed
- % Done changed from 50 to 100

投屏引导界面已经由其他同事投入，关闭该票

#12 - 2023-03-14 20:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
187266	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:LeboCast:VC1 UI matchTC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I59fa8b6e33c0c12a103566a93349e3e15d581cb8			

#13 - 2023-04-07 17:03 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
192410	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wujun.wang@thundersoft.com
AF:LeboCast: update new sdkVersion:SDK_r60055_27705TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: Ib52e7cee3bb8dd062f272c8628820f4b308c2e32			

#14 - 2023-04-21 17:11 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
195320	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:LeboCast: update new sdkVersion:SDK_r60055_27707TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: Ie4d74ed97a17b832a3ae57629781054c1c4bcd2a			

#15 - 2023-05-26 13:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
201726	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:LeboCast: update launch icon and app name1.update launch icon2.update app name3.update package name4.update sdkTC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I7bb508a908d4832e1ae0c741a68a5d97f8767573			

#16 - 2023-06-05 16:00 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
204022	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:LeboCast: Set prefer ip address to AP1.Set prefer ip to AP2.When cast service on create init lebo serviceTC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I55d25bf7ecbbd47095e397d6c51472397b06ee3f			

#17 - 2023-06-13 21:16 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
207025	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:LeboCast: Fixed can't find deviceTC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I6f709c7284e9dd72b900da4f5d3e8888853d06de			

#18 - 2023-06-14 09:31 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
207048	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:LeboCast: Fixed can't find deviceTC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I6f709c7284e9dd72b900da4f5d3e8888853d06de(cherry picked from commit 4866a4b3e4fdcbcd6a112e655be025c9b4671527)			

#19 - 2023-06-15 22:06 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
207854	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:LeboCast: Restart server when wifi changed.TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I43833d6ddd3e0d854bd62019a1a1fc6670755f3f			

#20 - 2023-06-15 22:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
207832	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

AF:LeboCast: Restart server when wifi changed.TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I43833d6ddd3e0d854bd62019a1a1fc6670755f3f

#21 - 2023-06-20 14:04 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208640	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:LeboCast: Disable watermark on top-left corner.TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I93d8fb4641f0d0e975b1af9b98ab3b81bd18bd51			

#22 - 2023-06-20 19:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208739	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:LeboCast: Use Device's SerialNo for Lebo license.TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I7b6d873b536484cabe65493a0d0f6cfa08db9434			

#23 - 2023-06-25 21:31 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209205	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:LeboCast: Disable watermark on top-left corner.TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I93d8fb4641f0d0e975b1af9b98ab3b81bd18bd51(cherry picked from commit a2640391bbe3e9c08d2414eac4da265b3fa5b454)			

#24 - 2023-06-25 21:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209666	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:LeboCast: Use Device's SerialNo for Lebo license.TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I7b6d873b536484cabe65493a0d0f6cfa08db9434(cherry picked from commit de19f5c5ebf83c6204db6100519f37ffe804bae5)			

#25 - 2023-06-28 17:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
210832	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:LeboCast: Fix lebo can't find device problem.Add option of control music steam only.TC-RID: 1201-0300501IssueID: TS-R-DF-111811, IOVDEV-36124Change-Id: I822371393d1a8f9231e47f0de643f6f1e283df09			

#26 - 2023-06-30 16:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
210855	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:LeboCast: Fix lebo can't find device problem.Add option of control music steam only.TC-RID: 1201-0300501IssueID: TS-R-DF-111811, IOVDEV-36124Change-Id: I822371393d1a8f9231e47f0de643f6f1e283df09(cherry picked from commit 1334b6705521372969971d895df05f008ca06839)			

#27 - 2023-08-14 18:09 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
303090	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:LeboCast: update new sdkversion: SDK_r60057_28110TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I4f497274b39c1faf6f371fae4a97f0af590e4fe3			

#28 - 2023-08-14 18:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
303212	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:LeboCast: update new sdkversion: SDK_r60057_28110TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I4f497274b39c1faf6f371fae4a97f0af590e4fe3(cherry picked from commit ed37efe0c07fa728b56ba5b4413d9d81c6a4541e)			

#29 - 2023-09-13 11:01 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
312174	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:LeboCast: Disable when HiCar connectTC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I025510397c1a75366d183fef76b3f60f44256f6f			

#30 - 2023-09-19 15:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
313742	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:LeboCast: VC1 UI V1.2TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: If404511c78dd2d84f6934ec7fe792d8e25aabf72			

#31 - 2023-09-20 20:18 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
314643	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:LeboCast: Disable when HiCar connectTC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I025510397c1a75366d183fef76b3f60f44256f6f(cherry picked from commit b42328426755183b97b523adef7c79b928a22a24)			

#32 - 2023-09-20 20:18 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
314644	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:LeboCast: VC1 UI V1.2TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: If404511c78dd2d84f6934ec7fe792d8e25aabf72(cherry picked from commit 754db9cf994cce58a77ee99ce196b376542dcf64)			

#33 - 2023-10-12 19:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317743	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com

AF:LeboCast: update new sdkversion: SDK_r60057_28112TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: l1c450b8197d1d83f0847c40f55a7ee3c6c5377e2

#34 - 2023-10-12 22:35 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
319126	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:LeboCast: update new sdkversion: SDK_r60057_28112TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: l1c450b8197d1d83f0847c40f55a7ee3c6c5377e2(cherry picked from commit 39e6cf238a306cd686d5024491602b28a6aefe36)			

#35 - 2023-10-18 15:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
320451	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:LeboCast: MCE UI V2.1TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: l5ec7d01f23076ba06f2c67dd84f0e3847e88c187			

#36 - 2023-10-27 01:49 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323304	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:LeboCast: MCE UI V2.1TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: l5ec7d01f23076ba06f2c67dd84f0e3847e88c187(cherry picked from commit e9a9e9ddce0fe91c632b4ebdcb9d85d0991ce151)			

#37 - 2023-12-21 19:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
338463	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com

AF:LeboCast: update new sdkversion: SDK_r60065_29501TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id:
I3fe01e2661a84b5a66c675a0e902d05f5d6c65fb

#38 - 2023-12-25 21:38 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
339810	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:LeboCast: update new sdkversion: SDK_r60065_29501TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I3fe01e2661a84b5a66c675a0e902d05f5d6c65fb(cherry picked from commit cafec28ef788855b624e86c1b7552473a9b03d7d)			

#39 - 2023-12-28 14:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
340130	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:LeboCast: update new sdkversion: SDK_r60065_29505TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I8c462b1781e26cda5c04d23ce40b10fa21e1fdca			

#40 - 2023-12-28 14:56 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
340720	general/platform/vendor/hht/apps/LeBoCast	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
AF:LeboCast: update new sdkversion: SDK_r60065_29505TC-RID: 1201-0300501IssueID: TS-R-DF-111811Change-Id: I8c462b1781e26cda5c04d23ce40b10fa21e1fdca(cherry picked from commit 6fd9107b1799985bae0dc9b4361c63f4756a0be5)			