

Figure - Bug #112016

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 110895 (New): AF-V1.0功能测试-桌面

【AF】【EVT】【桌面】长按有微件功能的应用图标出现微件添加按钮，点击该按钮，屏幕刷新，回到主页面

2022-09-19 15:32 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-09-19
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20220919
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	2022-09-22
Severity:	Normal	Fixed Version:	2022-09-22
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、有微件功能的应用图标			
2、在弹出的菜单中选择微件			
【预期结果】			
2、进入微件添加列表			
【实际结果】			
2、屏幕刷新，回到主页面			
【复现率】			
必现			

History

#1 - 2022-09-19 17:07 - CD FW-王伟
- Assignee changed from CD FW-王伟 to CD APP-黄棚

#2 - 2022-09-19 17:34 - CD APP-黄棚
- Status changed from New to ASSIGNED

■ Current conclusion
分析中
■ My analysis
通过log分析，对象类型转换错误导致
■ Next action / ■ Submit URL
修改对象类型为linearlayout

#3 - 2022-09-19 17:36 - CD APP-黄棚

- Status changed from ASSIGNED to RESOLVED
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED

■ Current conclusion

已经找打维妮塔

■ My analysis

通过log分析，对象类型转换错误导致

■ Next action / ■ Submit URL

修改对象类型为linearlayout

#4 - 2022-09-20 10:15 - CD APP-黄棚

- Verified Version set to 2022-09-21
- Fixed Version set to 2022-09-21

#5 - 2022-09-20 16:09 - CD APP-黄棚

- Assignee changed from CD APP-黄棚 to CD TEST-方永红

#6 - 2022-09-20 16:26 - CD APP-王营

- Root cause set to 编码问题

#7 - 2022-09-20 16:36 - CD APP-王营

- Degrated changed from -- to No

#8 - 2022-09-21 10:10 - CD TEST-方永红

- Status changed from RESOLVED to VERIFY_FAILED
- Assignee changed from CD TEST-方永红 to CD APP-黄棚

#9 - 2022-09-21 10:50 - CD APP-黄棚

- Status changed from VERIFY_FAILED to RESOLVED
- Verified Version changed from 2022-09-21 to 2022-09-22
- Fixed Version changed from 2022-09-21 to 2022-09-22

■ Current conclusion

已经找到问题，之前只改了一处，还有另外一处需要转换，以确定只有两处

■ My analysis

通过log分析，对象类型转换错误导致

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Launcher3/+150293>

#10 - 2022-09-21 18:50 - CD APP-黄棚

- Assignee changed from CD APP-黄棚 to CD TEST-方永红

#11 - 2022-09-23 10:18 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

#12 - 2022-09-23 10:19 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Gerrit Merge Information :

ID	Project	Branch	Uploader
149832	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:Launcher: Fix the bug of adding widgets from the application information entry to crash1.Fix the bug of adding widgets from the application information entry to crashTC-RID: 1201-0205305IssueID: TS-R-DF-112016Change-Id: I470b969009a604a8c777ab3297b418337a472352			

Gerrit Merge Information :

ID	Project	Branch	Uploader
150293	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW:Launcher: Fix the bug of adding widgets from the application information entry to crash1.Fix the bug of adding widgets from the application information entry to crashTC-RID: 1201-0205305IssueID: TS-R-DF-112016Change-Id: I45f7c20bed651ff0d9528f349661bb7bdf6f5b25			

Files

应用-微件-闪退.log	17.1 KB	2022-09-19	CD TEST-方永红
--------------	---------	------------	-------------