

Figure - 开发 Dev #112090

开发 Dev # 110122 (New): 【MK】 管理总票
开发 Dev # 110125 (New): 【MK】 【BSP】 管理总票
开发 Dev # 112089 (New): 【MK】 【012】 【TSNV】 主任务
【MK】 【012】 【TSNV】 基本功能 bring up
2022-09-21 20:58 - CD BSP-丁武伟

Status:	完成 Closed	Start date:	2022-09-21
Priority:	Normal	Due date:	2022-09-30
Assignee:	CD BSP-丁武伟	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V2.0_20220930		
Description			
TSNV基本功能：			
- 分区创建 - bootloader api - driver - host 工具 - hal接口 - 测试工具			

History

#1 - 2022-09-26 15:43 - CD BSP-丁武伟
- Status changed from 进行中 In Progress to 解决 Resolved
- % Done changed from 0 to 100

基本功能验证OK：

vendor侧验证情况：

```
figure:/ # tsnv_test -r -s 4 -n 1
0x1348bf9
```

Platform侧验证情况：

```
figure:/ # setenforce 0
figure:/ # tsnvwrapper_test -r -s 4 -n 1
0x1348bf9
```

BRs,
Ding Wuwei

#2 - 2022-10-31 20:08 - CD BSP-唐金泽
- Due date set to 2022-09-30
- Status changed from 解决 Resolved to 完成 Closed

#3 - 2022-12-22 20:34 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150338	general/abl/tianocore/edk2	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:TSNV: bootloader nv supporttsnv bootloader bring upTC-RID: 1200-0102301IssueID: TS-R-DF-112090Change-Id: I31743984db7b9792949064a931309fe56306d23b			

#4 - 2022-12-22 20:35 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150377	general/vendor/thundercomm/tsnv	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:TSNV: nv integrationintegrate nv main componentsTC-RID: 1200-0102301IssueID: TS-R-DF-112090Change-Id: I20847cf3e4457d1803a9c52567e0f3e04420d56a			

#5 - 2022-12-22 20:35 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150390	general/vendor/thundercomm/productions/common	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:TSNV: add tsnv to commonadd tsnv to thundercomm commonTC-RID: 1200-0102301IssueID: TS-R-DF-112090Change-Id: Ic87ac834f4b5226d207499d4a4ad20d093ac3afe			

#6 - 2022-12-22 20:35 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150391	general/vendor/thundercomm/productions/sepolicy_vndr	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:TSNV: nv integrationremove duplicate typeTC-RID: 1200-0102301IssueID: TS-R-DF-112090Change-Id: Ica8bfddddd55ac44966c33892e5b1dc06ca47b514			

#7 - 2022-12-22 20:35 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150399	general/vendor/thundercomm/productions/figure	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:TSNV: nv integrationadd tsnv related to commonTC-RID: 1200-0102301IssueID: TS-R-DF-112090Change-Id: I5b229ec833d83938f85dcb672125e31ecd766c0c			

#8 - 2022-12-22 20:35 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150401	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:TSNV: nv integrationfix QIIFA error:ERROR Description : Hidl interface doesn't exist in thecoresponding QIIFA cmdby:vendor/qcom/proprietary/commonsys-intf/QIIFA-fwk/qiifa_main.py \--create hidl_new <interface-name>TC-RID: 1200-0102301IssueID: TS-R-DF-112090Change-Id: Iebf911ed63ef71347696290522e26a3e3d29aa43			

#9 - 2022-12-22 20:35 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150407	general/LA.QSSI/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	dingww0707@thundersoft.com
BSP:TSNV: nv integrationfix QIIFA error:ERROR Description : Hidl interface doesn't exist in thecoresponding QIIFA cmdby:vendor/qcom/proprietary/commonsys-intf/QIIFA-fwk/qiifa_main.py \--create hidl_new <interface-name>TC-RID: 1200-0102301IssueID: TS-R-DF-112090Change-Id: Iaf44386b7df974962dad6aaf037256198d2d0ed4			

#10 - 2022-12-22 20:35 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150408	general/device/qcom/qssi	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	dingww0707@thundersoft.com
BSP:TSNV: add qssi customization entryadd thundercomm qssi cust entryTC-RID: 1200-0102301IssueID: TS-R-DF-112090Change-Id: I257e5a41049900a5db407bde668eca2ecd21ca03			

#11 - 2022-12-22 20:35 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
150412	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:TSNV: nv integrationdisable kernel module signatureTC-RID: 1200-0102301IssueID: TS-R-DF-112090Change-Id: Ia0070e66de520b5ae58815dfa2f63143e2ca41fd			