

Figure - 开发 Dev #112095

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 112093 (New): 【MK】【电子电气零部件环境可靠性实验ClassC】实现汇总

【MK】【AF】APP 恢复实现

2022-09-22 10:57 - CD TPM-申艳艳

Status:	完成 Closed	Start date:	2022-09-22
Priority:	Normal	Due date:	
Assignee:	CD APP-王营	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_20221030		
Description			
1. 和MCU通讯			
2. APP 恢复			

History

#1 - 2022-09-22 11:27 - CD FW-王伟

- Assignee changed from CD FW-王伟 to CD- FW-石豪

请豪哥帮忙实现一下吧，我们这边先实现：

1.接收MCU过来的数据，获取到过压或者欠压的事件。

2.收到信息之后，打桩，记录状态，也周知音乐播放器保存状态。

#2 - 2022-09-26 18:40 - CD FW-王伟

- Target version set to VX1_MCE_FSE_V2.0_20220930

#3 - 2022-10-10 20:19 - CD FW-王伟

- Status changed from New to 进行中 In Progress

- Target version changed from VX1_MCE_FSE_V2.0_20220930 to VX1_MCE_FSE_V3.0_20221030

#4 - 2022-10-20 14:26 - CD TPM-王祥林

功能已调通，能够恢复到掉电前的状态。如果掉电前在播放视频，则恢复到上一个界面即视频列表界面。

需要注意的点：

如果掉电前最后一个界面是屏保就不做记录，恢复的时候恢复到屏保的上一个应用。

#5 - 2022-10-20 14:30 - CD TPM-王祥林

- Assignee changed from CD- FW-石豪 to CD APP-王营

- % Done changed from 0 to 90

#6 - 2022-11-14 11:32 - CD APP-王营

- % Done changed from 90 to 100

#7 - 2022-11-14 11:33 - CD APP-王营

- Status changed from 进行中 In Progress to 完成 Closed

#8 - 2022-12-22 20:36 - CD FW-王伟

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
151334	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:ExceptionProtect:Add abnormal voltage protection serviceTC-RID: 1201-0206901IssueID: TS-R-DF-112095Change-Id: Idd4fb40897a54f80f0b618e278acea0f24a60dfd			

#9 - 2022-12-22 20:36 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
151337	general/platform/build/soong	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:Exception_Protect:allow uart sdk apiTC-RID: 1201-0206901IssueID: TS-R-DF-112095Change-Id: Idf591476966d0143b9ffc47d16a68bab98a4fd9b			

#10 - 2022-12-22 20:37 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
151587	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:Exception_Protect:add se permission for protectTC-RID: 1201-0206901IssueID: TS-R-DF-112095Change-Id: I7296a5fce8c803b5ca3031ea9e057ccc7d1d5425			

#11 - 2022-12-22 20:37 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
151769	general/platform/system/sepolicy	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:Exception_Protect:add se permission for protect serviceTC-RID: 1201-0206901IssueID: TS-R-DF-112095Change-Id: I4841afabe1ff1b60d174e9824a536728816fbfbf			

#12 - 2022-12-22 20:37 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152182	general/platform/system/sepolicy	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com

AF:Exception_Protect:No longer neededThis reverts commit b7074c534c5c53ff5c1f7f7c7cab0675e2f729cf.Reason for revert: <no need>TC-RID: 1201-0206901IssueID: TS-R-DF-112095Change-Id: lbf45d480cf48ec243a07e09793667042bedcb3de

#13 - 2022-12-22 20:38 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152220	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:ExceptionProtect:Add tc service managerTC-RID: 1201-0206901IssueID: TS-R-DF-112095Change-Id: l43fd6dce1d104147d20ef3f5b52228907898eab2			

#14 - 2022-12-22 20:38 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152226	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:Exception_Protect:add se permission for TcService and preinstallTC-RID: 1201-0206901IssueID: TS-R-DF-112095Change-Id: l8bc5b52311fbd22fddcd9aeabac9edfa2e435782			

#15 - 2022-12-22 20:38 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152230	general/platform/build/soong	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:Exception_Protect:allow tcservice manager apiTC-RID: 1201-0206901IssueID: TS-R-DF-112095Change-Id: l6a82583cd56306e791e1b39fba67beaf4c8f0b6b			

#16 - 2022-12-22 20:38 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152251	general/platform/vendor/thundercomm/apps/TCService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:ExceptionProtect:Add tc service codeTC-RID: 1201-0206901IssueID: TS-R-DF-112095Change-Id: laf30095e0edc4e0699158b14dfed10f4efd18f1b			

#17 - 2022-12-22 20:39 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152679	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12	shihao0506@thundersoft.com

		-dev	
AF:Exception_Protect:add se permission for launcher and music appTC-RID: 1201-0206901IssueID: TS-R-DF-112095Change-Id: I497139515eb883898a729f2795a406bd78736e4a			

#18 - 2022-12-22 20:39 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152701	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:ExceptionProtect:Add music whitelistTC-RID: 1201-0206901IssueID: TS-R-DF-112095Change-Id: I999d3e144e27c8eeef89938917d7fbc8c952bb87			

#19 - 2022-12-22 20:44 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155932	general/platform/vendor/thundercom/apps/TCService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:ExceptionProtect:Notify the mcu of the completion of bootTC-RID: 1201-0206901IssueID: TS-R-DF-112095Change-Id: Id1446e9d13a463134aff1403577e991f1a17a8bb			

#20 - 2022-12-22 20:44 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
156369	general/platform/vendor/thundercom/apps/TCService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:ExceptionProtect:Run shutdown after protect completedTC-RID: 1201-0206901IssueID: TS-R-DF-112095Change-Id: I3720686fd35814aa7ea0d46dd52003705920a0dd			