

Figure - Bug #112105

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【Settings】设置 - 显示菜单中缺少深色模式同步的开关

2022-09-22 18:18 - CD Test赵飞

Status:	CLOSED	Start date:	2022-09-22
Priority:	Normal	Due date:	2022-09-29
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_update_20221130	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20220921.alpha
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20220921.alpha
Severity:	Normal	Fixed Version:	2022-10-13
Reproducibility:	Every time	Root cause:	原生安卓无此功能,需要定制
Test Type:	IT		

Description
测试版本：FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20220921.alpha
【前提条件】 1、设备已开机 【测试步骤】 1、打开设置 - 显示 2、查看显示页面菜单 【预期结果】 2、显示页面有深色模式同步的开关，可打开和关闭 【实际结果】 2、显示页面没有深色模式同步的开关 【复现率】 5/5 【Note】 1、原生的“护眼模式”开关是“深色模式同步”开关为关闭的情况下显示的 2、控制中心中的快捷组件“深色主题”也需要修改为“深色模式同步”开关

History

#1 - 2022-09-22 18:18 - CD Test赵飞

- Due date set to 2022-09-29

#2 - 2022-09-26 18:33 - CD FW-王伟

- Target version set to VX1_MCE_FSE_V3.0_update_20221130

#3 - 2022-09-27 20:53 - CD FW-程天颖

- Status changed from New to ASSIGNED

- % Done changed from 0 to 10

- Root cause set to 原生安卓无此功能,需要定制

#4 - 2022-09-28 19:36 - CD FW-程天颖
- % Done changed from 10 to 20

制作了相关开关以及开关的显示逻辑

#5 - 2022-09-29 16:22 - CD FW-程天颖
- % Done changed from 20 to 60

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+152722>
<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+152725>

#6 - 2022-10-13 10:08 - CD FW-程天颖
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-程天颖 to CD Test赵飞
- % Done changed from 60 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Verified Version set to FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.202201013.alpha
- Fixed Version set to 2022-10-13

■ Current conclusion
已完成,代码已入库
■ My analysis
原生安卓无此功能,需要定制
■ Submit URL
<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+152722>
<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+152725>

#7 - 2022-10-18 16:53 - CD Test赵飞
- Status changed from RESOLVED to VERIFIED

验证版本：FlatBuild_VX1_MCE_xx.xx_FSE.R.userdebug.0.0.0.20221018.alpha_0037
验证结果：PASS

#8 - 2022-10-18 17:10 - CD Test赵飞
- Status changed from VERIFIED to CLOSED

#9 - 2022-12-22 20:39 - CD FW-王伟
Gerrit Merge Information：

ID	Project	Branch	Uploader
152722	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com

AF:Settings: Sync dark mode switch1.Add sync dark mode switchTC-RID: 1201-0201806IssueID: TS-R-BUG-112105Change-Id: lae1d0c4d0fc7d7b5f2ba364e709c6108fdcb3865

#10 - 2022-12-22 20:39 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152725	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:Settings:Sync dark mode switch value1.Sync dark mode switch valueTC-RID: 1201-0201806IssueID: TS-R-BUG-112105Change-Id: Ifaff4cac6eb35a10364bdadb9f739c336ed4383c			

Files				
screenshot1.jpg	88.8 KB	2022-09-22	CD Test	赵飞
screenshot2.jpg	120 KB	2022-09-22	CD Test	赵飞
PRD.png	51.1 KB	2022-09-22	CD Test	赵飞