

Figure - Bug #112111

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 110892 (New): AF-V1.0功能测试-WIFI

【AF】【EVT】【WIFI】输入密码后点击连接按钮，闪退回主页面

2022-09-23 11:01 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-09-23
Priority:	Urgent	Due date:	2022-09-23
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V1.0_update_20220925	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20220924
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20220924
Severity:	Critical	Fixed Version:	2022-09-24
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	IT		

Description
【前提条件】 1、设备已开机 【测试步骤】 1、打开WiFi 2、选择一个已知密码的热点进行连接 3、输入密码后，点击连接按钮 【预期结果】 3、成功连接热点 【实际结果】 3、点击连接按钮，闪退回主页面 【复现率】 必现

History

#1 - 2022-09-23 11:11 - CD AF-陈羽杰
- Status changed from New to ASSIGNED
- Assignee changed from CD FW-王伟 to CD AF-陈羽杰
#2 - 2022-09-23 11:15 - CD AF-陈羽杰
- Due date set to 2022-09-23
- % Done changed from 0 to 80
- Resolution changed from -- to FIXED
- Root cause set to 编码问题
#3 - 2022-09-23 11:18 - CD AF-陈羽杰
■ Current conclusion
已经分析定位到问题
■ My analysis
修改为双屏显示后，与原生逻辑冲突，导致settings页面被关闭

■ Next action

修改原生逻辑，使之不关闭页面

#4 - 2022-09-23 14:11 - CDTS_TEST 王成

- Priority changed from Normal to Urgent
- Severity changed from Normal to Critical

#5 - 2022-09-23 14:17 - CD AF-陈羽杰

■ Current conclusion

问题已通过代码解决

■ My analysis

修改为双屏显示后，与原生逻辑冲突，导致settings页面被关闭

■ Submit Url

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+151016>

#6 - 2022-09-23 14:17 - CD AF-陈羽杰

- Status changed from ASSIGNED to RESOLVED
- % Done changed from 80 to 100

#7 - 2022-09-23 14:18 - CD AF-陈羽杰

- Assignee changed from CD AF-陈羽杰 to CD TEST-方永红

■ Current conclusion

问题已通过代码解决

■ My analysis

修改为双屏显示后，与原生逻辑冲突，导致settings页面被关闭

■ Submit Url

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+151016>

#8 - 2022-09-23 14:18 - CD AF-陈羽杰

- Degrated changed from -- to No

#9 - 2022-09-23 15:06 - CD TPM-申艳艳

- Fixed Version set to 2022-09-24

#10 - 2022-09-23 15:10 - CDTS-TEST 周婷

- Target version set to VX1_MCE_FSE_V1.0_update_20220925

#11 - 2022-09-24 13:01 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

#12 - 2022-09-24 13:02 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED
- Verified Version set to FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20220924.alpha_0019

#13 - 2022-12-22 20:36 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader

151016	general/platform/packages/apps/Settings	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	yujie.chen@thundersoft.com
AF:Settings: Fix Wifi Page Crash Bug1.Fix Go back to the wifi page and launch directlyTC-RID: 1201-0201801IssueID: TS-R-DF-112111Change-Id: I3bb6b444ca53fbc834d7a205252d168abcc5c293			

Files

wifi-unconnect.txt	5.23 MB	2022-09-23	CD TEST-方永红
--------------------	---------	------------	-------------