

Figure - Bug #112115

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】打开“开发者选项”时，页面卡顿

2022-09-23 14:04 - CD Test赵飞

Status:	CLOSED	Start date:	2022-09-23
Priority:	Normal	Due date:	2022-09-30
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_20221030		
Need_Info:	--	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20220923
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20220923
Reproducibility:	Every time	Fixed Version:	2022-09-28
Test Type:	IT	Root cause:	编码问题

Description	
测试版本：FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20220923.alpha_0017	
【前提条件】	
1、设备已开机	
【测试步骤】	
1、打开设置 - 关于平板电脑	
2、连续点击“版本号”7次	
3、点击“系统” - “开发者选项”	
【预期结果】	
3、进入“开发者选项”页面，无卡顿现象	
【实际结果】	
3、进入“开发者选项”页面时，页面卡顿；进入后在“开发者选项”页面上下滑动时，也非常卡顿	
【复现率】	
5/5	
【日志】	
见附件	
【Note】	
1、进入设置中其他选项时，不会有卡顿	
2、测试使用的是user版本，在userdebug版本上也复现	

History
#1 - 2022-09-26 13:39 - CD FW-程天颖
- Assignee changed from CD FW-程天颖 to CD AF-陈羽杰
#2 - 2022-09-26 18:34 - CD FW-王伟
- Target version set to VX1_MCE_FSE_V3.0_update_20221130
#3 - 2022-09-27 15:29 - CDTS_TEST 王成

- Target version changed from VX1_MCE_FSE_V3.0_update_20221130 to VX1_MCE_FSE_V3.0_20221030

#4 - 2022-09-28 11:20 - CD AF-陈羽杰
- Status changed from New to ASSIGNED

#5 - 2022-09-28 11:21 - CD AF-陈羽杰
- % Done changed from 0 to 60
- Degrated changed from -- to No
- Root cause set to 编码问题

■ Current conclusion
已定位到问题
■ My analysis
由于修改双屏显示，父布局NestedScrollView嵌套RecyclerView，导致RecyclerView复用模式失效，从而创建大量viewholder使系统发生卡顿
■ Next action
本地修改，取消NestedScrollView验证。

#6 - 2022-09-28 15:44 - CD AF-陈羽杰
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD AF-陈羽杰 to CD Test赵飞
- % Done changed from 60 to 100
- Resolution changed from -- to FIXED
- Fixed Version set to 2022-09-28

■ Current conclusion
已修复
■ My analysis
由于修改双屏显示，父布局NestedScrollView嵌套RecyclerView，导致RecyclerView服用模式失效，从而创建大量viewholder使系统发生Anr导致崩溃。
■ submit url
<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+/152503>

#7 - 2022-10-10 11:09 - CD Test赵飞
- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20221010.alpha

验证版本：FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20221010.alpha
验证结果：PASS

#8 - 2022-10-10 11:09 - CD Test赵飞
- Status changed from VERIFIED to CLOSED

Files			
logcat-1.txt	920 KB	2022-09-23	CD Test赵飞
bugreport.txt	278 Bytes	2022-09-23	CD Test赵飞