

Figure - Bug #112134

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】声音- 勿扰模式-时间表-添加时间表，配置完成后点击添加按钮，会闪退回主界面

2022-09-26 13:57 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-09-26
Priority:	High	Due date:	2022-09-29
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V2.0_20220930	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20220924.alpha
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_VX1_MCE_xx.xx_FSE.R.userdebug.0.0.0.20220924.alpha
Severity:	Normal	Fixed Version:	2022-09-27
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	IT		
Description			
【前提条件】 设备已开机			
【测试步骤】 1、进入设置 声音 勿扰模式-时间表 2、选择“ 添加更多 ”并进行配置 3、点击添加按钮			
【预期结果】 2、添加成功			
【实际结果】 2、点击之后闪退回到主界面			
【复现率】 必现			

History

- #1 - 2022-09-26 14:07 - CD FW-程天颖
- Assignee changed from CD FW-程天颖 to CD AF-陈羽杰
- #2 - 2022-09-26 16:15 - CD TEST-方永红
- Found Version changed from FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20220924.alpha_0019 to FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20220924.alpha
- #3 - 2022-09-26 18:34 - CD FW-王伟
- Target version set to VX1_MCE_FSE_V2.0_20220930
- #4 - 2022-09-27 10:28 - CD TEST-方永红
- Priority changed from Normal to High
- #5 - 2022-09-27 17:54 - CD AF-陈羽杰
- Status changed from New to ASSIGNED
- % Done changed from 0 to 60
- Degrated changed from -- to No

- Verified Version set to 编码问题

■ Current conclusion

已定位到问题

■ My analysis

修改双屏显示时，由于忽略了原生Intent所带数据，导致目标页面报空指针异常。

■ Next action

本地修复验证

#6 - 2022-09-27 18:03 - CD AF-陈羽杰

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD AF-陈羽杰 to CD TEST-方永红
- % Done changed from 60 to 100
- Resolution changed from -- to FIXED
- Fixed Version set to 2022-09-27

■ Current conclusion

本地已经验证

■ My analysis

修改双屏显示时，由于忽略了原生Intent所带数据，导致目标页面报空指针异常。

■ submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+/152114>

#7 - 2022-09-28 14:44 - CD AF-陈羽杰

- Verified Version deleted (编码问题)
- Root cause set to 编码问题

#8 - 2022-09-28 14:45 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_VX1_MCE_xx.xx_FSE.R.userdebug.0.0.0.20220928.alpha_0022

#9 - 2022-09-28 14:45 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#10 - 2022-12-22 20:37 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152114	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	yujie.chen@thundersoft.com
AF:Settings: Fix Do Not Disturb Mode crash1.Fix Repair Do Not Disturb Mode Schedule Add Button crash2.Fix Do Not Disturb Mode Schedule Set Button crashTC-RID: 1201-0201805IssueID: TS-R-BUG-112134,TS-R-BUG-112130Change-Id: I99d34dedb7cf001eb793a66eec4b8e038ab1a907			

