

Figure - Bug #112160

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】系统-重置选项-恢复出厂设置，点击之后闪退回主页面，系统未恢复出厂设置

2022-09-27 11:27 - CD TEST-方永红

| | | | |
|------------------|---------------------------|-------------------|--|
| Status: | CLOSED | Start date: | 2022-09-29 |
| Priority: | High | Due date: | |
| Assignee: | CD TEST-方永红 | % Done: | 100% |
| Category: | CD-FW | Estimated time: | 0.00 hour |
| Target version: | VX1_MCE_FSE_V2.0_20220930 | Found Version: | FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20220927 |
| Need_Info: | -- | Degrated: | No |
| Resolution: | FIXED | Verified Version: | |
| Severity: | Critical | Fixed Version: | 2022-09-29 |
| Reproducibility: | Every time | Root cause: | Since the setting is divided into two levels of screen display, the system will flash back to the home page after clicking the reset option. |
| Test Type: | IT | | |

| |
|--|
| Description |
| <p>【前提条件】</p> <p>设备已开机,并且已经进行一些配置修改</p> <p>【测试步骤】</p> <p>1、进入设置 系统-重置选项</p> <p>2、点击恢复出厂设置</p> <p>【预期结果】</p> <p>2、系统恢复出厂设置</p> <p>【实际结果】</p> <p>2、点击之后闪退回主页面，系统未恢复出厂设置</p> <p>【复现率】</p> <p>必现</p> |

| |
|---|
| Subtasks: |
| Bug # 112288: 【AF】【EVT】【设置】（使用屏幕的情况下）系统-重置选项-恢复出厂设置，页面与屏幕不适配，无... <div>CLOSED</div> |

History

- #1 - 2022-09-27 11:33 - CD FW-程天颖
- Assignee changed from CD FW-程天颖 to CD AF-陈羽杰
- #2 - 2022-09-27 17:57 - CD AF-陈羽杰
- Assignee changed from CD AF-陈羽杰 to CD FW-程天颖
- #3 - 2022-09-27 19:59 - CDTS_TEST 王成
- Severity changed from Major to Critical
- #4 - 2022-09-28 15:22 - CD FW-程天颖
- Status changed from New to RESOLVED
- Assignee changed from CD FW-程天颖 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No

- Fixed Version set to 2022-09-29

- Root cause set to Since the setting is divided into two levels of screen display the sub-screen activity definition is not used, and the theme definition will not be adopted.

So we dynamically loaded the theme

Current conclusion

bug is fixed

My analysis

Since the setting is divided into two levels of screen display the sub-screen activity definition is not used, and the theme definition will not be adopted.

So we dynamically loaded the theme

Next action / Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+/152526>

#5 - 2022-09-29 20:22 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

#6 - 2022-09-29 20:22 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#7 - 2022-12-22 20:37 - CD FW-王伟

| | | | |
|---|--|---|-----------------------------|
| Gerrit Merge Information : | | | |
| ID | Project | Branch | Uploader |
| 152020 | general/platform/packages/apps/Settins | Pre_figure_turbox-c2130c-la1.1-qssi12-dev | wangwei0629@thundersoft.com |
| FW:Settings: Fix bug for reset app dataFix bug for reset app dataTC-RID: 1201-0201809IssueID: TS-R-BUG-112160Change-Id: Iaf65003bf4bd435905fd8308deaaddc8f4737745 | | | |

#8 - 2022-12-22 20:38 - CD FW-王伟

| | | | |
|---|--|---|---------------------------|
| Gerrit Merge Information : | | | |
| ID | Project | Branch | Uploader |
| 152526 | general/platform/packages/apps/Settins | Pre_figure_turbox-c2130c-la1.1-qssi12-dev | caoqg0702@thundersoft.com |
| AF:Settings: Fix the problem of factory reset screen crashSince the setting is divided into two levels of screen displaythe sub-screen activity definition is not used, and the theme definition will not be adopted.So we dynamically loaded the themeTC-RID: 1201-0201809IssueID: TS-R-BUG-112160Change-Id: I3ef707afa35b5d6f35d9a3c81f35b99528669e7f | | | |

| | | | |
|---------------|---------|------------|-------------|
| Files | | | |
| sys crash.log | 8.25 KB | 2022-09-27 | CD TEST-方永红 |