

Figure - 需求 Requirement #112164

【测试指令自启动需求】合入客户测试指令并且能够开机自启动

2022-09-27 14:07 - CD BSP-杜磊

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |                                  |                 |            |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|-----------------|------------|
| Status:                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      | 完成 Closed                        | Start date:     | 2022-09-27 |
| Priority:                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | Normal                           | Due date:       |            |
| Assignee:                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | CD BSP-杜磊                        | % Done:         | 100%       |
| Category:                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    | SYSTEM                           | Estimated time: | 0.00 hour  |
| Target version:                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              | VX1_MCE_FSE_V2.0_update_20221012 |                 |            |
| Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |                                  |                 |            |
| <p>附件是VX1 MCE FSE-M的UT 请查收 麻烦将UT设置成自启动 并且启动时添加参数 192.168.8.16 并且我们目前发现FSE-M的mac地址错误未按照vlan规范中要求的mac地址设置 并且phy应该是100M slave而不是千兆 麻烦一并修复后给出软硬件测试</p> <p>解决selinux权限问题</p> <p>■ 需求列表</p> <p><a href="https://thundersoft.feishu.cn/sheets/shtcnqaFykINsnMcKWLuICl3xnc?sheet=0PCdJS">https://thundersoft.feishu.cn/sheets/shtcnqaFykINsnMcKWLuICl3xnc?sheet=0PCdJS</a></p> <p>验证方法：</p> <p>adb shell ifconfig</p> <p>vlan8   Link encap:Ethernet  HWaddr a6:17:a1:5a:1f:e6</p> <p>        inet addr:*192.168.8.16*  Bcast:192.168.8.255  Mask:255.255.255.0</p> <p>        UP BROADCAST MULTICAST  MTU:1500  Metric:1</p> <p>        RX packets:0 errors:0 dropped:0 overruns:0 frame:0</p> <p>        TX packets:0 errors:0 dropped:0 overruns:0 carrier:0</p> <p>        collisions:0 txqueuelen:1000</p> <p>        RX bytes:0 TX bytes:0</p> |                                  |                 |            |

History

- #1 - 2022-09-29 09:49 - CD BSP-杜磊
- File ept\_upptester\_v2.0\_fse added
- #2 - 2022-09-29 09:50 - CD BSP-杜磊
- Target version changed from VX1\_MCE\_FSE\_V2.0\_20220930 to VX1\_MCE\_FSE\_V2.0\_update\_20221012
- #3 - 2022-09-29 10:07 - CD BSP-杜磊
- Description updated
- #4 - 2022-09-29 17:40 - CD BSP-杜磊
- Assignee changed from CD BSP-杜磊 to CD\_BSP 彭文亮
- #5 - 2022-10-08 17:57 - CD BSP-杜磊
- Description updated
- #6 - 2022-10-08 18:09 - CD BSP-杜磊
- Description updated
- #7 - 2022-10-17 11:42 - CD BSP-杜磊
- Status changed from New to 分析&分解中 In Analysis
- Assignee changed from CD\_BSP 彭文亮 to CD BSP-杜磊
- % Done changed from 0 to 100

#8 - 2022-10-17 11:43 - CD BSP-杜磊

- Status changed from 分析&分解中 In Analysis to 完成 Closed

#9 - 2022-12-22 20:40 - CD FW-王伟

Gerrit Merge Information :

| ID                                                                                                                                                                          | Project                                       | Branch                                        | Uploader                  |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------|-----------------------------------------------|---------------------------|
| 153924                                                                                                                                                                      | general/vendor/thundercomm/produ<br>ts/figure | Pre_figure_turbox-c2130c-la1.1-vendo<br>r-dev | dulei0503@thundersoft.com |
| <div>BSP:Ethernet: Set vlan8 ip addressAdd ept_upptester_v2.0_fse toolTC-RID: 1201-0400601IssueID: TS-R-DF-112164Change-Id: led4645c7efa59496941c28055940582deaa20d09</div> |                                               |                                               |                           |

#10 - 2022-12-22 20:43 - CD FW-王伟

Gerrit Merge Information :

| ID                                                                                                                                                                                                                                              | Project                                       | Branch                                        | Uploader                  |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------|-----------------------------------------------|---------------------------|
| 155318                                                                                                                                                                                                                                          | general/vendor/thundercomm/produ<br>ts/figure | Pre_figure_turbox-c2130c-la1.1-vendo<br>r-ftm | dulei0503@thundersoft.com |
| <div>BSP:Ethernet: Set vlan8 ip addressAdd ept_upptester_v2.0_fse toolTC-RID: 1201-0400601IssueID: TS-R-DF-112164Change-Id: led4645c7efa59496941c28055940582deaa20d09(cherry picked from commit 5636c0df8f452e0e7c688a4e009fa2ee88aa8f60)</div> |                                               |                                               |                           |

#11 - 2022-12-22 20:44 - CD FW-王伟

Gerrit Merge Information :

| ID                                                                                                                                                                                         | Project                                              | Branch                                        | Uploader                  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------|-----------------------------------------------|---------------------------|
| 156453                                                                                                                                                                                     | general/vendor/thundercomm/produ<br>ts/sepolicy_vndr | Pre_figure_turbox-c2130c-la1.1-vendo<br>r-dev | dulei0503@thundersoft.com |
| <div>BSP:Ethernet: Add service to start upper_testAdd selinux sepolity for upper_testTC-RID: 1201-0400601IssueID: TS-R-DF-112164Change-Id: I70957670e2f2e87c6c194fa849ab0ae8d3bc0ac3</div> |                                                      |                                               |                           |

#12 - 2022-12-22 20:45 - CD FW-王伟

Gerrit Merge Information :

| ID                                                                                                                                           | Project                                       | Branch                                        | Uploader                  |
|----------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------|-----------------------------------------------|---------------------------|
| 156454                                                                                                                                       | general/vendor/thundercomm/produ<br>ts/figure | Pre_figure_turbox-c2130c-la1.1-vendo<br>r-dev | dulei0503@thundersoft.com |
| <div>BSP:Ethernet: Add service to start upper_testSet vlan8 ip address as serviceTC-RID: 1201-0400601IssueID: TS-R-DF-112164Change-Id:</div> |                                               |                                               |                           |

#13 - 2022-12-22 20:45 - CD FW-王伟

Gerrit Merge Information :

| ID                                                                                                                                                                                            | Project                                              | Branch                                        | Uploader                  |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------|-----------------------------------------------|---------------------------|
| 157144                                                                                                                                                                                        | general/vendor/thundercomm/produ<br>ts/sepolicy_vndr | Pre_figure_turbox-c2130c-la1.1-vendo<br>r-dev | dulei0503@thundersoft.com |
| <div>BSP:Ethernet: Fix upper_test selinux build errorAdd selinux sepolicy for upper_testTC-RID: 1201-0400601IssueID: TS-R-DF-112164Change-Id: I2c3471998a6841485555bde51a19e66c85e0e7b5</div> |                                                      |                                               |                           |

#14 - 2022-12-22 20:47 - CD FW-王伟

Gerrit Merge Information :

| ID                                                                                                                                                                                                                                   | Project                                       | Branch                                        | Uploader                  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------|-----------------------------------------------|---------------------------|
| 158616                                                                                                                                                                                                                               | general/vendor/thundercomm/produ<br>ts/figure | Pre_figure_turbox-c2130c-la1.1-vendo<br>r-dev | dulei0503@thundersoft.com |
| <div>BSP:Ethernet: Disable upper_test at startupEnable: setprop persist.sys.ut.active 1Disable: setprop persist.sys.ut.active 0TC-RID: 1201-0400601IssueID: TS-R-DF-112164Change-Id: I08df782d9aaa8c0a90f6190a200f7fe739efd5d9</div> |                                               |                                               |                           |

Files

|                          |        |            |           |
|--------------------------|--------|------------|-----------|
| ept_uppertester_v2.0_fse | 222 KB | 2022-09-29 | CD BSP-杜磊 |
|--------------------------|--------|------------|-----------|