

Figure - Bug #112175

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111047 (New): AF-V2.0-小窗模式

【AF】【EVT】【小窗模式】应用以小窗模式打开后，双击小窗窗口，无法全屏

2022-09-27 18:37 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-09-27
Priority:	High	Due date:	2022-09-29
Assignee:	CD TEST-方永红	% Done:	100%
Category:	窗口定制	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V2.0_update_20221012	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20220927
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	
Severity:	Major	Fixed Version:	2022-10-10
Reproducibility:	Every time	Root cause:	小窗状态下，小窗的内容区没有对双击操作进行判断
Test Type:	IT		

Description	
【前提条件】 1、设备已开机 2、后台未运行任何应用	
【测试步骤】 1、长按桌面上任意一个支持小窗的应用（如“图库”） 2、在弹出的菜单中点击“小窗” 3、双击小窗窗口	
【预期结果】 3、应用由小窗模式变为全屏	
【实际结果】 3、应用小窗没有全屏	
【复现率】 5/5	
【Log】 截图见附件	

History

- #1 - 2022-09-28 14:55 - DL FW-王琳
- Status changed from New to ASSIGNED
- #2 - 2022-09-28 14:56 - DL FW-王琳
- Assignee changed from DL FW-王琳 to DL FW-张挽强
- #3 - 2022-09-29 18:20 - DL FW-王琳
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from DL FW-张挽强 to CD TEST-方永红

■ Current state

问题已解决

■ My Analyze
小窗增加双击功能的逻辑处理

提交：<http://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+152891>

请验证。

#4 - 2022-09-30 11:47 - DL FW-张挽强
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Fixed Version set to 2022-09-30
- Root cause set to 小窗状态下，小窗的内容区没有对双击操作进行判断和处理。

#5 - 2022-09-30 20:16 - CDTS_TEST 王成
- Target version changed from VX1_MCE_FSE_V2.0_20220930 to VX1_MCE_FSE_V2.0_update_20221012

概率性可打开，需要优化

#6 - 2022-10-08 17:43 - CD TEST-方永红
- File 小窗双击全屏问题.log added

#7 - 2022-10-09 10:37 - CD TEST-方永红
- Status changed from RESOLVED to VERIFY_FAILED
- Assignee changed from CD TEST-方永红 to DL FW-张挽强

#8 - 2022-10-09 10:53 - DL FW-张挽强

屏幕上验证通过，测试这边投屏验证有问题，增加log以便定位问题

#9 - 2022-10-09 11:06 - DL FW-张挽强
- Assignee changed from DL FW-张挽强 to CD TEST-方永红
- Fixed Version changed from 2022-09-30 to 2022-10-10

log 已经增加好了 可以用明天最新的db验证问题了

#10 - 2022-10-10 13:56 - CD TEST-方永红
- Status changed from VERIFY_FAILED to VERIFIED

#11 - 2022-10-10 13:56 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

#12 - 2022-12-22 20:39 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152707	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12	zhangwq0711@thundersoft.com

		-dev	
AF:MultiWindow:fixed double-click the freeform cannot be full screen1.fixed doubleclick the freeform cannot be full screenTC-RID: 1201-0204601IssueID: TS-R-BUG-112175Change-Id: I73e22026edc9ebc4944de34622eb27b9582d8507			

#13 - 2022-12-22 20:40 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
153423	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	zhangwq0711@thundersoft.com
AF:MultiWindow:Optimize double click sensitivity1.Optimize double click sensitivity about freeform windowChange-Id: I2c3c22eeabd15a6a211a00c7d08d32cbf6e291ceTC-RID: 1201-0204601IssueID: TS-R-BUG-112175			

#14 - 2022-12-22 20:40 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154053	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	zhangwq0711@thundersoft.com
AF:MultiWindow:Optimize double click sensitivity1.Add log location problemChange-Id: I531b3774282505a923de847a9af988733f81e8f2TC-RID: 1201-0204601IssueID: TS-R-BUG-112175			

Files			
小窗双击全屏问题.log	11.2 KB	2022-10-08	CD TEST-方永红