

Figure - 开发 Dev #112192

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 110125 (New): 【MK】【BSP】管理总票

开发 Dev # 112089 (New): 【MK】【012】【TSNV】主任务

【MK】【012】【TSNV】工厂测试 flags & SN 支持

2022-09-28 14:32 - CD BSP-丁武伟

Status:	完成 Closed	Start date:	2022-12-17
Priority:	Normal	Due date:	
Assignee:	CD BSP-丁武伟	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V2.0_20220930		
Description			
添加工厂测试flags支持			
Subtasks:			
开发 Dev # 114670: 【MK】【012】【TSNV】SN 42位支持			完成 Closed

History

#1 - 2022-10-08 11:07 - CD BSP-丁武伟

- Subject changed from 【MK】【012】【TSNV】工厂测试flags支持 to 【MK】【012】【TSNV】工厂测试 flags & SN 支持

- Status changed from 进行中 In Progress to 解决 Resolved

- % Done changed from 50 to 100

#2 - 2022-10-25 10:35 - CD BSP-丁武伟

Update: 2022/10/25

更新nvftm：写入新值时，完全覆盖之前的数据。

验证情况如下：

255|figure:/ # /data/nvftm sn read IOB
TC0003456789
figure:/ # /data/nvftm sn write IOB TC123
figure:/ # /data/nvftm sn read IOB
TC123
figure:/ # /data/nvftm sn write IOB TC123456789
figure:/ # /data/nvftm sn read IOB
TC123456789
figure:/ # /data/nvftm sn write IOB TC12
figure:/ # /data/nvftm sn read IOB
TC12

BRs/丁武伟

#3 - 2022-10-31 20:17 - CD BSP-唐金泽

- Due date set to 2022-10-14

- Status changed from 解决 Resolved to 完成 Closed

#4 - 2022-12-09 14:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
167963	general/vendor/thundercomm/tsnv	Pre_figure_turbox-c2130c-la1.1-vendor-ftm-dvt1	tangjz1204@thundersoft.com
BSP:TSNV: Change tsnv.ko for FTM-DVT1 branchexchange tsnv.ko for FTM-DVT1 branchTC-RID: 1200-0102003IssueID: TS-R-DF-112192Change-Id: Ie8af72157f14b96642f674ba2f8e94c95abee90a			

#5 - 2022-12-22 20:37 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
151912	general/vendor/thundercomm/tsnv	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:TSNV: add nvftmadd nvftm for factoryTC-RID: 1200-0102003IssueID: TS-R-DF-112192Change-Id: I4d374cd813d3819e0ddb93913373c9a1ac6f20ff			

#6 - 2022-12-22 20:37 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
152022	general/vendor/thundercomm/products/common	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:TSNV: add nvftmadd nvftm for factory flagsTC-RID: 1200-0102003IssueID: TS-R-DF-112192Change-Id: Ida8df99b4b51888d0f3b7e2d43e99344e638b06f			

#7 - 2022-12-22 20:40 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
153751	general/vendor/thundercomm/tsnv	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:TSNV: add sn support for PCBA ASSY IOBupdate nvftm and kernel driverTC-RID: 1200-0102003IssueID: TS-R-DF-112192Change-Id: I0e920be0c4ae825c18680ad77e5065a19ab813b0			

#8 - 2022-12-22 20:43 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155319	general/vendor/thundercomm/tsnv	Pre_figure_turbox-c2130c-la1.1-vendor-ftm	dulei0503@thundersoft.com
BSP:TSNV: add sn support for PCBA ASSY IOBupdate nvftm and kernel driverTC-RID: 1200-0102003IssueID: TS-R-DF-112192Change-Id: I0e920be0c4ae825c18680ad77e5065a19ab813b0(cherry picked from commit 15ea7d670a57e6bb2e90c1ce7dd0f49bf452e1be)			

#9 - 2022-12-22 20:46 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
157684	general/vendor/thundercomm/tsnv	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dingww0707@thundersoft.com
BSP:TSNV: nvftm updateupdate the whole data when wrting a new valTC-RID: 1200-0102003IssueID: TS-R-DF-112192Change-Id: I0cb626580fe99751197239ff42ce9f0e32435711			

#10 - 2022-12-22 20:54 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
164938	general/vendor/thundercomm/tsnv	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangwei0629@thundersoft.com
BSP:TSNV: update comment for id#25set id 25 as DUT ActivitationTC-RID: 1200-0102003IssueID: TS-R-DF-112192Change-Id: I20da443a4ae91a0eeb6d6a294e4e6ef8cfb14a			

#11 - 2023-03-30 19:56 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
191084	general/vendor/thundercomm/tsnv	Pre_figure_turbox-c2130c-la1.1-vendor-ftm_v0081	dulei0503@thundersoft.com
BSP:TSNV: Change tsnv.ko for FTM-DVT1 branchexchange tsnv.ko for FTM-DVT1 branchTC-RID: 1200-0102003IssueID: TS-R-DF-112192Change-Id: Ie8af72157f14b96642f674ba2f8e94c95abee90a(cherry picked from commit 235b65c0ab94661f104f0c5c4b905c594c3d42c0)			

Gerrit Merge Information :

BSP:TSNV: Change tsnv.ko for FTM-DVT2 branchexchange tsnv.ko for FTM-DVT1 branchTC-RID: 1200-0102003IssueID: TS-R-DF-112192Change-Id: Ie8af72157f14b96642f674ba2f8e94c95abee90a(cherry picked from commit 235b65c0ab94661f104f0c5c4b905c594c3d42c0)(cherry picked from commit f673ab068491306a3ec7060547b4cdca8f06b4e0)

Gerrit Merge Information :

BSP:SYSTEM: Restore metadata/userdata/persist partition to FTMRevert BSP:SYSTEM: Keep metadata/userdata/persist the sameThis reverts commit e089815d0afe57f915d33e31bfc9cf56efea82f.TC-RID: 0301-0100805IssueID: TS-R-DF-112192Change-Id: I8661a06e967b50098ac445c27d6ae9a79d74e53

Gerrit Merge Information :

BSP:TSNV: Change tsnv.ko for FTM-DVT2 branchexchange tsnv.ko for FTM-DVT1 branchTC-RID: 1200-0102003IssueID: TS-R-DF-112192Change-Id: le8af72157f14b96642f674ba2f8e94c95abee90a(cherry picked from commit 235b65c0ab94661f104f0c5c4b905c594c3d42c0)(cherry picked from commit f673ab068491306a3ec7060547b4cdca8f06b4e0)(cherry picked from commit 1522cd93818a9d0b8bea5d71be14217eb39b1f4e)

Gerrit Merge Information :

197299	general/common	Pre_figure_turbox-c2130c-la1.1-vendor-ftm v0095	dulei0503@thundersoft.com
--------	----------------	---	---------------------------

BSP:SYSTEM: Restore metadata/userdata/persist partion to FTMRevert BSP:SYSTEM: Keep metadata/userdata/persist the sameThis reverts commit
e089815d0afe57f915d33e31bfcec9f56efea82f.TC-RID: 0301-0100805IssueID: TS-R-DF-112192Change-Id: I8661a06e96e7b50098ac445c27d6ae9a79d74e53(cherry
picked from commit 26e504582d54470456f456f5970257d802378635)