

Figure - 需求 Requirement #112217

需求 Requirement # 110107 (New): 【Locked需求】总票

需求 Requirement # 110997 (分析&分解中 In Analysis): 【Locked需求】Launcher UI需求

需求 Requirement # 112194 (取消 Canceled): 【Locked需求】Launcher UI需求-以太网和wifi共存

【Locked需求】Launcher UI需求-以太网和wifi共存

2022-09-28 23:03 - CD LC 陶洪普

Status:	New	Start date:	2022-09-28
Priority:	Normal	Due date:	2022-09-30
Assignee:	ETH 黄鹏飞	% Done:	0%
Category:	ETH	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V2.0_20220930		
Description			
在 https://share.thundersoft.com/redmine/issues/112194 中确认如下需求:			
1. 通过配置脚本文件, 将MCE中的FSE屏幕相关的以太网配置参入写入, 并且用户侧不可更改			
这部分是有Ethernet设置vlan脚本实现的,请帮确认是否与需求符合?			
需求在 https://thundersoft.feishu.cn/docs/doccn80x4252yfuTtqFzwkSgrcf# 中, 为避免更新,在这里不贴出具体要求,请查看链接文档.			
2. 以太网与Wifi共存规则 :			
a. 支持以太网和WiFi同时连接, 在屏幕侧需要展示两种连接状态			
这个在父票中确认具体需求			
b. VLAN 配置的地址都走以太网			
这个理解由具体的应用来指定使用, 不需要做其他配置. 请确认该理解是否正确?			
c. 其余的地址都走WiFi			
同上. 默认网关是WiFi			

History			
#1 - 2022-10-28 00:16 - CD LC 陶洪普			
https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/ethernet/+/153277			
Add vlan route 已Merged.			
#2 - 2022-12-22 20:40 - CD FW-王伟			
Gerrit Merge Information :			
ID	Project	Branch	Uploader
153277	general/platform/vendor/thundercomm/ethernet	Pre_figure_turbox-c2130c-la1.1-vendor-dev	huangpf1028@thundersoft.com

LC:Ethernet: Add vlan routeAdd vlan routeTC-RID: 1201-0400601IssueID: TS-R-DF-112217Change-Id: I5509463c818520f9627712c8c9bd8bec5e322c01

#3 - 2023-05-11 13:05 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
195457	general/platform/vendor/thundercomm/ethernet	Pre_figure_turbox-c2130c-la1.1-vendor-dev	huangpf1028@thundersoft.com
LC:Ethernet: Add the switch gateway routing featureAdd the switch gateway routing featureTC-RID: 1201-0400601IssueID: TS-R-DF-112217Change-Id: I00662ae3b65759b7e750be98b37111229a095c47			

#4 - 2023-05-11 13:05 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
196741	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpf1028@thundersoft.com
LC:Ethernet: Add ethernet configAdd ethernet configTC-RID: 1201-0400601IssueID: TS-R-DF-112217Change-Id: Id600846e5f5806f4abb75869c418a681fc0f7022			

#5 - 2023-05-15 00:42 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
199840	general/platform/vendor/thundercomm/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpf1028@thundersoft.com
LC:Ethernet: Add DNS configuration informationAdd DNS configuration informationTC-RID: 1201-0400601IssueID: TS-R-DF-112217Change-Id: If5c0ff226d570569b1575ac6d3f5e559e2212205			

#6 - 2023-05-15 00:42 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
199805	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpf1028@thundersoft.com

LC:Ethernet: Add DNS dynamic switching permissionsAdd DNS dynamic switching permissionsTC-RID: 1201-0400601IssueID: TS-R-DF-112217Change-Id: I3de3db1acaf46056fe6bb91c2336dedb08678afc

#7 - 2023-05-15 00:42 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
199820	general/platform/vendor/thundercomm/ethernet	Pre_figure_turbox-c2130c-la1.1-vendor-dev	huangpf1028@thundersoft.com
LC:Ethernet: Related actions are ported to QSSIRelated actions are ported to QSSITC-RID: 1201-0400601IssueID: TS-R-DF-112217Change-Id: I63689a446394ef9a1702a0af1934f96a6b5c3568			

#8 - 2023-05-29 20:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
200621	general/platform/vendor/thundercomm/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpf1028@thundersoft.com
LC:Ethernet: Updating multiple rules for DNS fails to remove the issueUpdating multiple rules for DNS fails to remove the issueTC-RID: 1201-0400601IssueID: TS-R-DF-112217Change-Id: I7f4702ade90324bd4c2b19b0dbf0c653d879954f			

#9 - 2023-05-29 20:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
200620	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpf1028@thundersoft.com
LC:Ethernet: Update DNS permission issuesUpdate DNS permission issuesTC-RID: 1201-0400601IssueID: TS-R-DF-112217Change-Id: If309401346c060e7a54ae96c7855b36185f62c05			

#10 - 2023-05-31 22:09 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
203757	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpf1028@thundersoft.com
LC:Ethernet: Fix the DNS service IP address to 218.4.4.4Fix the DNS service IP address to 218.4.4.4TC-RID: 1201-0400601IssueID: TS-R-DF-112217Change-Id:			

#11 - 2023-05-31 22:09 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
203758	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpf1028@thundersoft.com
LC:Ethernet: Remove the DNS toggle featureRemove the DNS toggle featureTC-RID: 1201-0400601IssueID: TS-R-DF-112217Change-Id: I420ae7b23c87f91e121f038d3efad436d997e33d			

#12 - 2023-06-02 02:17 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
204178	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangxl0510@thundersoft.com
LC:Ethernet: Change the DNS service IP address to 101.226.4.6Change the DNS service IP address to 101.226.4.6TC-RID: 1201-0400601IssueID: TS-R-DF-112217Change-Id: I012beea683d2a902b72abbb60b62fa1c79bb9b04			

#13 - 2023-06-09 15:20 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
205909	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
LC:Ethernet: Change net switchTC-RID: 1201-0400601IssueID: TS-R-DF-112217Change-Id: Iacff11c7bb4b3ff0ebd0c61df321a954f9289cc5			

#14 - 2023-06-09 15:21 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
205831	general/platform/vendor/thundercom/apps/VehicleControl	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpf1028@thundersoft.com
LC:Ethernet: Delete the sys.network.tbox attribute valueThe fix for switching the network is to use an attribute valueTC-RID: 1201-0400601IssueID: TS-R-DF-112217Change-Id: I4a7cae08080d646b1d217acdad2b58b196fdff			

Gerrit Merge Information :

ID	Project	Branch	Uploader
212969	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
LC:Ethernet: Change the DNS service IP address to 218.2.2.2/218.4.4.4Change the DNS service IP address to 218.2.2.2/218.4.4.4TC-RID: 1201-0400601IssueID: TS-R-DF-112217Change-Id: I7af4cf74c555f2f9bd01822d98ad6480e0c87767			

Gerrit Merge Information :

ID	Project	Branch	Uploader
212979	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
Revert LC:Ethernet: Change the DNS service IP address to 218.2.2.2/218.4.4.4This reverts commit 68d3220972b6521220f7607b17934207a1ece386.Reason for revert: <use old dns>TC-RID: 1201-0400601IssueID: TS-R-DF-112217Change-Id: If991a6bd74202dd4c80ef6d9eaa0a92743fe6f74			