

Figure - Bug #112224

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】在setting界面，点任意功能，会随机闪退;点版本号必现闪退.显示安卓开机LOGO

2022-09-29 11:08 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-09-29
Priority:	Immediate	Due date:	2022-09-29
Assignee:	CD TEST-方永红	% Done:	100%
Category:	窗口定制	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V2.0_20220930	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20220929
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	
Severity:	Critical	Fixed Version:	2022-09-30
Reproducibility:	Every time	Root cause:	Setting应用重写了onTouch方法，小窗在onTouch方
Test Type:	IT		

Description	
【前提条件】 设备已开机	
【测试步骤】 1、打开设置，点版本号 2、随意点击其他配置项	
【预期结果】 1、成功进入开发者模式 2、成功切换页面，可正常进行配置	
【实际结果】 1、点版本号必现闪退.显示安卓开机LOGO 2、点任意功能，会随机闪退，显示安卓开机LOGO	
【复现率】 必现	

History

- #1 - 2022-09-29 11:23 - DL FW-王琳
- Status changed from New to ASSIGNED
- Assignee changed from DL FW-王琳 to DL FW-张挽强
- #2 - 2022-09-29 18:22 - DL FW-王琳
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from DL FW-张挽强 to CD TEST-方永红

■ Current state

问题已解决

■ My Analyze

小窗增加双击功能的逻辑处理

提交：<http://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+152891>

请验证。

#3 - 2022-09-30 11:35 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
- % Done changed from 0 to 100

#4 - 2022-09-30 11:35 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

#5 - 2022-09-30 11:45 - DL FW-张挽强
- Resolution changed from -- to FIXED
- Fixed Version set to 2022-09-30
- Root cause set to Setting应用重写了onTouch方法，小窗在onTouch方法中增加了双击逻辑中对顶部的View没有进行为空检查，导致了空指针异常的出现。

Files			
111.txt	4.57 MB	2022-09-29	CD TEST-方永红
222.txt	14.8 MB	2022-09-29	CD TEST-方永红