

Figure - Bug #112293

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111049 (New): AF-V2.0-副屏遥控器

【AF】【EVT】【副屏遥控器】无法使用遥控器进行音量调节

2022-09-29 19:54 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-09-29
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V2.0_update_20221012	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20220929
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	
Severity:	Major	Fixed Version:	
Reproducibility:	Every time	Root cause:	之前的修改把AudioManager的IVolumeController回调
Test Type:	IT		
Description			
【前提条件】 设备已开机			
【测试步骤】 1、 DUT与手机连接在同一第三方网络下 2、 启动遥控器 3、 在遥控app上点击音量加减			
【预期结果】 1、 成功进行音量加减且屏幕上有相应展示			
【实际结果】 1、 无法进行音量加减			
【复现率】 必现			

History

- #1 - 2022-09-29 20:35 - CD FW-王伟
- Assignee changed from CD FW-王伟 to CD FW-廖涛
- #2 - 2022-09-30 14:22 - CD FW-廖涛
- Assignee changed from CD FW-廖涛 to CD FW-鲁凯峰
- #3 - 2022-09-30 17:02 - CD TPM-王祥林
- Target version changed from VX1_MCE_FSE_V2.0_20220930 to VX1_MCE_FSE_V2.0_update_20221012
- #4 - 2022-09-30 20:34 - CD FW-鲁凯峰
- Status changed from New to RESOLVED
- Assignee changed from CD FW-鲁凯峰 to CD TEST-方永红
- Resolution changed from -- to FIXED
- Root cause set to 之前的修改把AudioManager的IVolumeController回调给了VolumeController,但是在VolumeController没有show volume ui的操作,所以没有显示侧边音量条

■ Current state

问题已经解决

■ My Analyze

之前的修改把AudioManager的IVolumeController回调给了VolumeController,但是在VolumeController没有show volume ui的操作,所以没有显示侧边音量条

重新修改后,添加VolumeDialogController的Callbacks,统一由VolumeDialogControllerImpl收到AudioManager回调后,交给Callbacks处理

■ Next Step

<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+/153268/>

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+/153440>

请在下个版本进行测试验证

#5 - 2022-10-09 10:06 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

- % Done changed from 0 to 100

#6 - 2022-10-09 10:07 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#7 - 2022-12-22 20:40 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
153268	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com
AF:QuickSettings: update qs volumeadd callback to update volumeTC-RID: 1201-0201903IssueID: TS-R-BUG-112293Change-Id: I29a28a95ae4ed4c98334eb22e79d0cff8a62810a			

#8 - 2022-12-22 20:40 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
153440	general/platform/packages/apps/Settings	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	yujie.chen@thundersoft.com
AF:Settings: Fix OnKeyDown Lose1.Fix OnKeyDown LoseTC-RID: 1201-0201813IssueID: TS-R-BUG-112293Change-Id: Ib2d0897dc20737fda1e6feb2ade68dc667a2f40d			

Files

音量加减	7.26 MB	2022-09-29	CD TEST-方永红
------	---------	------------	-------------