

Figure - 开发 Dev #112378

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 110126 (New): 【MK】【AF】管理总票

【MK】【MCU-OTA】【TC-RID: 1201-0200401】

2022-10-08 15:55 - CD FW-王伟

Status:	完成 Closed	Start date:	2022-10-08
Priority:	Normal	Due date:	2022-10-12
Assignee:	CD- FW-石豪	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_B sample_20221016		
Description			
BSP需要将mcu的固件包放在目录： /vender/tc/mcu/xxxxx_version_xxxx.zip			
压缩包的名字里面会包含版本信息			
FW需要在开机的时候检查此文件夹下面的文件，并且解析出版本号，然后与MCU的版本相对比，如果有差异则升级。			

History

#1 - 2022-11-10 15:48 - CD- FW-石豪

- Status changed from New to 完成 Closed

- % Done changed from 0 to 100

【相关提交】<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/TCService/+158369>

【测试方式】放置figureAPP_V0.0.1_a.bin figureAPP_V0.0.1_b.bin到/system/tc/mcu/下，若当前版本不是V0.0.1,重启之后将会触发升级。升级情况可以通过adb logcat | grep -i MCUUpdate进行查看日志

#2 - 2022-12-22 20:41 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154212	general/platform/vendor/thundercomm/apps/TCService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
AF:MCU-OTA:Add Mcu upgrade in TcService codeTC-RID: 1201-0200401IssueID: TS-R-DF-112378Change-Id: I839a87aece1b871a8782495063cf648499c8604b			

#3 - 2022-12-22 20:41 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154345	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
FW:MCU-OTA:Add the pre installed directory of mcu versionTC-RID: 1201-0200401IssueID: TS-R-DF-112378Change-Id:			

#4 - 2022-12-22 20:43 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155634	general/platform/vendor/thundercom/apps/TCService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
FW:MCU-OTA:Fix Mcu upgrade version compile1.modif mcu version compile logic2.system reboot after the mcu auto upgrade completedTC-RID: 1201-0200401IssueID: TS-R-DF-112378Change-Id: Ib3a119fa34621b5381d73f55b65499e24a1a677f			

#5 - 2022-12-22 20:44 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155959	general/platform/vendor/thundercom/apps/TCService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shihao0506@thundersoft.com
FW:MCU-OTA:Disable EVT1 to upgrade mcuTC-RID: 1201-0200401IssueID: TS-R-DF-112378Change-Id: I65ae52747ab1f65af7579d46d5926c45f38fbacf			

#6 - 2022-12-22 20:53 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
162530	general/platform/packages/apps/SettinsIntelligence	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:McuUpdate: Add Special Code to start McuUpdate1.Add Special Code to start McuUpdate2.Use switch instead of if to determine the special codeTC-RID: 1201-0200401IssueID: TS-R-DF-112378Change-Id: I92b1800247c66b27856a8a2225b928c22a88e013			

#7 - 2022-12-22 20:53 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
162569	general/platform/vendor/thundercom/apps/FOTA	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:McuUpdate: Don't display on launcher1.Don't display on launcherTC-RID: 1201-0200401IssueID: TS-R-DF-112378Change-Id: Id9253d0ab0b286b69836ebf4d2cbe6e58cde2be3			

