

Figure - Bug #112449

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】开发者选项-图片驱动程序偏好设置-点击之后闪退会主界面

2022-10-09 14:44 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-10-09
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V2.0_update_20221012	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20221009
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Major	Fixed Version:	
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	IT		

Description

- 【前提条件】
- 1、设备进入开发者模式
- 【测试步骤】
- 1、进入开发者选项
- 2、点击图片驱动程序偏好设置
- 【预期结果】
- 2、成功进入图片驱动程序偏好设置
- 【实际结果】
- 2、点击之后闪退会主界面
- 【复现率】
- 5/5
- 【Log】
- 截图见附件

History

- #1 - 2022-10-09 17:12 - CD AF-陈羽杰
- Status changed from New to ASSIGNED
- % Done changed from 0 to 60
- Resolution changed from -- to FIXED
- Root cause set to 编码问题

- Current conclusion
- 分析中
- My analysis
- 原生页面与SettingActivity强绑定。强转失败导致crash
- Next action
- 本地修复验证

#2 - 2022-10-09 18:33 - CD AF-陈羽杰

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD AF-陈羽杰 to CD TEST-方永红
- % Done changed from 60 to 100
- Degrated changed from -- to No

■ Current conclusion

已修复

■ My analysis

原生页面与SettingActivity强绑定。强转失败导致crash

■ Submit URL

<https://dev.thundercomm.com/gerriit/c/general/platform/packages/apps/Settings/+/154168>

#3 - 2022-10-10 11:25 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

#4 - 2022-10-10 11:25 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#5 - 2022-12-22 20:41 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154168	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	yujie.chen@thundersoft.com
AF:Settings: Fix Developer Page BugDeveloper Options - Image Driver Preferences - Click to exit the main interfaceTC-RID: 1201-0201809IssueID: TS-R-BUG-112449Change-Id: Ia06f656d505eab62cb41600f0df049e79ce1ca21			

Files			
Phone-5221FC0 2022-10-09 14-27-50.mp4	21.7 MB	2022-10-09	CD TEST-方永红
图片驱动配置闪退.log	18.4 KB	2022-10-09	CD TEST-方永红