

Figure - 开发 Dev #112528

开发 Dev # 110122 (New): 【MK】管理总票
开发 Dev # 110126 (New): 【MK】【AF】管理总票
开发 Dev # 110715 (完成 Closed): 【MK】【FW】【VehicleDataControl】【TC-RID: 1201-0206101】
【MK】【FW】【InitialSetting】【TC-RID: 1201-0200701】购车激活引导
2022-10-12 16:53 - CD FW 曹覃刚

Status:	取消 Canceled	Start date:	2022-10-12
Priority:	Normal	Due date:	2022-10-15
Assignee:	CD FW-程天颖	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:			
Description			
■需求列表: 中控进行激活，副屏用户引导 ■提出URL： 暂无 ■自测case： 暂无 ■注意点：需要测试注意的前提条件 暂无			

History

- #1 - 2022-10-13 17:06 - CD FW-程天颖
- Status changed from New to 进行中 In Progress
- % Done changed from 0 to 10
- #2 - 2022-10-17 10:23 - CD FW-程天颖
- % Done changed from 10 to 40
- #3 - 2022-10-17 10:24 - CD FW-程天颖
- % Done changed from 40 to 10
- #4 - 2022-11-08 10:59 - CD FW-程天颖
- Status changed from 进行中 In Progress to 取消 Canceled
- % Done changed from 10 to 100

和首次购车激活重复

#5 - 2022-12-22 20:42 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
154955	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:InitialSetting: Add InitialSetting to the compilation environmentAdd InitialSetting to the compilation environmentTC-RID: 1201-0200701IssueID:			

#6 - 2022-12-22 20:42 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155002	general/platform/vendor/thundercom/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:InitialSetting: Add InitialSetting base versionAdd InitialSetting base versionTC-RID: 1201-0200701IssueID: TS-R-DF-112528Change-Id: I721ee8feb2d22016a9356aa6ca90db87bcb6501b			

#7 - 2022-12-22 20:42 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155175	general/platform/packages/apps/Provision	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:InitialSetting: Add activation guide portalAdd activation guide portalTC-RID: 1201-0200701IssueID: TS-R-DF-112528Change-Id: I1035bcf6531e12ee4ac7bdf1ac6eca108bad9764			

#8 - 2022-12-22 20:43 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
155366	general/platform/packages/apps/Provision	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:InitialSetting: remove activation guide portalremove activation guide portalTC-RID: 1201-0200701IssueID: TS-R-DF-112528Change-Id: I4f5c9b7b863ceed3878b96fa0b203a0df5b78875			

#9 - 2022-12-22 20:54 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
164981	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:InitialSetting: 1.Cant click TCSetupWizard when launch by Provision1.Cant click TCSetupWizard when launch by ProvisionTC-RID: 1201-0200701IssueID: TS-R-DF-112528Change-Id: Ia3a71b69462e6e648dbc93c7ee999bc2fe24a23			

#10 - 2022-12-22 20:55 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
165202	general/platform/vendor/thundercom/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:InitialSetting:Save activate data when factory reset1.Save activate data when factory resetTC-RID: 1201-0200701IssueID: TS-R-DF-112528Change-Id: I85a1f473112379afe0d5047f6f100fd627223ceb			

#11 - 2023-02-17 18:05 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
182377	general/platform/vendor/thundercom/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:InitialSetting:Eliminate the sound of the guide videosSince we enable the IDCM audio control, If there is no IDCM,we can't play audio then it will stay at bootanimation and can'tenter home screen.Delete audio data to make sure devicecan enter home screen.TC-RID: 1201-0200701IssueID: TS-R-DF-112528Change-Id: If9c22e69298bfb62d8c8e86b91ed28f6899a5fff			

#12 - 2023-03-29 19:20 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
190558	general/platform/packages/apps/Provision	Pre_figure_turbox-c2130c-la1.1-qssi12-ftm_v0081	caoqg0702@thundersoft.com
AF:InitialSetting: Remove activation guide portalTC-RID: 1201-0200701IssueID: TS-R-DF-112528Change-Id: I6793e53a51c08faed0b6513a0428daf0aba302bd			

#13 - 2023-04-16 11:28 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
193849	general/platform/packages/apps/Provision	Pre_figure_turbox-c2130c-la1.1-qssi12-ftm_v0090	wangxl0510@thundersoft.com
AF:InitialSetting: Remove activation guide portalTC-RID: 1201-0200701IssueID: TS-R-DF-112528Change-Id:			

I6793e53a51c08faed0b6513a0428daf0aba302bd(cherry picked from commit 2e554bfcd44913b11c1760363805d60d191cbd2d)

#14 - 2023-04-19 09:54 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
194574	general/platform/vendor/thundercom m/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:InitialSetting: Add unactivation loop banner images.TC-RID: 1201-0200701IssueID: TS-R-DF-112528Change-Id: I856150b3a8abe9e9074914302a682e11ae5e2c8a			

#15 - 2023-04-25 19:07 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
196119	general/platform/vendor/thundercom m/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:InitialSetting: Optimize natigate to home function.TC-RID: 1201-0200701IssueID: TS-R-DF-112528Change-Id: I5db60703204e0265a81cdbc28544f905c1e99d45			

#16 - 2023-05-03 16:34 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
197286	general/platform/packages/apps/Provis ion	Pre_figure_turbox-c2130c-la1.1-qssi12 -ftm_v0095	wangxi0510@thundersoft.com
AF:InitialSetting: Remove activation guide portalTC-RID: 1201-0200701IssueID: TS-R-DF-112528Change-Id: I6793e53a51c08faed0b6513a0428daf0aba302bd(cherry picked from commit 2e554bfcd44913b11c1760363805d60d191cbd2d)(cherry picked from commit e8faf90690601ece8887219a64aa775dcd8d9659)			

#17 - 2023-05-16 13:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
200314	general/platform/vendor/thundercom m/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:InitialSetting: Set lottie animation load cache to false.TC-RID: 1201-0200701IssueID: TS-R-DF-112528Change-Id: I20140b2c4b9be571acae97dadb0499d9cbaa3c36			

#18 - 2023-07-06 11:19 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212465	general/platform/vendor/thundercom m/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:InitialSetting: The USER version does not allow skipping activation.TC-RID: 1201-0200701IssueID: TS-R-DF-112528, IOVDEV-36267Change-Id: ladcaa28de38861d27ea3b103800e663e986fc1cb			

#19 - 2023-07-06 19:32 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212788	general/platform/vendor/thundercom m/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:InitialSetting: The USER version does not allow skipping activation.TC-RID: 1201-0200701IssueID: TS-R-DF-112528, IOVDEV-36267Change-Id: ladcaa28de38861d27ea3b103800e663e986fc1cb(cherry picked from commit b451867e408d52d3e6edcab34417d149b7389050)			

#20 - 2023-07-18 19:59 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
215799	general/platform/packages/apps/Provis ion	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:InitialSetting: Make page provision transparentMake page provision transparentTC-RID: 1201-0200701IssueID: TS-R-DF-112528, IOVDEV-37515Change-Id: l0581e4b466f475aeb3806537393402a49d9df371			

#21 - 2023-07-19 23:55 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
216246	general/platform/packages/apps/Provis ion	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:InitialSetting: Make page provision transparentMake page provision transparentTC-RID: 1201-0200701IssueID: TS-R-DF-112528, IOVDEV-37515Change-Id: l0581e4b466f475aeb3806537393402a49d9df371(cherry picked from commit b48a2097da3aedfcdcc2c5e8590e082e6180d412)			

#22 - 2023-07-28 18:16 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
218271	general/platform/vendor/thundercom m/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	lei.zheng@thundersoft.com
AF:InitialSetting: Fix missing unregisterReceiver issueTcSetupStartActivity has leaked IntentReceive when run monkey test.TC-RID: 1201-0200701IssueID: TS-R-DF-112528, IOVDEV-38328Change-Id: I674e2ee2451d936512df1c2f1d51d144117c3b6d			

#23 - 2023-08-01 22:18 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
219405	general/platform/vendor/thundercom m/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:InitialSetting: Fix missing unregisterReceiver issueTcSetupStartActivity has leaked IntentReceive when run monkey test.TC-RID: 1201-0200701IssueID: TS-R-DF-112528, IOVDEV-38328Change-Id: I674e2ee2451d936512df1c2f1d51d144117c3b6d(cherry picked from commit a8844eb9d64c84e197bfe056b5b4357f052c4568)			

#24 - 2023-08-16 19:23 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
303690	general/platform/vendor/thundercom m/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:InitialSetting: Timer task request activate statusTC-RID: 1201-0200701IssueID: TS-R-DF-112528Change-Id: Iaa62e91343569f0d03f979170857dfe6f6b4d8b9			

#25 - 2023-08-17 19:13 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
304161	general/platform/vendor/thundercom m/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:InitialSetting: Timer task request activate statusTC-RID: 1201-0200701IssueID: TS-R-DF-112528Change-Id: Iaa62e91343569f0d03f979170857dfe6f6b4d8b9(cherry picked from commit e61a33d258ad39286a9aa00a867651fbd1d2f991)			

#26 - 2023-09-01 10:23 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
308749	general/platform/vendor/thundercom m/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:InitialSetting: Disable status bar and navigation barTC-RID: 1201-0200701IssueID: TS-R-DF-112528,IOVISSUE-15335Change-Id: I70f8dc20a98d91a2b1b9c34de6dde8536fb100c9			

#27 - 2023-10-08 00:31 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317139	general/platform/vendor/thundercom m/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:InitialSetting: Disable status bar and navigation barTC-RID: 1201-0200701IssueID: TS-R-DF-112528,IOVISSUE-15335Change-Id: I70f8dc20a98d91a2b1b9c34de6dde8536fb100c9(cherry picked from commit 878638baeb969de36de9100d367bed9eed4e150a)			

#28 - 2023-10-12 09:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
318581	general/platform/vendor/thundercom m/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:InitialSetting: Update setup wizard animation.TC-RID: 1201-0200701IssueID: TS-R-DF-112528Change-Id: I66407591226eabf30b9974270e8d3fffe0c7eb24			

#29 - 2023-10-27 01:25 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323281	general/platform/vendor/thundercom m/apps/TCSetupWizard	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:InitialSetting: Update setup wizard animation.TC-RID: 1201-0200701IssueID: TS-R-DF-112528Change-Id: I66407591226eabf30b9974270e8d3fffe0c7eb24(cherry picked from commit 00ead16cb56bdb30da13ba398cae50772e57d1e0)			