

Figure - Bug #112553

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】在设置打开的情况下，重复从控制空心进入“wlan、蓝牙、深色模式、护眼模式”，会出现页面空白的情况

2022-10-13 15:49 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-10-13
Priority:	Normal	Due date:	2022-10-19
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_20221030	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20221020
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20221020
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	IT		
Description			
【前提条件】 1、设备正常开机 【测试步骤】 1、打开设置-网络与互联网页面 2、在该页面下划打开控制中心 3、长按“互联网”进入设置 4、上划关闭控制中心，查看设置页面 5、重复2、3、4操作 【预期结果】 5、正常显示“WLAN”页面 【实际结果】 5、会出现页面空白的情况（只有一个标题） PS: 1、在出现空白页面之后点击左上角的返回按钮，会回到正常显示页面，详情见视频 2、《wlan、蓝牙、深色模式、护眼模式》都会出现该情况			

History

- #1 - 2022-10-18 10:29 - CD FW-王伟
- Assignee changed from CD FW-程天颖 to CD AF-陈羽杰
- #2 - 2022-10-19 14:39 - CD AF-陈羽杰
- Status changed from New to ASSIGNED
- #3 - 2022-10-19 14:41 - CD AF-陈羽杰
- Due date set to 2022-10-19
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD AF-陈羽杰 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED

- Degrated changed from -- to No
- Root cause set to 编码问题

■ Current conclusion

已修复本地验证

■ My analysis

对外部跳转settings 判断不够准确，导致添加重复页面，从而导致白屏

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+/156316>

#4 - 2022-10-20 11:25 - CD TEST-方永红

- Verified Version set to FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20221020.alpha_0038

10.20 验证成功

#5 - 2022-10-20 11:26 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

#6 - 2022-10-21 10:51 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#7 - 2022-12-22 20:44 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
156316	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	yujie.chen@thundersoft.com
AF:Settings: Fix outside jump exception1.Repeatedly enter the setting from the control blank, and the page will be blank2.Shortcut entry setting page display exceptionTC-RID: 1201-0201813IssueID: TS-R-BUG-112553,TS-R-BUG-112606Change-Id: I041190b277bdf6ff6487daeb0c6433afa9620780			

Files

131528.txt	8.72 MB	2022-10-13	CD TEST-方永红
Phone-5221FC0 2022-10-13 15-44-04.mp4	24 MB	2022-10-13	CD TEST-方永红