

Figure - Bug #112554

Bug # 111192 (CLOSED): 【Figure】【EVT3】【EE】【启动时间1分6秒】【Performance】

service and HAL crop

2022-10-13 16:09 - CD SYSTEM-龚元祝

Status:	CLOSED	Start date:	2022-10-13
Priority:	Normal	Due date:	
Assignee:	CDTS_TEST 刘勇	% Done:	100%
Category:	SYSTEM	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_update_20221115	Found Version:	every version
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	Free Test		
Description			
经调查需要裁剪以下服务：			
1 qvrd			
2 sxrd			
3 android.hardware.light			
4 android.hardware.camera.provider			

History

#1 - 2022-10-20 11:21 - CD SYSTEM-赵正军

- Status changed from New to ASSIGNED

- % Done changed from 0 to 100

代码已提交，待VB验证

<https://dev.thundercomm.com/gerrit/c/152942>

<https://dev.thundercomm.com/gerrit/c/156625>

#2 - 2022-10-24 15:38 - CD SYSTEM-龚元祝

crop the camera provider service：

<https://dev.thundercomm.com/gerrit/c/general/LINUX/android/vendor/qcom/proprietary/+/156863>

crop the lights service：

<https://dev.thundercomm.com/gerrit/c/general/platform/hardware/interfaces/+/154265>

#3 - 2022-10-24 16:37 - CD SYSTEM-龚元祝

- Status changed from ASSIGNED to RESOLVED

- Assignee changed from CD SYSTEM-赵正军 to CDTS_TEST 王成

已入库。请用25日的DB版本验证。

check要点如下：

1 adb logcat -b all > l.txt

2 检查确认l.txt中无camera.provider和android.hardware.light相关日志。

#4 - 2022-10-26 14:46 - CD SYSTEM-龚元祝
- Category set to SYSTEM

#5 - 2022-10-28 10:19 - CDTS_TEST 王成
- Assignee changed from CDTS_TEST 王成 to 移动测试一组_CDTS 刘强

#6 - 2022-10-28 16:53 - 移动测试一组_CDTS 刘强
- Status changed from RESOLVED to VERIFY_FAILED
- Assignee changed from 移动测试一组_CDTS 刘强 to CD SYSTEM-龚元祝

验证失败：
版本号：01.00.X101_20221028_private_user

112554：service and HAL crop
figure:/ \$ ps -A | grep camera.provider
1|figure:/ \$ ps -A | grep hardware.light
system 818 1 13035952 4872 0 0 S android.hardware.lights-service.qti
需要继续调查：android.hardware.lights-service.qti

#7 - 2022-11-02 13:52 - CDTS-TEST 周婷
- Target version set to VX1_MCE_FSE_V3.0_update_20221115

#8 - 2022-11-03 14:13 - CD SYSTEM-龚元祝
- Status changed from VERIFY_FAILED to RESOLVED

已裁剪android.hardware.lights-service.qti service

<https://dev.thundercomm.com/gerrit/c/general/device/qcom/vendor-common/+159912>

#9 - 2022-11-03 17:46 - CD SYSTEM-龚元祝
- Assignee changed from CD SYSTEM-龚元祝 to CDTS_TEST 刘勇

请用下面的版本验证。
/Pre_figure/VerifyBuild/Pre_figure_turbox-c2130c-la1.1-qssi12-dev/20221103/202211031415-2097

#10 - 2022-11-10 16:09 - CDTS_TEST 刘勇
- File logcat.txt added

【HW】EVT2-VX1
【SW】/Pre_figure/VerifyBuild/Pre_figure_turbox-c2130c-la1.1-qssi12-dev/20221103/202211031415-2097
【操作步骤】
1.DUT烧录版本
2.使用一下命令查看
figure:/ \$ ps -A | grep camera.provider
figure:/ \$ ps -A | grep hardware.light
【实际结果】

2.无任何输出

【验证次数】2次
【验证结果】验证VB版本通过，无

#11 - 2022-11-10 16:10 - CDTs_TEST 刘勇
- Assignee changed from CDTs_TEST 刘勇 to CD SYSTEM-龚元祝

#12 - 2022-11-17 16:05 - CD SYSTEM-胡兵
- Assignee changed from CD SYSTEM-龚元祝 to CDTs_TEST 刘勇

提交已合入，请使用明天的DB进行回归
<https://dev.thundercomm.com/gerrit/c/general/device/qcom/vendor-common/+159912>

#13 - 2022-11-18 16:13 - CD SYSTEM-胡兵

Hi 刘勇
已沟通，最新patch回退合入，android.hardware.light不用裁剪，android.hardware.sensor.light已被裁剪，请使用最新的DB进行回归

Thanks

#14 - 2022-11-18 16:31 - CDTs_TEST 刘勇
- Status changed from RESOLVED to VERIFIED

【HW】EVT2-VX1
【SW】FlatBuild_HH_VX1_MCE_FSE.M.D.userdebug.01.00.X101.202211181428
【操作步骤】
1.DUT烧录版本
2.使用一下命令查看
figure:/ \$ ps -A | grep camera.provider
figure:/ \$ ps -A | grep hardware.light
【实际结果】
figure:/ \$ ps -A | grep hardware.light
system 858 112941744 4984 0 0 S android.hardware.lights-service.qti
figure:/ \$ ps -A | grep camera.provider 无任何输出

【验证次数】2次
【验证结果】验证UD版本验证通过。

#15 - 2022-11-18 17:07 - CDTs_TEST 刘勇
- Status changed from VERIFIED to CLOSED

#16 - 2022-12-22 20:41 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
154265	general/platform/hardware/interfaces	Pre_figure_turbox-c2130c-la1.1-vendor-dev	gongyz1203@thundersoft.com

SYSTEM: crop lights service1. crop the lights service when there is no LEDs hardware.TC-RID: 1200-0800201IssueID: TS-R-BUG-112554Change-Id: lafc26a88728b01ba188f3440b01174e014ad95e9

#17 - 2022-12-22 20:45 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
156863	general/LINUX/android/vendor/qcom/proprietary	Pre_figure_turbox-c2130c-la1.1-vendor-dev	gongyz1203@thundersoft.com
SYSTEM: crop camera.provider service1. crop the camera.provider service when there is no camera hardware.TC-RID: 1200-0800201IssueID: TS-R-BUG-112554Change-Id: I51113b1639e64b863c10f611a76b21c65f1cc270			

#18 - 2022-12-22 20:53 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
163747	general/device/qcom/vendor-common	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiao.yu@thundersoft.com
Revert "SYSTEM: crop lights-qt service" This reverts commit 1a719f26397b1fe389c9640d9d4b257e53a836aa.Reason for revert: System can't startTC-RID: 1200-0800201IssueID: TS-R-BUG-112554Change-Id: Id3f4dbbe74209e05b9a3e07c38388608aa26ea09			

Files

logcat.txt	2.06 MB	2022-11-10	CDTS_TEST 刘勇
------------	---------	------------	--------------