Figure - Bug #112647

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111046 (New): AF-V2.0-系统手势

【AF】【EVT】【系统手势】添加微件页面无法通过左划或者右划手势返回

2022-10-18 17:39 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-10-18
Priority:	Normal	Due date:	2022-10-18
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour

Target version: VX1_MCE_FSE_V3.0_20221030

 Need_Info:
 - Found Version:
 FlatBuild_VX1_MCE_xx.xx_FSE.R.userdebug.0.0.0.202

 Resolution:
 FIXED
 Degrated:
 No

Severity: Normal Verified Version: FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221023

Reproducibility: Every time Fixed Version: 2022-10-22
Test Type: IT Root cause: 编码问题

Description

【前提条件】

1、设备已开机

【测试步骤】

- 1、长按桌面进入微件添加模式
- 2、通过左划或者右划手势返回

【预期结果】

2、成功返回桌面

【实际结果】

2、无法返回

【复现率】

必现

History

#1 - 2022-10-19 09:42 - CD APP-王营

- Status changed from New to ASSIGNED
- Assignee changed from CD APP- 王营 to CD APP-李蛟

#2 - 2022-10-19 11:47 - CD APP-李蛟

- Due date set to 2022-10-18
- Status changed from ASSIGNED to RESOLVED
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Root cause set to 编码问题
- #3 2022-10-19 12:28 CD APP-**李蛟**
- Status changed from RESOLVED to ASSIGNED

#4 - 2022-10-20 09:23 - CD APP-李蛟

2025-07-04 1/2

Current conclusion

时序问题

My analysis

mlsOpen标志修改在状态检测之后,导致无法正确检测当前状态,启用返回手势 Submit URL

https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Launcher3/+/156601

#5 - 2022-10-21 10:23 - CD APP-李蛟

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-李蛟 to CD TEST-方永红
- Fixed Version set to 2022-10-22

#6 - 2022-10-24 10:40 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221023.alpha

10.24 验证通过

#7 - 2022-10-24 10:40 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#8 - 2022-12-22 20:45 - CD FW-王伟

Gerrit Merge Information:

ID	Project	Branch	Uploader
156601	general/platform/packages/apps/Launc	Pre_figure_turbox-c2130c-la1.1-qssi12	jiao.li_a@thundersoft.com
	her3	-dev	

FW:Launcher: Fix back gesture in WidgetsFullSheet1. Set mlsOpen before addView WidgetsFullSheet.TC-RID: 1201-0205305IssueID: TS-R-DF-112647Change-Id: I0a4ae61e98e76cc0af8af7f328945e871a13f251

Files

1738.txt 4.62 MB 2022-10-18 CD TEST-方永红

2025-07-04 2/2