

Figure - Bug #112712

测试 Test-IT # 111062 (New): V3.0功能测试

测试 Test-IT # 111069 (New): AF-V3.0--Launcher/SystemUI-小窗模式入口

【AF】【EVT】【小窗模式】应用小窗Mini模式下，拖动小窗应用至其它位置时，小窗消失

2022-10-19 15:36 - CD Test赵飞

Status:	CLOSED	Start date:	
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	窗口定制	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_20221030	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20221019.alpha
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.20221028
Severity:	Normal	Fixed Version:	2022-10-28
Reproducibility:	Every time	Root cause:	轻滑动逻辑错误 导致小窗消失
Test Type:	IT		

Description
测试版本：FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20221019.alpha
【前提条件】
1、设备已开机
【测试步骤】
1、长按桌面任意一个支持小窗的应用，如“图库”图标，选择“小窗”
2、点击小窗顶部“Mini模式”图标
3、任意拖动小窗至其他位置（屏幕其他三个角）
【预期结果】
3、应用Mini小窗正常被拖动至预期的位置
【实际结果】
3、应用Mini小窗被拖动了几次后，小窗消失
【复现率】
5/5
【日志】
录屏及日志见附件

History

#1 - 2022-10-19 15:45 - CD Test赵飞

- File logcat.txt added

#2 - 2022-10-24 20:45 - DL FW-张挽强

- Status changed from New to ASSIGNED

My analysis

上划触发了轻滑动造成了小窗关闭

Current conclusion

1.上划区域有问题 已经修正

2.小窗无法向上移除屏幕 已经解除限制

Next action / ■ Submit URL

调查上划小窗造成屏幕下侧黑屏

#3 - 2022-10-25 09:08 - DL FW-王琳

My analysis

当前修改方式, 引发其它问题, 还需要调查原因

Next action

10/30交付有风险, 建议放到下一个交付节点

#4 - 2022-10-25 10:16 - CDTS-TEST 周婷

10/25或者10/26出一个 结论说明

#5 - 2022-10-25 10:51 - DL FW-张挽强

- % Done changed from 100 to 40

#6 - 2022-10-25 18:19 - DL FW-张挽强

My analysis

解除windowConfiguration.getBounds(), 这使应用程序的边界可能回受到动画或者瞬态交互边界的影响, 造成屏幕下侧有闪黑的现象。

Next action

- 1.下载编译winscop 来分析闪黑的窗口内容
- 2.如果这个问题没有结论, 我理解可以做一个上移边界的限制, 来暂时解决消失和平衡轻滑动的方案。

#7 - 2022-10-27 18:12 - DL FW-张挽强

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from DL FW-张挽强 to CD TEST-方永红
- % Done changed from 40 to 100
- Resolution changed from -- to FIXED
- Fixed Version set to 2022-10-28
- Root cause set to 轻滑动逻辑错误 导致小窗消失

#8 - 2022-10-28 15:12 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202210280435

10.28 验证关闭

#9 - 2022-10-28 15:12 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#10 - 2022-12-22 20:46 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
158160	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12	zhangwq0711@thundersoft.com

		-dev	
AF:MultiWindow:fixed freeform movement disappeared1.Modify the freeform light sliding logicTC-RID: 1201-0204601IssueID: TS-R-BUG-112712Change-Id: I464945785bb1aa343b7e8c2611bdae9bdaa60c49			

Files

screen-20221019-061321.mp4	10.9 MB	2022-10-19	CD Test赵飞
logcat.txt	3.66 MB	2022-10-19	CD Test赵飞