Figure - Bug #112753

测试 Test-IT # 111062 (New): V3.0功能测试

测试 Test-IT # 111067 (New): AF-V3.0--Launcher/SystemUI-任务管理器

【AF】【EVT】【任务管理器】打开应用小窗,进入多任务管理器,后台进程卡片显示有误

2022-10-20 17:40 - CD TEST-方永红

Status:	CLOSED	Start date:		
Priority:	Normal	Due date:		
Assignee:	CD TEST-方永红	% Done:	100%	
Category:	窗口定制	Estimated time:	0.00 hour	
Target version:	VX1_MCE_FSE_V3.0_update_20221130			
Need_Info:		Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.2	022102
Resolution:	FIXED	Degrated:		
Severity:	Normal	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.0).X101.:
Reproducibility:	Every time	Fixed Version:	2022-10-26	
Test Type:	IT	Root cause:	截图时小窗的尺寸不对 小窗进入 recent	task 去
Target version: Need_Info: Resolution: Severity: Reproducibility: Test Type:	国口に前 VX1_MCE_FSE_V3.0_update_20221130 FIXED Normal Every time IT	Found Version: Degrated: Verified Version: Fixed Version: Root cause:	FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0. FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.0 2022-10-26 截图时小窗的尺寸不对 小窗进入 recer	2)(

Description

【前提条件】

- 1、设备已开机
- 2、后台无进程

【测试步骤】

- 1、打开一个小窗
- 2、进入任务管理器
- 3、查看后台进程卡片

【预期结果】

3、只有一个小窗进程卡片

【实际结果】

3、同时出现一个小窗卡片一个功能卡片(见截图)

【Log】

Log见附件

History

#1 - 2022-10-20 18:55 - CD APP-王营

- Assignee changed from CD APP- 王营 to DL FW- 张挽强

Current conclusion

目前启动小窗后将此task放入了recent的tasklist中

My analysis

之前和王琳沟通,打开小窗应用的时候,不要将这个任务加入到Recent的tasklist

目前recent中小窗卡片的显示获取方式为小窗开发同事在ActivityManager中提供了对应的接口获取

所以启动小窗的时候就不要将这个task放入recent的tasklist中。

Next action

请小窗同事帮忙修改此问题。

#2 - 2022-10-24 14:17 - DL FW-**张挽强**

- Status changed from New to RESOLVED

- Assignee changed from DL FW- 张挽强 to CD TEST- 方永红
- Resolution changed from -- to FIXED
- Fixed Version set to 2022-10-25
- Root cause set to 截图时小窗的尺寸不对

#3 - 2022-10-24 14:24 - DL FW-王琳

- Status changed from RESOLVED to ASSIGNED
- Assignee changed from CD TEST-方永红 to DL FW-张挽强

#4 - 2022-10-25 09:05 - DL FW-王琳

My analysis 初步分析是进入recent的时候调用时序上存在问题, Next action 需要结合112698 112753 112755 case一起考虑下交互时序的设计. 10/30交付有风险,建议放到下一个交付节点

#5 - 2022-10-25 14:23 - CDTS-TEST 周婷 - Target version changed from VX1_MCE_FSE_V3.0_20221030 to VX1_MCE_FSE_V3.0_update_20221115

#6 - 2022-11-01 14:56 - CD TPM-王祥林

- Category changed from CD-APP to 窗口定制

#7 - 2022-11-02 14:29 - CDTS-TEST 周婷

- Target version changed from VX1_MCE_FSE_V3.0_update_20221115 to VX1_MCE_FSE_V3.0_update_20221130

重新梳理方案,11/30 fix

- #8 2022-11-08 15:11 DL FW-张挽强
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from DL FW- 张挽强 to CD TEST-方永红
- % Done changed from 40 to 100
- Fixed Version changed from 2022-10-25 to 2022-10-26
- Root cause changed from 截图时小窗的尺寸不对 to 截图时小窗的尺寸不对
- 小窗进入 recenttask 去重

#9 - 2022-11-09 10:39 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202211090616

11.9 目前打开小窗,直接进入任务管理器,只有小窗进程 验证通过

#10 - 2022-11-09 10:39 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#11 - 2022-12-22 20:50 - CD FW-**王伟**

Gerrit Merge Information :

ID	Project	Branch	Uploader				
160878	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12	jian.hao@thundersoft.com				
		-dev					
AF:MultiWindow:Open the application window and enter the multitask manager. The background process card displays incorrectly1. Modify the return value of							
RecentListChange-Id: I81095d64f0101916a55b02923106e5c72337bc83TC-RID: 1201-0204601IssueID: TS-R-BUG-112753 TS-R-BUG-112905							
TS-R-BUG-112755							

_	•	
-	I	201
	I	100

1 100			
Phone-STS40X190122 2022-10-20 17-33-39.mp4	7.19 MB	2022-10-20	CD TEST-方永红
小窗任务栏.png	136 KB	2022-10-20	CD TEST-方永红
1739.txt	6.83 MB	2022-10-20	CD TEST-方永红