

Figure - Bug #112773

测试 Test-IT # 111062 (New): V3.0功能测试

测试 Test-IT # 111069 (New): AF-V3.0--Launcher/SystemUI-小窗模式入口

【AF】【EVT】【小窗模式】小窗进入mini模式后进行快速上下滑动（单独动作，不连贯），小窗移动后吸附的位置不对

2022-10-21 18:20 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-10-21
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	窗口定制	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_20221030	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20221020
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221026
Severity:	Normal	Fixed Version:	2022-10-26
Reproducibility:	Every time	Root cause:	轻滑动逻辑错误 造成mini窗小窗落点位置出错
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、打开一个应用的mini模式（如图库）（默认位置为左上角）			
2、用手指按住mini小窗，快速向下滑动			
【预期结果】			
2、小窗吸附到左下角			
【实际结果】			
2、小窗吸附到右下角			
注：从其他三个角落快速滑动也会有此问题			

History

- #1 - 2022-10-24 16:18 - DL FW-张挽强
 - Status changed from New to ASSIGNED
 - % Done changed from 0 to 80
 - Resolution changed from -- to FIXED
 - Root cause set to 轻滑动逻辑错误 造成mini窗小窗落点位置出错
- #2 - 2022-10-24 20:56 - DL FW-张挽强
 - Status changed from ASSIGNED to RESOLVED
 - Assignee changed from DL FW- 张挽强 to CD TEST- 方永红
 - Fixed Version set to 2022-10-25
- #3 - 2022-10-24 21:09 - DL FW-张挽强
 - Assignee changed from CD TEST- 方永红 to DL FW- 张挽强
- #4 - 2022-10-25 10:48 - CD TEST-方永红
 - Parent task changed from #112712 to #111069

#5 - 2022-10-25 14:08 - DL FW-张挽强

- Assignee changed from DL FW-张挽强 to CD TEST-方永红
- % Done changed from 80 to 100
- Fixed Version changed from 2022-10-25 to 2022-10-26

#6 - 2022-10-26 10:26 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221026.alpha

10.26 经验证，小窗快速移动后，落点不准确的问题已修复（消失问题还在，已有票进行跟踪）

#7 - 2022-10-26 10:27 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
20.txt	991 KB	2022-10-21	CD TEST-方永红