

Figure - Bug #112820

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI---Setting
【AF】【EVT】【设置】安全-可信代理部分需裁剪掉
2022-10-24 16:31 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-10-24
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_20221030	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221026.alpha
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221026.alpha
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	不需要的项目，已裁剪
Test Type:	IT		
Description			
【前提条件】 设备已开机			
【测试步骤】 1、进入设置 - 安全 2、查看页面显示			
【预期结果】 2、无“可信代理”功能及相应UI显示			
【实际结果】 2、目前安全菜单中存在可信代理			

History

- #1 - 2022-10-25 13:41 - CD FW 曹覃刚
- Status changed from New to RESOLVED
 - Resolution changed from -- to FIXED
 - Root cause set to 不需要的项目，已裁剪
- 提交已入库
- <https://dev.thundercomm.com/gerriit/c/general/platform/packages/apps/Settings/+157686>
- #2 - 2022-10-26 14:17 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
 - Assignee changed from CD AF-陈羽杰 to CD TEST-方永红
 - Verified Version set to FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221026.alpha
- 10.26 验证关闭
- #3 - 2022-10-26 14:17 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED
- % Done changed from 0 to 100

#4 - 2022-12-22 20:46 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
157686	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:Settings: delete trust agents itemdelete trust agents itemTC-RID: 1201-0201807IssueID: TS-R-BUG-112820Change-Id: I6d2a962b69e0901f01437a73d739e1c802603a43			

Files

1630.png	98.4 KB	2022-10-24	CD TEST-方永红
----------	---------	------------	-------------