

Figure - Bug #112910

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111045 (New): AF-V2.0-蓝牙接入兼容性

【AF】 【EVT】 【蓝牙】 手机蓝牙可以搜索到DUT， 并且可以进行配对连接

2022-10-25 15:06 - 物联网测试组_CDTS 段小刚

Status:	CLOSED	Start date:	2022-10-25
Priority:	Normal	Due date:	2022-11-04
Assignee:	物联网测试组_CDTS 段小刚	% Done:	50%
Category:	LC	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_update_20221115	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221023
Need_Info:	--	Degrated:	--
Resolution:	DUPLICATE	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	IT		

Description
Description
测试版本：FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221023.alpha
【前提条件】
1、设备已开机
2、车屏上的蓝牙已被打开
【测试步骤】
1、使用手机打开蓝牙进行搜索
2、找到对应车屏蓝牙——进行配对申请
3、配对成功
【预期结果】
3、根据prd文件只支持 耳机、音箱、键盘、手柄；所以应该手机蓝牙配对失败
【实际结果】
3、手机蓝牙配对成功
【复现率】
3/3
【Log】
log见附件

History

#1 - 2022-10-25 15:11 - 物联网测试组_CDTS 段小刚
- Parent task set to #111045

#2 - 2022-10-27 15:18 - CDTS-TEST 周婷
- Due date changed from 2022-10-29 to 2022-11-04
- Target version changed from VX1_MCE_FSE_V3.0_20221030 to VX1_MCE_FSE_V3.0_update_20221115

#3 - 2022-11-07 16:02 - CD LC 陶洪普

<http://192.168.87.66:8003/source/xref/plum-c6490-la2.0-vendor-qssi11-dev/LINUX/android/vendor/qcom/opensource/commonsys/packages/apps/Bluetooth/res/values/config.xml#16>

保留下面profile

```
<bool name="profile_supported_a2dp">true</bool>
<bool name="profile_supported_hs_hfp">true</bool>
<bool name="profile_supported_hid_host">true</bool>
<bool name="profile_supported_gatt">true</bool>
<bool name="pbap_include_photos_in_vcard">true</bool>
<bool name="pbap_use_profile_for_owner_vcard">true</bool>
<bool name="profile_supported_avrcp_target">true</bool>
<bool name="profile_supported_avrcp_controller">true</bool>
```

Disable 下面Profile

```
<bool name="profile_supported_pan">false</bool>
<bool name="profile_supported_hid_device">false</bool>
<bool name="profile_supported_opp">false</bool>
```

待确定

```
<bool name="profile_supported_sap">false</bool>
<bool name="profile_supported_pbap">false</bool>
<bool name="profile_supported_map">false</bool>
```

#4 - 2022-11-10 09:58 - CD LC 陶洪普

@涂宇,

请帮忙把patch连接更新上去,谢谢!

#5 - 2022-11-10 19:25 - CD LC 涂宇

- % Done changed from 0 to 50
- Resolution changed from -- to DUPLICATE

Hi ALL,

此问题同<https://share.thundersoft.com/redmine/issues/112914>

Thanks

#6 - 2022-11-14 01:54 - CD LC 陶洪普

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+/161706>
<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/qcom-opensource/packages/apps/Bluetooth/+/161709>

已验证。

下一步, review & merge.

#7 - 2022-11-14 21:44 - CD LC 陶洪普

- Status changed from New to RESOLVED
- Assignee changed from CD LC 陶洪普 to CDTs_TEST 王成

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+/161706>
<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/qcom-opensource/packages/apps/Bluetooth/+/161709>

已入库，请使用11.15DB Verify.谢谢！

#8 - 2022-11-16 10:06 - 物联网测试组_CDTS 段小刚

- Status changed from RESOLVED to VERIFIED
- Assignee changed from CDTS_TEST 王成 to 物联网测试组_CDTS 段小刚
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202211160534

验证结果：手机蓝牙可搜索到设备蓝牙，进行配对时，设备会主动决绝，导致无法配对——Pass

#9 - 2022-11-16 10:07 - 物联网测试组_CDTS 段小刚

- Status changed from VERIFIED to CLOSED

使用11.16user版本验证 该问题已解决——关闭

#10 - 2023-05-24 18:55 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
202288	general/platform/vendor/qcom-opensource/system/bt	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:BT: Adjust the bt trace level temporarilySet all the bt trace level to verbose for issue analysis.TC-RID: 1201-0400120IssueID: TS-R-BUG-112910Change-Id: I2ec3128e299009742f6c715e18842f0ddf938180			

#11 - 2023-10-08 17:53 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
316762	general/device/qcom/qssi	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:BT:Enable bt snoop log by defaultEnable bt snoop log by default.TC-RID: 1201-0400120IssueID: TS-R-BUG-112910Change-Id: Ib07289dd48ab409e4bb0cb89ec2e5b4a7766fec5			

#12 - 2023-10-13 19:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
317370	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com

LC:HiCar: Reconnect for nomanual hicar disconnection1. Init HiCarBtReconnectService2. When HiCar is disconnected and the list of trusted devices is not empty,try to connect trusted devices.3. After successful connection, stop the connection attempt.TC-RID: 1201-0400120IssueID: TS-R-BUG-112910, VCH-269Change-Id: I51c0c2863fd6630db44e03b76d261039a9b18383

#13 - 2023-10-13 19:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
318504	general/platform/vendor/qcom-opensource/packages/apps/Bluetooth	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:HiCar: Set HFP Client connect policy to ALLOWEDSet HFP Client connect policy to ALLOWED.TC-RID: 1201-0400120IssueID: TS-R-BUG-112910, VCH-269Change-Id: I92df5ad404871fd86b92998963c3655352407491			

#14 - 2023-10-16 17:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
319351	general/platform/vendor/qcom-opensource/packages/apps/Bluetooth	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
Revert LC:HiCar: Set HFP Client connect policy to ALLOWEDThis reverts commit 623bf5725c883a7a4bb2efaf566c9de870337ade.Reason for revert: For HiCar connect/reconnect when bt is A2dp source.TC-RID: 1201-0400120IssueID: TS-R-BUG-112910, VCH-269Change-Id: I26c06eef5cf4887c3014cc2e4e8e20482d034fc9			

#15 - 2023-10-16 17:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
319507	general/platform/vendor/qcom-opensource/packages/apps/Bluetooth	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:HiCar: Auto connect PANAutomatically connect PAN when Bluetooth is turned on.TC-RID: 1201-0400120IssueID: TS-R-BUG-112910, VCH-269Change-Id: I7e87f40afe55d727ee318392a6ffc3c2a4a9592a			

#16 - 2023-10-16 17:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
319502	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:HiCar: Reconnect for nomanual hicar disconnection(2/2)Try reconnecting the Bluetooth protocol untilthe HiCar connection is successful.TC-RID: 1201-0400120IssueID: TS-R-BUG-112910, VCH-269Change-Id: Ie7c403ae7397fea853326430f52f6094e1f0c68f			

#17 - 2023-10-20 20:42 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
321307	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:HiCar: Remove the task delay when HiCarBtConnectService initRemove the task delay when HiCarBtConnectService init.TC-RID: 1201-0400120IssueID: TS-R-BUG-112910, VCH-269Change-Id: I4a4425737b01e49bbc023777a0b0e06e100ea9b0			

#18 - 2023-10-20 20:42 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
321308	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:HiCar: Set supported 5G channelSet supported 5G channel [36,40,44,48,149]TC-RID: 1201-0400120IssueID: TS-R-BUG-112910, VCH-269Change-Id: I3c92ff48791301e9d5c5d658c070e7dfef39ade3			

#19 - 2023-10-20 20:42 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
321027	general/platform/vendor/hht/apps/HiCar	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:HiCar: Attempt to reconnect only after successful initAttempt to reconnect only after Bluetooth connected successfullyand HiCar init is successful.TC-RID: 1201-0400120IssueID: TS-R-BUG-112910, VCH-262Change-Id: Id775010686e3384ad19915d935125d668d37f437			

#20 - 2023-10-20 20:42 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
320999	general/platform/packages/modules/NetworkStack	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:HiCar: Set softap IP to 192.168.43.1 for wlan1Set softap IP to 192.168.43.1 for wlan1.TC-RID: 1201-0400120IssueID: TS-R-BUG-112910, VCH-262Change-Id: I770ec4c5652905550b6e3f95a186198acc59e03			

#21 - 2023-10-27 01:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323258	general/device/qcom/qssi	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
LC:BT:Enable bt snoop log by defaultEnable bt snoop log by default.TC-RID: 1201-0400120IssueID: TS-R-BUG-112910Change-Id: Ib07289dd48ab409e4bb0cb89ec2e5b4a776fec5(cherry picked from commit ad688fb20a1ecca1f75ac673b4b1a03e5afb87e5)			

#22 - 2023-10-27 01:14 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323272	general/platform/vendor/qcom-opensource/packages/apps/Bluetooth	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
LC:HiCar: Set HFP Client connect policy to ALLOWEDSet HFP Client connect policy to ALLOWED.TC-RID: 1201-0400120IssueID: TS-R-BUG-112910, VCH-269Change-Id: I92df5ad404871fd86b92998963c3655352407491(cherry picked from commit 623bf5725c883a7a4bb2efaf566c9de870337ade)			

#23 - 2023-10-27 01:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323273	general/platform/vendor/qcom-opensource/packages/apps/Bluetooth	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
Revert LC:HiCar: Set HFP Client connect policy to ALLOWEDThis reverts commit 623bf5725c883a7a4bb2efaf566c9de870337ade.Reason for revert: For HiCar			

connect/reconnect when bt is A2dp source.TC-RID: 1201-0400120IssueID: TS-R-BUG-112910, VCH-269Change-Id: I26c06eef5cf4887c3014cc2e4e8e20482d034fc9(cherry picked from commit 0547e5484be830ca7e127eb180ccc35c3a26889f)

#24 - 2023-10-27 01:18 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323276	general/platform/vendor/qcom-opensource/packages/apps/Bluetooth	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
LC:HiCar: Auto connect PANAutomatically connect PAN when Bluetooth is turned on.TC-RID: 1201-0400120IssueID: TS-R-BUG-112910, VCH-269Change-Id: I7e87f40afe55d727ee318392a6ffc3c2a4a9592a(cherry picked from commit 8c1a69ee37aae94c915f23d5ef1781aa65138931)			

#25 - 2023-10-27 01:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323320	general/platform/packages/modules/NetworkStack	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
LC:HiCar: Set softap IP to 192.168.43.1 for wlan1Set softap IP to 192.168.43.1 for wlan1.TC-RID: 1201-0400120IssueID: TS-R-BUG-112910, VCH-262Change-Id: I770ec4c5652905550b6e3f95a186198acc59e03(cherry picked from commit 18ba92538ef42be453dd8ce623b01dea1d0eb306)			

Files

log2.log	1.66 MB	2022-10-25	物联网测试组_CDTs 段小刚
----------	---------	------------	-----------------