

Figure - Bug #112914

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111045 (New): AF-V2.0-蓝牙接入兼容性

【AF】【EVT】【蓝牙】DUT蓝牙可以搜索到除了prd指定的四种设备的蓝牙(笔记本、手环、蓝牙手表等)

2022-10-25 15:22 - 物联网测试组_CDTS 段小刚

Status:	CLOSED	Start date:	2022-10-25
Priority:	Normal	Due date:	2022-10-29
Assignee:	物联网测试组_CDTS 段小刚	% Done:	50%
Category:	LC	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_update_20221115	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221023
Need_Info:		Degrated:	
Resolution:		Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	IT		
Description			
【前提条件】 1、设备已开机 2、设备上的蓝牙已被打开 【测试步骤】 1、打开蓝牙设置 2、点击—— ‘ 与新设备配对 ’ 3、等待查看搜索结果 【预期结果】 3、根据prd文件只支持 耳机、音箱、键盘、手柄；所以无法搜索到除这四种类型的设备 【实际结果】 3、能搜索到手表、笔记本 【复现率】 3/3 【Log】 log见附件			

History

- #1 - 2022-10-28 17:21 - 物联网测试组_CDTS 段小刚
- Tracker changed from 测试 Test-IT to Bug
- Severity set to Critical
- Reproducibility set to Every time
- Test Type set to IT
- Found Version set to FlatBuild_VX1_MCE_xx.xx_FSE.D.user.0.0.0.20221023.alpha
- #2 - 2022-10-28 17:25 - 物联网测试组_CDTS 段小刚
- Severity changed from Critical to Normal
- #3 - 2022-10-28 20:04 - CDTS_TEST 王成
- Target version changed from VX1_MCE_FSE_V3.0_20221030 to VX1_MCE_FSE_V3.0_update_20221115

#4 - 2022-11-07 15:44 - CD LC 陶洪普

patch

<https://dev.thundercomm.com/gerriit/c/general/platform/packages/apps/Settings/+152542>

#5 - 2022-11-10 09:58 - CD LC 陶洪普

@涂宇,

请帮忙把patch连接更新上去,谢谢!

#6 - 2022-11-10 19:23 - CD LC 涂宇

- Status changed from New to ASSIGNED

- % Done changed from 0 to 50

Hi ALL,

已提交相关patch, 正在进行Jenkins编译。

Note: 此修改根据蓝牙CoD规范进行匹配, 如果设备制造商没有按照蓝牙规范定义该设备的CoD则可能出现兼容性问题。

<https://dev.thundercomm.com/gerriit/c/general/platform/packages/apps/Settings/+161706>

<https://dev.thundercomm.com/gerriit/c/general/platform/vendor/qcom-opensource/packages/apps/Bluetooth/+161709>

<https://dev.thundercomm.com/gerriit/c/general/platform/frameworks/base/+161691>

Thanks.

#7 - 2022-11-14 01:54 - CD LC 陶洪普

<https://dev.thundercomm.com/gerriit/c/general/platform/packages/apps/Settings/+161706>

<https://dev.thundercomm.com/gerriit/c/general/platform/vendor/qcom-opensource/packages/apps/Bluetooth/+161709>

已验证。

下一步, review & merge.

#8 - 2022-11-14 21:43 - CD LC 陶洪普

- Status changed from ASSIGNED to RESOLVED

- Assignee changed from CD LC 陶洪普 to CDTS_TEST 王成

<https://dev.thundercomm.com/gerriit/c/general/platform/packages/apps/Settings/+161706>

<https://dev.thundercomm.com/gerriit/c/general/platform/vendor/qcom-opensource/packages/apps/Bluetooth/+161709>

已入库, 请使用11.15DB Verify.谢谢!

#9 - 2022-11-16 10:23 - 物联网测试组_CDTS 段小刚

- Status changed from RESOLVED to VERIFIED

- Assignee changed from CDTS_TEST 王成 to 物联网测试组_CDTS 段小刚

- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202211160534

验证版本：11.16user版本
验证结果：打开设备蓝牙进行搜索，查找不到非指定的设备蓝牙——Pass

#10 - 2022-11-16 10:24 - 物联网测试组_CDTS 段小刚
- Status changed from VERIFIED to CLOSED

该问题已修复——关闭

#11 - 2022-12-22 20:51 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
161691	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tuyu0702@thundersoft.com
LC:BT: Add API to check if the bluetooth CoD is supportedAdd API to check if the remote class of device is supported on thecurrent platform.TC-RID: 1201-0400120IssueID: TS-R-BUG-112914Change-Id: I73c6e6ebcbc1af15ff2d78644bc27123fa139657			

#12 - 2022-12-22 20:52 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
161706	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tuyu0702@thundersoft.com
LC:BT: Filter out unsupported devices from Bluetooth scan listFilter out Bluetooth devices of this device class that are notsupported by the current platform.TC-RID: 1201-0400120IssueID: TS-R-BUG-112914Change-Id: I8c5a08280ed9025f3bf7a963304541c8de7c97f7			

#13 - 2022-12-22 20:52 - CD FW-王伟

Gerrit Merge Information：

ID	Project	Branch	Uploader
161709	general/platform/vendor/qcom-opens ource/packages/apps/Bluetooth	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tuyu0702@thundersoft.com
LC:BT: Don't pairing if the remote class of divice is not supportedDon't process pairing progress if the remote class of device is notsupported on the current platform.TC-RID: 1201-0400120IssueID: TS-R-BUG-112914Change-Id: I2013442a2c0fd4868017dcd86944bef3318af894			

#14 - 2023-11-13 17:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
325448	general/platform/vendor/qcom-opensource/packages/apps/Bluetooth	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:BT: Don't pairing if the remote device is central controllerDon't process pairing progress if the remote device is central controller.TC-RID: 1201-0400120IssueID: TS-R-BUG-112914Change-Id: If0997161ad71b7027d7762724f769c28b0e03677			

#15 - 2023-11-13 17:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
326870	general/platform/vendor/qcom-opensource/packages/apps/Bluetooth	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:BT: Remove bond central controller1. Remove bond if the central controller is inactive.2. Don't connect the central controller and remove bond.TC-RID: 1201-0400120IssueID: TS-R-BUG-112914Change-Id: I10e72a61df6901cd48a76cf7939ae71a33de7892			

#16 - 2023-11-20 13:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
323018	general/platform/vendor/qcom-opensource/packages/apps/Bluetooth	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	taohp0107@thundersoft.com
LC:BT: Don't pairing if the remote device is central controllerDon't process pairing progress if the remote device is central controller.TC-RID: 1201-0400120IssueID: TS-R-BUG-112914Change-Id: If0997161ad71b7027d7762724f769c28b0e03677(cherry picked from commit fe2a277027942f3e235b5efe99375bcc273df654)			

#17 - 2023-11-20 13:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
329425	general/platform/vendor/qcom-opensource/packages/apps/Bluetooth	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com

LC:BT: Remove bond central controller1. Remove bond if the central controller is inactive.2. Don't connect the central controller and remove bond.TC-RID: 1201-0400120IssueID: TS-R-BUG-112914Change-Id: I10e72a61df6901cd48a76cf7939ae71a33de7892(cherry picked from commit c5d671d9db48d3e0e6c904541e1fc0fc1cad5161)

#18 - 2023-12-06 09:34 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
333378	general/platform/vendor/qcom-opensource/packages/apps/Bluetooth	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	taohp0107@thundersoft.com
LC:BT: Don't connect if the remote device is central controllerDon't connect if the remote device is central controller.Change-Id: I25b12fd4acda726882d51edb7760e0b26417ecccTC-RID: 1201-0400120IssueID: TS-R-BUG-112914			

#19 - 2023-12-11 13:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
334887	general/platform/vendor/qcom-opensource/packages/apps/Bluetooth	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
LC:BT: Don't connect if the remote device is central controllerDon't connect if the remote device is central controller.Change-Id: I25b12fd4acda726882d51edb7760e0b26417ecccTC-RID: 1201-0400120IssueID: TS-R-BUG-112914(cherry picked from commit c8ee63a6b11edf39da260bc44ab5e65417608dda)			

Files			
PA9ijv500t.png	109 KB	2022-10-25	物联网测试组_CDTS 段小刚
log3.log	500 KB	2022-10-25	物联网测试组_CDTS 段小刚