

Figure - Bug #112916

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 112101 (New): AF-V2.0-Launcher/SystemUI-控制中心

【AF】【EVT】【控制中心】打开设置，选中一个非网络与互联网的页面，下拉打开控制中心，点击控制中心最上面时间旁边的一小部分空白区域->设备退出控制中心，设置页面跳转到网络与互联网

2022-10-25 15:47 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-10-25
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_20221030	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.R.user.0.0.0.20221025
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.userdebug.01.00.0
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	原生的运营商逻辑引起，车载副屏不需要，因此需
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、进入设置-系统页面			
2、下拉打开控制中心			
3、点击控制中心最上面时间旁边的一小部分空白区域（具体见截图）			
【预期结果】			
3、退出控制中心，设置仍然保持在系统页面			
【实际结果】			
3、退出控制中心，设置页面跳转到网络与互联网			
【复现率】			
必现			

History

#1 - 2022-10-26 10:05 - CD TEST-方永红

测试步骤补充：

在不打开设置的情况下

在桌面或者其他应用页面，打开控制中心，点击如截图所示的区域，也会跳转到网络与互联网页面

综上所述：

在任何情况下点击截图所示的区域，都会跳转到网络与互联网页面

#2 - 2022-10-26 20:20 - CD FW 曹覃刚

- Status changed from New to RESOLVED

- Resolution changed from -- to FIXED

- Root cause set to 原生的运营商逻辑引起，车载副屏不需要，因此需要删除

代码已入库
<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+157961>

#3 - 2022-10-27 11:26 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
- Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
- % Done changed from 0 to 100
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.R.userdebug.01.00.0040.X101

#4 - 2022-10-27 11:26 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

#5 - 2022-12-22 20:46 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
157961	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings: delete click event for operator viewdelete click event for operator viewDoes not support sim card and operator informationthe network signal will be synchronized from the central controlTC-RID: 1201-0201903IssueID: TS-R-BUG-112916Change-Id: Icd3fb07f0c0cfbc9f99bfd8ee34ec1c760080584			

Files			
1546.png	154 KB	2022-10-25	CD TEST-方永红
1546.txt	3.84 MB	2022-10-25	CD TEST-方永红