

Figure - Bug #113026

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111050 (New): AF-V2.0-Launcher/SystemUI-桌面管理

【AF】【EVT】【桌面管理】将第三方应用移动到dock栏中，长按删除，dock栏剩下的三个应用不会自适应排列

2022-10-26 15:36 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-10-26
Priority:	Normal	Due date:	2022-11-04
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_update_20221115	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20221026
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.20221028
Severity:	Normal	Fixed Version:	2022-10-28
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	IT		
Description			
【前提条件】 1、设备已开机 2、安装一个第三方应用 【测试步骤】 1、将安装的第三方应用替换一个dock栏中的应用（任意位置） 2、长按第三方应用，在弹出框中选择卸载 3、成功卸载该应用，观察dock栏布局 【预期结果】 3、dock栏剩下的三个应用与dock栏上下端距离一致，中间间隔一致 【实际结果】 3、dock栏剩下的三个应用不会自适应排列，呈现空一个应用图标的状态（如图） 长按或拖动剩下图标中的任意一个，dock栏恢复自适应排列 【复现率】 必现 ps:dock中一共只有2或者3个应用也有此现象，此处以4个为例			

History

#1 - 2022-10-26 15:40 - CD APP-王营

- Status changed from New to ASSIGNED
- Assignee changed from CD APP-王营 to CD APP-李德盛

#2 - 2022-10-27 15:14 - CDTs-TEST 周婷

- Due date set to 2022-11-04
- Target version changed from VX1_MCE_FSE_V3.0_20221030 to VX1_MCE_FSE_V3.0_update_20221115

#3 - 2022-10-27 16:35 - CD APP-李德盛

- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No

- Fixed Version set to 2022-10-28
- Root cause set to 编码问题

■ Current conclusion

dock布局未更新

■ My analysis

删除后需要刷新dock

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Launcher3/+/158434>

#4 - 2022-10-27 17:19 - CD APP-李德盛

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-李德盛 to CD TEST-方永红

#5 - 2022-10-28 11:05 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202210280435

10.28 验证通过

#6 - 2022-10-28 11:06 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#7 - 2022-12-22 20:47 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
158434	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	jjiao.li_a@thundersoft.com
FW:Launcher: Fix hotseat layout not update after uninstall1. Fixed hotseat layout not being updated after uninstalling app.TC-RID: 1201-0205303IssueID: TS-R-BUG-113026Change-Id: I12d293f9072f13386083be99df28bf43fca9cb8b			

Files

卸载第三方应用.png	227 KB	2022-10-26	CD TEST-方永红
1534.txt	961 KB	2022-10-26	CD TEST-方永红