

Figure - Bug #113043

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI---Setting

【AF】 【EVT】 【设置】系统-语言与输入法-语言-添加语言，添加一个语言后，一级列表选中态消失

2022-10-26 16:48 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-10-26
Priority:	Normal	Due date:	2022-11-04
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_update_20221115	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20221026
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	IT		

Description
【前提条件】 1、设备已开机 【测试步骤】 1、进入设置-系统-语言与输入法-语言页面 2、点击页面中的添加语言 3、随机选择一个语言添加，返回到语言页面 【预期结果】 3、页面正常显示，左侧的一级列表-系统呈选中态 【实际结果】 3、一级列表选中态消失，左侧列表有闪一下的现象 【复现率】 必现

History

#1 - 2022-10-27 15:26 - CDTs-TEST 周婷

- Due date set to 2022-11-04

- Target version changed from VX1_MCE_FSE_V3.0_20221030 to VX1_MCE_FSE_V3.0_update_20221115

#2 - 2022-10-28 09:55 - CD AF-陈羽杰

- Status changed from New to ASSIGNED

- % Done changed from 0 to 100

#3 - 2022-10-31 10:48 - CD FW 曹覃刚

- Assignee changed from CD AF-陈羽杰 to CD FW-程天颖

#4 - 2022-10-31 11:07 - CD AF-陈羽杰

- Status changed from ASSIGNED to RESOLVED

- Assignee changed from CD FW-程天颖 to CD TEST-方永红

- Resolution changed from -- to FIXED

- Degrated changed from -- to No

- Root cause set to 编码问题

■ Current conclusion

本地已修复并验证。

■ My analysis

由于原生代码，选择语言会跳转到全屏，导致一级菜单选中状态失效。

■ Submit URL

下一步做什么，或者提交是什么，写明验证步骤<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+158461>

#5 - 2022-10-31 18:48 - CD AF-陈羽杰

- Assignee changed from CD TEST-方永红 to CD AF-陈羽杰

#6 - 2022-10-31 18:48 - CD AF-陈羽杰

- Status changed from RESOLVED to ASSIGNED

#7 - 2022-11-02 16:50 - CD AF-陈羽杰

- Status changed from ASSIGNED to NEED_INFO

- Assignee changed from CD AF-陈羽杰 to CD TEST-方永红

■ Current conclusion

本地已修复验证

■ My analysis

选择语言后，settings重走生命周期导致

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+159360>

#8 - 2022-11-02 16:54 - CD AF-陈羽杰

- Status changed from NEED_INFO to RESOLVED

#9 - 2022-11-03 11:38 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

11.3 验证关闭

#10 - 2022-11-03 11:38 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#11 - 2022-12-22 20:47 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
158461	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	yujie.chen@thundersoft.com

AF:Settings: Modify language select1.Modify the language selection to the secondary page2.fix language selection first menu status exceptionTC-RID: 1201-0201809IssueID: TS-R-BUG-113043Change-Id: I6ea882a7158becc6d4f2fb38318e7f32e69905b7

#12 - 2022-12-22 20:48 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
159360	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	yujie.chen@thundersoft.com
AF:Settings: Add Language remove function1.Add Language remove function2.fix add language first menu unselect exceptionTC-RID: 1201-0201809IssueID: TS-R-BUG-113043Change-Id: Ia7273aa6819f530b597ffe8d8714190216e4938			

Files

1647.txt	1.81 MB	2022-10-26	CD TEST-方永红
Phone-STS40X190122 2022-10-26 16-47-35.mp4	11.2 MB	2022-10-26	CD TEST-方永红