

Figure - Bug #113047

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111050 (New): AF-V2.0-Launcher/SystemUI-桌面管理

【AF】【EVT】【桌面管理】向dock栏里面添加1*1的快捷方式，会出现覆盖原有应用或者无法添加的现象

2022-10-26 17:52 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-10-26
Priority:	Normal	Due date:	2022-11-04
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_update_20221115	Found Version:	FlatBuild_VX1_MCE_xx.xx_FSE.D.userdebug.0.0.0.20221026
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.20221028
Severity:	Normal	Fixed Version:	2022-10-28
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	IT		

Description	
【前提条件】 1、设备已开机 【测试步骤】 1、将dock栏里面的应用移除一个（dock栏里目前有三个应用） 2、长按桌面空白处进入微件添加模式 3、向dock栏里面添加1*1的快捷方式 4、将dock栏里面的应用移除一两个（dock栏里目前有两个应用） 5、长按桌面空白处进入微件添加模式 6、向dock栏里面添加1*1的快捷方式 【预期结果】 3、成功添加选择的快捷方式 6、成功添加选择的快捷方式 【实际结果】 3、添加的快捷方式覆盖了最近的应用图标 （后续动作： 在dock栏里面拖动一下会解除覆盖，快捷方式消失 or直接将其拖到桌面上，被覆盖的应用没有办法恢复） 6：快捷方式无法被添加	

History

#1 - 2022-10-27 10:57 - CD APP-王营
- Status changed from New to ASSIGNED
- Assignee changed from CD APP- 王营 to CD APP-李德盛
#2 - 2022-10-27 15:13 - CDTS-TEST 周婷
- Due date set to 2022-11-04
- Target version changed from VX1_MCE_FSE_V3.0_20221030 to VX1_MCE_FSE_V3.0_update_20221115
#3 - 2022-10-27 16:46 - CD APP-李德盛
- % Done changed from 0 to 100

- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2022-10-28
- Root cause set to 编码问题

■ Current conclusion

图标位置计算错误

■ My analysis

需要对dock进行重排序，预留新图标位置

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Launcher3/+/158435>

#4 - 2022-10-27 17:20 - CD APP-李德盛

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-李德盛 to CD TEST-方永红

#5 - 2022-10-28 11:07 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202210280435

10.28 验证关闭

#6 - 2022-10-28 11:07 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#7 - 2022-12-22 20:47 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
158435	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	jjiao.li_a@thundersoft.com
FW:Launcher: Fix fail to add shortcut to hotseat1. Fix fail to add shortcut to hotseat.TC-RID: 1201-0205303IssueID: TS-R-BUG-113047Change-Id: Idd3741a6967fba300aedfe9a03680ba37f1f8226			

Files

1747.txt	879 KB	2022-10-26	CD TEST-方永红
Phone-STs40X190122 2022-10-26 17-50-03.zip	27.1 MB	2022-10-26	CD TEST-方永红