

Figure - 开发 Dev #113216

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 110125 (New): 【MK】【BSP】管理总票

开发 Dev # 110643 (进行中 In Progress): 【MK】【006】【Ethernet】主任务

【MK】【006】【Ethernet】【TC-RID: 1201-0400601】DTC故障诊断

2022-10-27 21:19 - CD BSP-唐金泽

Status:	保留中 Pending	Start date:	2022-10-27
Priority:	Normal	Due date:	
Assignee:	CD BSP-唐金泽	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Description			
DTC故障诊断的支持			
PM需明确异常范围			

History

#1 - 2022-10-31 20:50 - CD BSP-唐金泽

- Status changed from 未着手 Not Started to 保留中 Pending

通过DoIP协议进行实现，暂时pending

#2 - 2023-01-11 16:17 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
175554	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wenliang.peng@thundersoft.com
BSP:Ethernet: DTC fault diagnosisSet 5S as the display cycle to print the Ethernet link status and signal quality.TC-RID: 0301-0400601IssueID: TS-R-DF-113216Change-Id: If1ea1819ff9aa224d84e6f05b712f2c0cf05d6e0			

#3 - 2023-01-16 19:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
176867	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wenliang.peng@thundersoft.com
BSP:Ethernet: DTC fault diagnosisTo continue.The abnormal state of ethernet has been specified clearly.The log of the error message is printed when link=0, or when sqi<13.TC-RID: 0301-0400601IssueID: TS-R-DF-113216Change-Id: I88ca29dc6515344648907b1c61830b248a0dec0e			

Gerrit Merge Information :

ID	Project	Branch	Uploader
195505	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	yepeng0322@thundersoft.com
BSP:Ethernet: Add ethernet DTC Diagnostics error codeAdd ethernet DTC Diagnostics error codeTC-RID: 0301-0400601IssueID: TS-R-DF-113216Change-Id: I61760af10b557a1c0cd8c387c333e7b2cc849145			

Files

Fiugre_DTC.jpg	315 KB	2022-10-27	CD BSP-唐金泽
----------------	--------	------------	------------