

Figure - Bug #113383

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】在设置中心里进入的网络与互联网的——热点和网络共享界面后，返回后，其热点开关UI还在界面上

2022-10-31 17:39 - 物联网测试组_CDTs 段小刚

Status:	CLOSED	Start date:	2022-10-31
Priority:	Normal	Due date:	2022-11-07
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_update_20221115	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.userdebug.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	DUPLICATE	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	该问题与113362属于同源问题，已经修复。
Test Type:	IT		

Description
【前提条件】 1、设备已开机 【测试步骤】 1、打开设置 2、点击“网络与互联网”界面>“热点和网络共享” 3、再点击返回 4、观察页面显示 【预期结果】 4、正常显示切换过去的页面 【实际结果】 4、其热点共享信息的开关按钮仍保留在切换后的页面上 【复现率】 必现——5/5 【Log】 见附件 PS：与Bug #113362类似

History

- #1 - 2022-11-01 10:35 - CD AF-陈羽杰
- Assignee changed from CD AF-陈羽杰 to CD FW-程天颖
- #2 - 2022-11-07 15:02 - CD AF-陈羽杰
- Status changed from New to ASSIGNED
- #3 - 2022-11-07 15:07 - CD AF-陈羽杰
- Due date set to 2022-11-07
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-程天颖 to CD TEST-方永红

- % Done changed from 0 to 100
- Resolution changed from -- to DUPLICATE
- Degrated changed from -- to No
- Root cause set to 该问题与113362属于同源问题，已经修复。

■ Current conclusion

已修复

■ My analysis

该问题与113362属于同源问题，已经修复。

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+/159687>

#4 - 2022-11-07 15:12 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202211050252

11.7 验证通过

#5 - 2022-11-07 15:13 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
screen-20221028-093152.mp4	9.3 MB	2022-10-31	物联网测试组_CDTS 段小刚