

Figure - Bug #113431

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】<长按设置图标添加的快捷方式>与<进入桌面编辑添加微件添加的快捷方式>不互通且存在互斥现象

2022-11-01 11:12 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-11-01
Priority:	High	Due date:	2022-11-08
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V3.0_update_20221115	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0042.X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	编码问题
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、长按设置图标在弹出框中随意添加一个快捷方式（如电池）			
2、长按桌面空白处进入桌面编辑模式			
3、点击添加微件			
4、添加设置的<电池>快捷方式			
5、观察两个快捷方式的图标			
6、分别使用两个快捷方式			
【预期结果】			
5、相同的快捷方式图标一致			
6、两个快捷方式都可正常使用			
【实际结果】			
5、相同的快捷方式图标有差异			
6、不能成功打开快捷方式且出现 ”未安装应用“ 的提示			

History

#1 - 2022-11-02 18:00 - CD AF-陈羽杰

- Status changed from New to ASSIGNED

#2 - 2022-11-08 10:33 - CD FW-王伟

除了本身的问题之外，我们为什么可以添加电池的快捷方式？请去掉此快捷方式。

#3 - 2022-11-08 17:24 - CD AF-陈羽杰

- Due date set to 2022-11-08

- Status changed from ASSIGNED to RESOLVED

- Assignee changed from CD AF-陈羽杰 to CD TEST-方永红

- % Done changed from 0 to 100

- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Root cause set to 编码问题

■ Current conclusion

本地验证

■ My analysis

经过讨论，去掉了长按settings，添加widgets，去掉部分launcher中可以选择的widgets

■ Next action

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+/160997>

#4 - 2022-11-09 10:24 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202211090616

11.9
已经不能通过长按设置添加微件
launcher中部分微件选项也被移除
验证通过

#5 - 2022-11-09 10:24 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#6 - 2022-12-22 20:51 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
160997	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	yujie.chen@thundersoft.com
AF:Settings: Fix Settings widgets bug1.cut crop long click Settings add widgets2.cut crop PowerUsage,LocationSettings,NotificationStation,AccessibilitySettings,DataUsage,Account,Do Not Disturb Mode widgetsTC-RID: 1201-0201813IssueID: TS-R-BUG-113431Change-Id: Ib32c3ab12dc788c3256096f9711f88f05fa3a759			

Files

电池.png	219 KB	2022-11-01	CD TEST-方永红
123333.png	221 KB	2022-11-01	CD TEST-方永红