

Figure - Bug #113768

【Figure】 【EVT2】 【RF】 RSSI测试fail

2022-11-07 17:36 - SZ HW Test-曾小文

Status:	CLOSED	Start date:	2022-11-07
Priority:	Normal	Due date:	
Assignee:	项目二组_SD3 邓瑞林	% Done:	0%
Category:	其他硬件bug	Estimated time:	0.00 hour
Target version:	依赖硬件的bugList	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.userdebug.01.00.0
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Major	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	Release Test		
Description			
RSSI测试fail			

History

#1 - 2022-11-07 17:39 - SZ HW Test-曾小文

- Assignee changed from IOT-SP-TEST 刘颖 to SZ-硬件二组_SD3 王苗

EVT1是改了匹配，是手焊的，EVT2是贴片的，有偏差

#2 - 2022-11-07 18:15 - IOT-SP-TEST 刘颖

- Assignee changed from SZ-硬件二组_SD3 王苗 to 硬件二组_SD3 陈澍锴

- Target version set to 依赖硬件的bugList

#3 - 2022-11-15 10:25 - 硬件二组_SD3 陈澍锴

- File Figure_EVT2_WIFI_BDF_20221108.rar added

#4 - 2022-11-21 19:11 - 硬件二组_SD3 陈澍锴

- Assignee changed from 硬件二组_SD3 陈澍锴 to 项目二组_SD3 邓瑞林

#5 - 2022-11-25 13:55 - SZ HW Test-曾小文

- Status changed from New to RESOLVED

#6 - 2022-11-25 13:56 - SZ HW Test-曾小文

- Status changed from RESOLVED to VERIFIED

FlatBuild_HH_VX1_MCE_FSE.M.R.userdebug.01.00.0048.X101 复测PASS,硬件更新了RF BIN文件

#7 - 2022-11-25 13:56 - SZ HW Test-曾小文

- Status changed from VERIFIED to CLOSED

#8 - 2022-12-27 16:37 - SZ HW Test-曾小文

- Category set to 其他硬件bug

Files

Figure_EVT2_WIFI_BDF_20221108.rar	105 KB	2022-11-15	硬件二组_SD3 陈澍锴
-----------------------------------	--------	------------	--------------