

Figure - Bug #113900

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111049 (New): AF-V2.0-副屏遥控器

【AF】【EVT】【副屏遥控器】遥控器进行音量调节及音量查询时，无法正确显示音量数值

2022-11-11 10:44 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-11-11
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Normal	Fixed Version:	2022-11-15
Reproducibility:	Every time	Root cause:	Audio 系统 MUSIC 最大音量由原来的 15 调整为 39
Test Type:	IT		
Description			
【前提条件】 1、设备已开机			
【测试步骤】 1、手机与设备连接同一WIFI 2、在手机中利用遥控器连接设备 3、进行音量调节及音量查询操作			
【预期结果】 3、点击相应调节按钮后，遥控器正确当前音量数值等信息			
【实际结果】 3、音量超过15时仍可加减，此时遥控器音量加减、查询，显示的值不正确 连接蓝牙耳机时第一次唤出音量条，音量调节失效			

History

- #1 - 2022-11-11 10:49 - CD FW 曹覃刚
- Status changed from New to ASSIGNED
- Assignee changed from CD FW 曹覃刚 to CD FW-廖涛

请帮忙分析下这个问题

- #2 - 2022-11-11 14:38 - CD FW-廖涛
- Assignee changed from CD FW-廖涛 to CD MM陈海波

- #3 - 2022-11-11 14:42 - CD TEST-方永红
- Description updated

- #4 - 2022-11-11 14:56 - CD FW-廖涛
- Assignee changed from CD MM陈海波 to CD FW-廖涛

- #5 - 2022-11-11 16:19 - CD FW-廖涛

- Status changed from ASSIGNED to RESOLVED
- % Done changed from 0 to 100
- Degrated changed from -- to No
- Fixed Version set to 2022-11-15
- Root cause set to Audio 系统 MUSIC 最大音量由原来的 15 调整为 39, 遥控器没有做对应的适配

连接蓝牙后，首次设置音量浮窗不能操作的问题，经分析不是遥控器问题，可单独提一个 BUG 给 Audio 开发。

提交：
<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/RemoteControlClients/+/162024>
<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/RemoteControlServer/+/162000>

#6 - 2022-11-11 18:01 - CD FW-廖涛
- Assignee changed from CD FW-廖涛 to CD TEST-方永红

#7 - 2022-11-14 10:11 - CD FW-廖涛
- Resolution changed from -- to FIXED

#8 - 2022-11-14 10:43 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202211120244

11.14 验证通过

#9 - 2022-11-14 10:43 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

#10 - 2022-12-22 20:52 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
162000	general/platform/vendor/thundercomm/apps/RemoteControlServer	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Service - Volume max value set to 39.TC-RID: 1201-0206001IssueID: TS-R-BUG-113900Change-Id: Id16ae6c48340bc8b0e417753ec09868d8aa4c042			

#11 - 2022-12-22 20:52 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
162068	general/platform/vendor/thundercomm/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Client(Android) - Volume max value set to 39.TC-RID: 1201-0206002IssueID: TS-R-BUG-113900Change-Id: I0bbc48a0677d67a8dababad5feb0aa6b214d9656			

Files

tlog_xxx_1111045155.tar.gz	969 KB	2022-11-11	CD TEST-方永红
logcat.txt	3.08 MB	2022-11-11	CD TEST-方永红