

Figure - 需求 Requirement #113979

【BSP】 【Security】 替换Google 默认AVB Key

2022-11-15 19:15 - CDTs-RD6-FW1 孙逊

Status:	New	Start date:	2022-11-15
Priority:	Normal	Due date:	
Assignee:	CDTS-RD6-FW1 孙逊	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Description			
Related issues:			
Related to Figure - 开发 Dev # 112372: 【MK】 【008】 【BOOT】 【TC-R...			进行中 In Progress2022-11-022022-11-26

History

#1 - 2022-12-22 20:51 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
161172	general/platform/external/avb	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiongfeng0704@thundersoft.com
BSP:Security: Replace the Android Verified Boot KeyUse avbtool to generate the private key and replace Google's original keyTC-RID: 1201-0100704IssueID: TS-R-DF-113979Change-Id: I2faf785d2d0b6a464d1e4b0d927403bcbe5af3a4			

#2 - 2022-12-22 20:51 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
161175	general/abl/tianocore/edk2	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xiongfeng0704@thundersoft.com
BSP:Security: Replace Google's default OEM public keyUse avbtool to generate the corresponding OEM public key and replace Google's default keyTC-RID: 1201-0100704IssueID: TS-R-DF-113979Change-Id: I0d596efb943a6b9953d31ccc395f5ff63fb37564			

#3 - 2022-12-22 20:51 - CD FW-王伟

Gerrit Merge Information :

ID	Project	Branch	Uploader
161178	general/platform/external/avb	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xiongfeng0704@thundersoft.com
BSP:Security: Replace the Android Verified Boot KeyUse avbtool to generate the private key and replace Google's original keyTC-RID: 1201-0100704IssueID: TS-R-DF-113979Change-Id: Ib1585960e29dcf450dab5ced66e42efd7bf9b26c			

#4 - 2023-04-14 21:01 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
193065	general/platform/external/avb	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	shuang.li_a@thundersoft.com
BSP:Security: Replace the AVB key provided by GoogleReplace the Google AVB private key on the Qssi sideTC-RID: 1201-0100704IssueID: TS-R-DF-113979Change-Id: I0e9ec3c5f867f5f8bd6c04333a17aca0665d3564			

#5 - 2023-04-14 21:02 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
192865	general/platform/external/avb	Pre_figure_turbox-c2130c-la1.1-vendor-dev	shuang.li_a@thundersoft.com
BSP:Security: Replace the AVB key provided by GoogleReplace the Google AVB private key on the Vendor sideTC-RID: 1201-0100704IssueID: TS-R-DF-113979Change-Id: I0e9ec3c5f867f5f8bd6c04333a17aca0665d3564			

#6 - 2023-04-14 21:02 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
192866	general/abl/tianocore/edk2	Pre_figure_turbox-c2130c-la1.1-vendor-dev	shuang.li_a@thundersoft.com
BSP:Security: Replace the AVB key provided by GoogleReplace Google AVB public keyTC-RID: 1201-0100704IssueID: TS-R-DF-113979Change-Id: Id873fd8dae52c14d70d87950a40fd2f4235052e9			

#7 - 2023-04-23 15:46 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
195081	general/abl/tianocore/edk2	Pre_figure_turbox-c2130c-la1.1-vendor-dev	shuang.li_a@thundersoft.com
BSP:Security: Set the status of the version to Lock/Unlock by defaultThe User version defaults to the Lock stateThe Userdebug version defaults to the Unlock stateTC-RID: 1201-0100704IssueID: TS-R-DF-113979Change-Id: Ie183db537ed559ecb44b874ee9ff4fb99e582ce1			

Gerrit Merge Information :

ID	Project	Branch	Uploader
195824	general/abl/tianocore/edk2	Pre_figure_turbox-c2130c-la1.1-vendor-dev	shuang.li_a@thundersoft.com
Revert BSP:Security: Set the status of the version to Lock/Unlock by defaultThis reverts commit 8620227e359b875150ed57776a9673c019d4b644.Reason for revert: And the previous bug fix patch conflictTC-RID: 1201-0100704IssueID: TS-R-DF-113979Change-Id: I1b4bde7180fdb459aad8837f08147538fac71ecc			