

Figure - 需求 Requirement #113980

【BSP】 【Security】 替换Google 默认 APP 签名 Key

2022-11-15 19:15 - CDTs-RD6-FW1 孙逊

Status:	New	Start date:	2022-11-15
Priority:	Normal	Due date:	
Assignee:	CDTS-RD6-FW1 孙逊	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:			
Description			
Related issues:			
Related to Figure - 开发 Dev # 112372: 【MK】 【008】 【BOOT】 【TC-R...			进行中 In Progress2022-11-022022-11-26

History

#1 - 2022-12-13 19:10 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
166672	general/platform/build	Pre_figure_turbox-c2130c-la1.1-vendor-dev	tangjz1204@thundersoft.com
Revert BSP:Security: Replace the app keyThis reverts commit 43755b9003875136eb085660c837c9169a439ee1.Reason for revert: revert app and release key in V4.0 releaseTC-RID: 1201-0100704IssueID: TS-R-DF-113980Change-Id: I456106b9ec1205a5a7aa26f78c75ec7ec8637ac0			

#2 - 2022-12-13 19:10 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
166671	general/platform/build	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tangjz1204@thundersoft.com
Revert BSP:Security: Replace the app keyThis reverts commit f021182fb1f40871c04f93f6e3475d8abebcda5c.Reason for revert: revert app and release key in V4.0 releaseTC-RID: 1201-0100704IssueID: TS-R-DF-113980Change-Id: Idd77cafd9d649d93dc032ff77375d79cdee9bb36			

#3 - 2022-12-13 20:35 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
170040	general/platform/build	Pre_figure_turbox-c2130c-la1.1-qssi12-release_v4.5	tangjz1204@thundersoft.com

Revert BSP:Security: Replace the app keyThis reverts commit f021182fb1f40871c04f93f6e3475d8abebcda5c.Reason for revert: revert app and release key in V4.0
releaseTC-RID: 1201-0100704IssueID: TS-R-DF-113980Change-Id: Idd77cafd9d649d93dc032ff77375d79cdee9bb36(cherry picked from commit
2c42bd8fd13edc77cd8be668bf0b03bddacc5e7f)

#4 - 2022-12-13 20:35 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
169979	general/platform/build	Pre_figure_turbox-c2130c-la1.1-vendor-release_v4.5	tangjz1204@thundersoft.com
Revert BSP:Security: Replace the app keyThis reverts commit 43755b9003875136eb085660c837c9169a439ee1.Reason for revert: revert app and release key in V4.0 releaseTC-RID: 1201-0100704IssueID: TS-R-DF-113980Change-Id: I456106b9ec1205a5a7aa26f78c75ec7ec8637ac0(cherry picked from commit 2afe4cdfbda221f5a369dea81b8036d235d43175)			

#5 - 2022-12-19 11:48 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
170965	general/platform/build	Pre_figure_turbox-c2130c-la1.1-vendor-ftm-dvt1	tangjz1204@thundersoft.com
Revert BSP:Security: Replace the app keyThis reverts commit 43755b9003875136eb085660c837c9169a439ee1.Reason for revert: revert app and release key in V4.0 releaseTC-RID: 1201-0100704IssueID: TS-R-DF-113980Change-Id: I456106b9ec1205a5a7aa26f78c75ec7ec8637ac0(cherry picked from commit 2afe4cdfbda221f5a369dea81b8036d235d43175)(cherry picked from commit f72be5994ef3433896fd6ed72befe8adfd999d98)			

#6 - 2022-12-19 11:49 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
170966	general/platform/build	Pre_figure_turbox-c2130c-la1.1-qssi12-ftm-dvt1	tangjz1204@thundersoft.com
Revert BSP:Security: Replace the app keyThis reverts commit f021182fb1f40871c04f93f6e3475d8abebcda5c.Reason for revert: revert app and release key in V4.0 releaseTC-RID: 1201-0100704IssueID: TS-R-DF-113980Change-Id: Idd77cafd9d649d93dc032ff77375d79cdee9bb36(cherry picked from commit 2c42bd8fd13edc77cd8be668bf0b03bddacc5e7f)(cherry picked from commit 52601c53662c1b2252c569d264fc4debb256ed0e)			

#7 - 2023-04-24 11:35 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
189607	general/platform/system/update_engine	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	yepeng0322@thundersoft.com
BSP:FOTA: Skip payload_verifier for change key.Skip payload_verifier for change key.TC-RID: 1201-0100801IssueID: TS-R-DF-113980Change-Id: I5f597331c087170e6d95b07d1104cf2edb6247e1			

#8 - 2023-06-20 19:28 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
193222	general/platform/build	Pre_figure_turbox-c2130c-la1.1-vendor-dev	yepeng0322@thundersoft.com
BSP:Security: Change default key to releasekey.TC-RID: 1201-0100801IssueID: TS-R-DF-113980Change-Id: I403b06d4825bac093884a911759fd32e73704be6			

#9 - 2023-06-20 19:28 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
192815	general/platform/build	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangxl0510@thundersoft.com
Revert Revert BSP:Security: Replace the app keyThis reverts commit 2afe4cdfbda221f5a369dea81b8036d235d43175.Reason for revert: add app keyTC-RID: 1201-0100801IssueID: TS-R-DF-113980Change-Id: I511cd77b5e55be6f56a3c91e882900c353f9de0d			

#10 - 2023-06-20 19:28 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
189802	general/platform/build	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	yepeng0322@thundersoft.com
BSP:Security:Change default key to releasekey.TC-RID: 1201-0100801IssueID: TS-R-DF-113980Change-Id: Iaf3862af6416741f60d6cbb4cc48830909a5f754			

#11 - 2023-06-20 19:28 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader

192814	general/platform/build	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangxl0510@thundersoft.com
Revert Revert BSP:Security: Replace the app keyThis reverts commit 2c42bd8fd13edc77cd8be668bf0b03bddacc5e7f.Reason for revert: add app keyTC-RID: 1201-0100801IssueID: TS-R-DF-113980Change-Id: I3c170051a0ada117eb501f6eae472218ba9303d5			

#12 - 2023-06-20 19:53 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
199158	general/platform/system/update_engine	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangxl0510@thundersoft.com
Revert BSP:FOTA: Skip payload_verifier for change key.This reverts commit 40141021094e1509acc1bee0a9029d4f468cd3e0.Reason for revert: enable payload verifier.TC-RID: 1201-0100801IssueID: TS-R-DF-113980Change-Id: I38c932d0f971b243ab932cf5b18a2e077e3847e1			

#13 - 2023-06-25 21:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209667	general/platform/build	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
BSP:Security:Change default key to releasekey.TC-RID: 1201-0100801IssueID: TS-R-DF-113980Change-Id: Iaf3862af6416741f60d6cbb4cc48830909a5f754(cherry picked from commit c0d08e4bdff23fc1cd238fb6f7472937caa43827)			

#14 - 2023-06-25 21:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209668	general/platform/build	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
Revert Revert BSP:Security: Replace the app keyThis reverts commit 2c42bd8fd13edc77cd8be668bf0b03bddacc5e7f.Reason for revert: add app keyTC-RID: 1201-0100801IssueID: TS-R-DF-113980Change-Id: I3c170051a0ada117eb501f6eae472218ba9303d5(cherry picked from commit 439e08969da743a45ccba50c1489f59d450362c7)			

#15 - 2023-06-25 21:39 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
209669	general/platform/system/update_engine	Pre_figure_turbox-c2130c-la1.1-qssi12-release_sorp	wangxl0510@thundersoft.com
Revert BSP:FOTA: Skip payload_verifier for change key.This reverts commit 40141021094e1509acc1bee0a9029d4f468cd3e0.Reason for revert: enable payload verifier.TC-RID: 1201-0100801IssueID: TS-R-DF-113980Change-Id: I38c932d0f971b243ab932cf5b18a2e077e3847e1(cherry picked from commit 81bd862490482117e0d43f646994ccb52f1dc267)			

#16 - 2023-06-25 21:57 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
209687	general/platform/build	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
BSP:Security: Change default key to releasekey.TC-RID: 1201-0100801IssueID: TS-R-DF-113980Change-Id: I403b06d4825bac093884a911759fd32e73704be6(cherry picked from commit 0f479031278a062386b241a15e44d87e030894b5)			

#17 - 2023-06-25 21:57 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
209688	general/platform/build	Pre_figure_turbox-c2130c-la1.1-vendor-release_sorp	wangxl0510@thundersoft.com
Revert Revert BSP:Security: Replace the app keyThis reverts commit 2afe4cdfbda221f5a369dea81b8036d235d43175.Reason for revert: add app keyTC-RID: 1201-0100801IssueID: TS-R-DF-113980Change-Id: I511cd77b5e55be6f56a3c91e882900c353f9de0d(cherry picked from commit c58cd6def470768953150c2c20bc331ee8352fc8)			

#18 - 2023-11-24 17:34 - IoT scm**Gerrit Merge Information :**

ID	Project	Branch	Uploader
330955	general/platform/build_repo	HylandPOC-c6490-la3.0-qssi13-dev	wangdq0907@thundersoft.com

BSP-SECURITY:Add temp releasekey for solving user build errorFAILED: ninja: 'build/make/target/product/security/releasekey.x509.pem',needed by 'out/target/product/qssi/obj/ETC/otacerts_intermediates/otacerts.zip', missingTC-RID: 1201-0100801IssueID: TS-R-DF-113980Change-Id: I43cbb5799bc9a11c40577e931735838f73781753

#19 - 2023-11-24 17:34 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
330952	general/platform/build_repo	HylandPOC-c6490-la3.0-vendor-dev	wangdq0907@thundersoft.com
BSP-SECURITY:Add temp releasekey for solving user build errorFAILED: ninja: 'build/make/target/product/security/releasekey.x509.pem',needed by 'out/target/product/qssi/obj/ETC/otacerts_intermediates/otacerts.zip', missingTC-RID: 1201-0100801IssueID: TS-R-DF-113980Change-Id: Ic936908e281bccbfc746f0a0da0eb17db6256c9a			

#20 - 2023-12-27 17:00 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
332683	general/platform/build_repo	HylandPOC-c6490-la3.0-vendor-dev	wangdq0907@thundersoft.com
BSP-SECURITY: Sign builds for releaseTC-RID: 1201-0100801IssueID: TS-R-DF-113980Change-Id: I64a50b434b65f115321ebce341708a66072dc4d4			

#21 - 2023-12-27 17:01 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
332686	general/platform/build_repo	HylandPOC-c6490-la3.0-qssi13-dev	wangdq0907@thundersoft.com
BSP-SECURITY: Sign builds for releaseTC-RID: 1201-0100801IssueID: TS-R-DF-113980Change-Id: I64a50b434b65f115321ebce341708a66072dc4d4			