

Figure - Bug #114082

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】进入恢复出厂设置的最后一次确认页面时，一级列表的选中态消失

2022-11-22 15:47 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-11-22
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0022.X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Normal	Fixed Version:	2022-11-25
Reproducibility:	Every time	Root cause:	页面跳转方式及对 ActionBar 的处理导致的问题
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、设置-系统			
2、点击重置选项-清楚所有数据			
3、进入恢复出厂设置的最后一次确认页面			
【预期结果】			
3、一级列表保持选中态			
【实际结果】			
3、一级列表的选中态消失，从而倒是点击返回按钮会直接退出设置			
【复现率】			
5/5			

History

- #1 - 2022-11-24 17:09 - CD FW-廖涛
- Status changed from New to RESOLVED
 - Assignee changed from CD FW-廖涛 to CD TEST-方永红
 - % Done changed from 0 to 100
 - Resolution changed from -- to FIXED
 - Degrated changed from -- to No
 - Fixed Version set to 2022-11-25
 - Root cause set to 页面跳转方式及对 ActionBar 的处理导致的问题

■ Current conclusion

已处理，提交：<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+164606>

■ My analysis

因为左右分隔展示处理导致的页面跳转及 ActionBar 丢失问题所引起的 BUG。

■ Next action

测试验证

#2 - 2022-11-28 10:46 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202211260343

11.28

验证通过

#3 - 2022-11-28 10:46 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
恢复.png	119 KB	2022-11-22	CD TEST-方永红