

Figure - 开发 Dev #114187

开发 Dev # 110122 (New): 【MK】管理总票
开发 Dev # 110125 (New): 【MK】【BSP】管理总票
开发 Dev # 110638 (解决 Resolved): 【MK】【008】【BOOT】主任务
【MK】【008】【BOOT】【TC-RID: 1201-0100803】创建工厂分支
2022-11-29 10:50 - CD BSP-唐金泽

Status:	进行中 In Progress	Start date:	2022-11-29
Priority:	Normal	Due date:	2022-12-15
Assignee:	CD TPM-王祥林	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:	VC1_FSE_0082_20230314		
Description			
产测版本，初步说明： 1.基于V4.0交付内容拉取分支； 2.去除开机启动动画； 3.使用user版本内核config文件（启动时间加快）； 4.adb和串口功能启用； 5.TSNV功能标志位使用OK； 6.获取MCU版本接口功能OK；			

History

#1 - 2023-03-10 11:07 - CD TPM-王祥林
- Assignee changed from CD BSP-唐金泽 to CD TPM-王祥林

新的ftm分支拉出来了
Pre_figure_turbox-c2130c-la1.1-vendor-ftm_v0081.xml
Pre_figure_turbox-c2130c-la1.1-qssi12-ftm_v0081.xml
需要检查是否需要合入的提交如下：
<https://thundersoft.feishu.cn/sheets/shtcnjG9L0jr3Wizd2YlwQUeDDh>

#2 - 2023-03-10 11:07 - CD TPM-王祥林
- Target version changed from VX1_MCE_FSE_V4.0_20221128 to VC1_FSE_0082_20230314

#3 - 2023-03-10 11:43 - CD BSP-杜磊

BSP相关修改如下：
https://dev.thundercomm.com/gerrit/q/branch:Pre_figure_turbox-c2130c-la1.1-vendor-ftm_v0081

#4 - 2023-03-10 13:38 - IoT scm

Gerrit Merge Information：

ID	Project	Branch	Uploader
186791	general/vendor/thundercomm/producs/figure	Pre_figure_turbox-c2130c-la1.1-vendor-ftm_v0081	dulei0503@thundersoft.com

BSP:FTM: Config User Kernel in FTM Userdebug BaseLineconfig user kernel in FTM userdebug baselineTC-RID: 1201-0100803IssueID:
TS-R-DF-114187Change-Id: Id9ee3d570ed78e853056c9e28d93cd5ddca4acf3(cherry picked from commit d3e075f1d15eec6c85cce144b7b89cbf681c7eaa)

#5 - 2023-03-10 13:41 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
186840	general/vendor/thundercomm/produ ts/figure	Pre_figure_turbox-c2130c-la1.1-vendo r-ftm_v0081	dulei0503@thundersoft.com
BSP:FTM: Add A2B chipset factory testadb shell tc_ftm_a2b_tool.shOutput: 0x28TC-RID: 1201-0100803IssueID: TS-R-DF-114187Change-Id: Icb8cb1b1de074735fb0bef93a4ec51ccb67f7671			

#6 - 2023-03-10 15:22 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
186881	general/platform/vendor/thundercom m/apps/TestTools	Pre_figure_turbox-c2130c-la1.1-qssi12 -ftm_v0081	wangxl0510@thundersoft.com
AF: TestTools: Add BurnInTest Application for factory testTC-RID: 1201-0204501IssueID: TS-R-DF-114187Change-Id: I95a5b5e2f7c883f5a27616b96cf34243363c5874			

#7 - 2023-03-10 17:47 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
186948	general/vendor/thundercomm/produ ts/figure	Pre_figure_turbox-c2130c-la1.1-vendo r-ftm_v0081	dulei0503@thundersoft.com
BSP:FTM: Add A2B chipset factory test2adb shell tc_ftm_a2b_tool.shOutput: 0x28TC-RID: 1201-0100803IssueID: TS-R-DF-114187Change-Id: I6c051b5ee3d74cbd78866be28b224bca8424966a			

#8 - 2023-03-14 19:54 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
186870	general/platform/vendor/thundercom m/apps/TestTools	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangxl0510@thundersoft.com
AF: TestTools: Add BurnInTest Application for factory testTC-RID: 1201-0204501IssueID: TS-R-DF-114187Change-Id:			

#9 - 2023-03-14 23:35 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
187532	general/device/qcom/qssi	Pre_figure_turbox-c2130c-la1.1-qssi12-ftm_v0081	wangxl0510@thundersoft.com
MM: Audio: Disable audio focus feature in ftm branch.Disable FSE audio focus control in ftm branch.TC-RID: 0301-0900116IssueID: TS-R-DF-114187Change-Id: Idb2da0d6db7549fb4c5bfd97220b266433a9e652			

#10 - 2023-03-29 20:56 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
190846	general/platform/vendor/thundercomm/apps/TestTools	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangxl0510@thundersoft.com
AF: TestTools: Fix video can not loop in BurnInTest Application for factory testTC-RID: 1201-0204501IssueID: TS-R-DF-114187Change-Id: I9986932a47363b9458de781f21785c0fdb976f43			

#11 - 2023-04-16 11:27 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
193968	general/device/qcom/qssi	Pre_figure_turbox-c2130c-la1.1-qssi12-ftm_v0090	wangxl0510@thundersoft.com
MM: Audio: Disable audio focus feature in ftm branch.Disable FSE audio focus control in ftm branch.TC-RID: 0301-0900116IssueID: TS-R-DF-114187Change-Id: Idb2da0d6db7549fb4c5bfd97220b266433a9e652(cherry picked from commit d8ec5b9183fb1d8ef11843453f2ab47bfa887c01)			

#12 - 2023-04-17 10:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
193706	general/vendor/thundercomm/products/figure	Pre_figure_turbox-c2130c-la1.1-vendor-ftm_v0090	dulei0503@thundersoft.com

BSP:FTM: Config User Kernel in FTM Userdebug BaseLineconfig user kernel in FTM userdebug baselineTC-RID: 1201-0100803IssueID:
TS-R-DF-114187Change-Id: Id9ee3d570ed78e853056c9e28d93cd5ddca4acf3(cherry picked from commit d3e075f1d15eec6c85cce144b7b89cbf681c7eaa)(cherry
picked from commit 268febdbdb294de3fe3d5c4277b648e31016a67e)

#13 - 2023-04-17 10:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
193707	general/vendor/thundercomm/produ ts/figure	Pre_figure_turbox-c2130c-la1.1-vendo r-ftm_v0090	dulei0503@thundersoft.com
BSP:FTM: Add A2B chipset factory testadb shell tc_ftm_a2b_tool.shOutput: 0x28TC-RID: 1201-0100803IssueID: TS-R-DF-114187Change-Id: Icb8cb1b1de074735fb0bef93a4ec51ccb67f7671(cherry picked from commit a89b3fd3e462bdccd0743cbd2bdccafd8643286a)			

#14 - 2023-05-03 16:33 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
197318	general/device/qcom/qssi	Pre_figure_turbox-c2130c-la1.1-qssi12 -ftm_v0095	wangxl0510@thundersoft.com
Revert MM: Audio: offload disableTC-RID: 0301-0900116IssueID: TS-R-DF-114187This reverts commit 194571f48563f4bb3a0398e9b3fba4cd03a3e028.Change-Id: I55b9bcd44184c23026d9a3c90348a9f9e18ed152			

#15 - 2023-05-03 16:34 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
197288	general/device/qcom/qssi	Pre_figure_turbox-c2130c-la1.1-qssi12 -ftm_v0095	wangxl0510@thundersoft.com
MM: Audio: Disable audio focus feature in ftm branch.Disable FSE audio focus control in ftm branch.TC-RID: 0301-0900116IssueID: TS-R-DF-114187Change-Id: Idb2da0d6db7549fb4c5bfd97220b266433a9e652(cherry picked from commit d8ec5b9183fb1d8ef11843453f2ab47bfa887c01)(cherry picked from commit 04def52592154542fffa47ff6e3bf24946d474ae)			

#16 - 2023-05-04 11:09 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
197297	general/vendor/thundercomm/produ ts/figure	Pre_figure_turbox-c2130c-la1.1-vendo r-ftm_v0090	dulei0503@thundersoft.com

	ts/figure	r-ftm_v0095	
BSP:FTM: Config User Kernel in FTM Userdebug BaseLineconfig user kernel in FTM userdebug baselineTC-RID: 1201-0100803IssueID: TS-R-DF-114187Change-Id: Id9ee3d570ed78e853056c9e28d93cd5ddca4acf3(cherry picked from commit d3e075f1d15eec6c85cce144b7b89cbf681c7eaa)(cherry picked from commit 268febddd294de3fe3d5c4277b648e31016a67e)(cherry picked from commit e60aea97f37304a4833872498612500f16927e1f)			

#17 - 2023-05-04 11:10 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
197298	general/vendor/thundercomm/producs/figure	Pre_figure_turbox-c2130c-la1.1-vendor-ftm_v0095	dulei0503@thundersoft.com
BSP:FTM: Add A2B chipset factory testadb shell tc_ftm_a2b_tool.shOutput: 0x28TC-RID: 1201-0100803IssueID: TS-R-DF-114187Change-Id: Icb8cb1b1de074735fb0bef93a4ec51ccb67f7671(cherry picked from commit a89b3fd3e462bdccd0743cbd2bdccafd8643286a)(cherry picked from commit 67b7eb6c794556784c07cbda322e2d644b19fa35)			

#18 - 2023-05-09 17:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
198092	general/platform/vendor/thundercomm/apps/TestTools	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangxl0510@thundersoft.com
AF: TestTools: BurnInTest will run again after power on even if result was success.TC-RID: 1201-0204501IssueID: TS-R-DF-114187Change-Id: I59a1f05fad71633acaabc704d42e07a12c234a64			

#19 - 2023-05-27 17:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
202533	general/platform/build/soong	Pre_figure_turbox-c2130c-la1.1-vendor-dev	wangxl0510@thundersoft.com
AF:Build:Delete test script to avoid building blocked in 99%.TC-RID: 1201-0101401IssueID: TS-R-DF-114187Change-Id: I7d3ec38e6412c0b4f86999e6cc2fd4a775396470			

Gerrit Merge Information :

ID	Project	Branch	Uploader
202535	general/platform/build/soong	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangxl0510@thundersoft.com
AF:Build:Delete test script to avoid building blocked in 99%.TC-RID: 1201-0101401IssueID: TS-R-DF-114187Change-Id: I7d3ec38e6412c0b4f86999e6cc2fd4a775396470			