

Figure - Bug #114196

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 112101 (New): AF-V2.0-Launcher/SystemUI-控制中心

【AF】 【EVT】 【控制中心】 控制中心的音量条不随设置中的音量调节而变化

2022-11-29 14:45 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-11-29
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	MCE_V4.0update_20221215(原VC1_FSE_Vdec1219)	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0052.X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Critical	Fixed Version:	2022-12-15
Reproducibility:	Every time	Root cause:	默认streamtype的时候不会更新音量条，添加了默认
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、进入设置-声音			
2、调节音量大小			
3、下拉打开控制中心，观察音量变化			
【预期结果】			
3、控制中心的音量条随设置中的音量调节而变化			
【实际结果】			
3、控制中心的音量条不随设置中的音量调节而变化			
【复现率】			
5/5			

History

#1 - 2022-11-29 15:32 - CD FW 曹覃刚

- Status changed from New to ASSIGNED
- Assignee changed from CD FW 曹覃刚 to CD FW-鲁凯峰

#2 - 2022-11-30 15:32 - CDTS_TEST 王成

- Severity changed from Normal to Critical

#3 - 2022-12-07 19:59 - CD FW-鲁凯峰

- Assignee changed from CD FW-鲁凯峰 to CD APP-王宏

#4 - 2022-12-08 11:18 - CDTS-TEST 周婷

- Target version set to MCE_V4.0update_20221215(原VC1_FSE_Vdec1219)

#5 - 2022-12-12 10:21 - CD APP-王宏

- Category changed from CD-FW to AUDIO-FW
- Assignee changed from CD APP-王宏 to CD MM陈海波

海波, 设备切换后 audio steam 存在问题, 请尽快查一下, 比较紧急, 多谢

#6 - 2022-12-12 14:48 - CD MM陈海波

<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+168736>

这份提交中的代码:

```
changed |= onVolumeChangedW(AudioManager.STREAM_MUSIC, 0);
```

改为下边的, 应该可以解决问题:

```
int mode = AudioManager.getMode()
if (mode == MODE_IN_COMMUNICATION || mode == MODE_IN_CALL){
    changed |= onVolumeChangedW(stream, 0);
} else {
    changed |= onVolumeChangedW(AudioManager.STREAM_MUSIC, 0);
}
```

多谢!

#7 - 2022-12-12 14:49 - CD MM陈海波

- Assignee changed from CD MM陈海波 to CD APP-王宏

#8 - 2022-12-14 11:12 - CD APP-王宏

- Category changed from AUDIO-FW to CD-FW

#9 - 2022-12-14 16:21 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
170149	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings: Fix the problem that the control center volume bar will not be updatedFix the problem that the control center volume bar will not be updatedTC-RID: 1201-0201903IssueID: TS-R-BUG-114196Change-Id: Ice52410f46ce7ac600cc82d85e4c95b29a260bc5			

#10 - 2022-12-14 16:25 - CD FW 曹覃刚

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-王宏 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2022-12-15

- Root cause set to 默认streamtype的时候不会更新音量条, 添加了默认情况的条件

#11 - 2022-12-16 09:58 - CD TEST-方永红

- Status changed from *RESOLVED* to *VERIFIED*
- Verified Version set to *FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202212160615*

12.16
验证通过

#12 - 2022-12-16 09:58 - CD TEST-方永红

- Status changed from *VERIFIED* to *CLOSED*

Files			
logcat.txt	4.82 MB	2022-11-29	CD TEST-方永红